

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT                 |   |   |                |       |                         |  |
|--|---|---|----------------|-------|-------------------------|--|
|  | AXA INSURANCE I   | PTE LTD   |                | Ref:  | CS3/ASM22001128/Vvy3e2  |  |
|  | 8 SHENTON WAY<br>SINGAPORE 0688   | #24-01 AXA TOWER<br>11                            |                | Date: | 15/03/2022              |  |
|  | ATTN: JANICE KOI  | Н   |                | Code: | ASM                     |  |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) |   |   |                |       |                         |  |
|  | Insured Veh.  | SML 2627L   | Veh. Inspected | k     | SKA 7780A               |  |
|  | Policy No.  | GA539731/1  | Coverage (\$)  |       | 0.00                    |  |
|  | Claim No.   | S2M03SKF  | Excess (\$)    |       | 0.00                    |  |
|  | Assign From   | JANICE KOH  | Assign Date    |       | 07/02/2022              |  |
| 2. Vehicle Particulars & Condition           |   |   |                |       |                         |  |
|  | Make & Model  | RENAULT GRAND SCENIC IV                           | c.c            |       | 1461                    |  |
|  | Engine No.  | HIDDEN  | Year of Reg.   |       | 2018                    |  |
|  | Chassis No.   | VF1RFA00259238297                                 | Colour         |       | SILVER                  |  |
|  | Odometer  | 124282 KM   | Steering       |       | IN ORDER                |  |
|  | Brakes  | IN ORDER  | Modification   |       | STANDARD ALLOY RIM      |  |
|  | General   | GOOD  |                |       |                         |  |
| 3. Conditions of Tyres                       |   |   |                |       |                         |  |
|  |   | Size  | Make           |       | Balance                 |  |
|  | R/H Front Tyre  | 195/55 R20  | MICHELIN       |       | 6 mm                    |  |
|  | L/H Front Tyre  | 195/55 R20  | MICHELIN       |       | 6 mm                    |  |
|  | R/H Rear Tyre   | 195/55 R20  | MICHELIN       |       | 6 mm                    |  |
|  | L/H Rear Tyre   | 195/55 R20  | MICHELIN       |       | 6 mm                    |  |
| 4. Description of Damages                    |   |   |                |       |                         |  |
|  | THE VEHICLE SUS   | E VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. |                |       |                         |  |
| 5.   | 5. General Information  |   |                |       |                         |  |
|  | Accident Date   | 31/01/2022  | Inspect Date / | Time  | 14/02/2022 ( 10:00 AM ) |  |
|  | Survey held at  | TAMPINES AUTO SERVICE                             |                |       |                         |  |
|  | BLK 9002 TAMPINES ST 93 #01-34/36 SINGAPORE 528836  |   |                |       |                         |  |
| 5a.  | 5a. Remarks   |   |                |       |                         |  |
|  | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000 |   |                |       |                         |  |
| 5b. Estimate Days of Repair                  |   |   |                |       |                         |  |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days  |   |                |       |                         |  |

Report Ref No. CS3/ASM22001128/Vvy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser