

Claim	S2M03SKF
Reference	CS3/ASM22001128/Vvy3e2
Loss Date	31 January 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	4 Feb 2022 1:12:14 PM
Request Date	7 February 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident	SKA7780A
Vehicle	
Registration #	
Make	TPVD
Model	Renault

Service Address

, , ,

Primary Contact/Insured

JOSEPHINE PANG TSING YANG
201C COMPASSVALE DRIVE, #03-543, 543201,
Singapore
83287108



Claim Handler

ONG Kian Theng Derick

derick.ongkt@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2201399.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	17 March 2022
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	17 March 2022

FAQ English (SG) ▼ Elaine Kuan ▼			E	SUBTYPE	AUTHOR	DATE UPLOADED
	Service Requests	...	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	8 March 2022
	SKA 7780A LKKPhotosIn4.pdf.pdf		Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	8 March 2022
	SKA 7780A RES.pdf.pdf		Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	8 March 2022
	No agreeable SJE & appoint LKK for PRI.msg.msg		Letters and Correspondence	Third Party	KUMAR Shailendra	7 February 2022
	SKA7780A TP GIA.pdf.pdf		Reports & Statement	GIA Report	KUMAR Shailendra	7 February 2022
	PRI TP EMAIL FROM SOLICITOR.msg.msg		Legal	Others	KUMAR Shailendra	7 February 2022
	SML2627L (Insd) GIA.pdf.pdf		Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	4 February 2022