

(08/11/13) wef
ASS. REC. BY: *form*

REF:

CS3/AH21013295/Rq 83

2890

COPIES: 2025/July

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *8JX 8935E*

at Workshop m/s *AH Koon*

of *1001, BUKIT MELAK LN 3 #01-69*

Insured: *AGI*

Policy No.

Claims No. *6743911707SG*

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

34K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time Action / Instruction

REPAIR LIMIT - 22k

04/01/22 Submit DAR.

04/03/22 SUBMIT LS \$4850, 6 DAYS (Red \$5250, 52%)

Veh No: *SJX 8935E*

Yr Regn: *2010 / July*

Type: *M.Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *MITSUBISHI LANCER 1.5 NIVUSP c.c 1499*

Colour: *WHITE*

A/C: Insured / Std / NI / NA

Sp. Reading: *137636*

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: *3MYSRCY2AN001892*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: *In order* / Jammed / Leaked / Burnt or

Brake: *In order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *205/55ZR16*

R:

BS / DUN / EXNOVA / GY / FS / LIZA / *MI* / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *6* mm

R/Bal. *6* mm

L/Bal. *6* mm

L/Bal. *6* mm

D.O.A.

D.O.I. *30/12/21*

Survey held at *AH Koon*

Des. of Damages: Frt / Rear / O/S / *NIS* / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1) 04/03 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: *6*

Resurvey No. of Trlp:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

): *S + RS* SI

☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others

☐ : Weekend (\$

)

Report Format: TP

Lump Sum *1.1B.1* (\$ 4850

TOTAL

Condition (CON)

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
 (07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary (12) Missing
 (13) Torn (14) Unconfirmed (15) Not Working

MOTOR CAR (LH)

SJX 8935E

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (?)
 (4) Not Consistent (NC)

Vehicle No:

Left Portion

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door	bx	R	
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror <i>broken</i>	ms	/	
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle	scr	R	
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH	scr	R	
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper	scr	/	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding <i>For Lamp cover</i>	scr	/	
1015	991407	Frt Bumper Lower Spoiler	scr	/	
1029	995153	Frt LH Headlamp Assy	scr	/	
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender	bx	/	
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector	de	/	
		<i>bumper</i>	scr	R	
		<i>Frt LH WHEEL RIM</i>	scr	/	
		<i>2 WHEEL TYRE</i>	scr	/	

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door	bx	R	
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper	scr	R	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1163	993851	Rear LH Taillamp			
1218	993436	Rear LH Fender	scr	R	
1219	993449	Rear LH Fender Protector			
1136	990247	Sticker			

10 days

No of Items: _____

Assessor: _____

Toyota Corolla Altis 1.6A

Overview

Financial

Accessories

Similar

Research

Photos

Map



Certified
Pre-☒Owned

The ☒☒☒☒ BEST for you

Price	\$68,800		
Depreciation	\$11,040 /yr View models with similar depre	Reg Date	02-May-2017 (5yrs 3mths 29days COE left)
Mileage	79,680 km (17k /yr)	Manufactured	2016
Road Tax	\$742 /yr	Transmission	Auto
Dereg Value	\$42,577 as of today (change)	OMV	\$19,990
COE	\$51,765	ARF	\$19,990
Engine Cap	1,598 cc	Power	90.0 kW (120 bhp)
Curb Weight	1,215 kg	No. of Owners	1

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	289D
Vehicle No.:	SJX8935E
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jan 2022
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.5 MIVEC SPORTS AT ABS D/AB
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	4A910170866
Chassis No.:	JMYSRCY2AAU001852
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$18,165.00
Original Registration Date:	21 Jul 2010
First Registration Date:	21 Jul 2010
Transfer Count:	3
Actual ARF Paid:	\$18,165.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	20 Jul 2025
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$16,438.00
COE Rebate Amount:	\$11,665.00
Total Rebate Amount:	\$11,665.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Jan 2022

OK