



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: DERICK ONG KIAN THENG			Ref: CS/ASM22001134/Uty3e2 Date: 01/03/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 5756J	Veh. Inspected	GBJ 4104G	
Policy No.	VFX/P2413997	Coverage (\$)	0.00	
Claim No.	S2M03S93	Excess (\$)	0.00	
Assign From	DERICK ONG KIAN THENG	Assign Date	07/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV350 (A)	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JN1MC2E26Z0001861	Colour	GREY	
Odometer	119295 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	FALKEN	6 mm	
L/H Front Tyre	195 R15	FALKEN	6 mm	
R/H Rear Tyre	195 R15	OHTSU	6 mm	
L/H Rear Tyre	195 R15	OHTSU	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/01/2022	Inspection Date	10/02/2022	
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		