


SA: Thevan

CS/SMA22001144 /UVF3

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop n/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: **SMB 324B**  
 Policy No: \_\_\_\_\_  
 Claims No: **BUS/01/22/7032**  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: **36kRM/12k**  
 IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: **6** days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT



Veh No: **SRD 6189** Yr Regn: **2015**  
 Type:  Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: **Toyota Vios E** a.c. **1497**  
 Colour: **Silver** A/C: Insured / Std / Nil / NA  
 Sp. Reading: **142104** T/Radlo: Insured / Std / Nil / NA  
 Eng/No: \_\_\_\_\_  
 C/No: **PN153HYF005080155**  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rlm /  STD A/Rlm or \_\_\_\_\_  
 Tyre Size: F: **185/60R15**  
 R: **185/60R15**  
 BS / DUN / EXNOVA / GY / FS / LIZA /  MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. **5** mm R/Bal. **5** mm  
 L/Bal. **5** mm L/Bal. **5** mm  
 D.O.A. **29/1/22** D.O.I. **8/2/22 1200**  
 Survey held at **Success united Pte Ltd**  
 Des. of Damages: Frt /  Rear / O/S / N/S / UIC / Rooftop or \_\_\_\_\_  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Sum insured: <b>36kRM/12k</b>
<b>2/3/22</b>	Thevan informed LS \$4300 (Red 4411 05,50%)

Date/Time File Pass to?  : Prell. Report  
 : Final Report  
 Date/Time File Return to?  
**3/3/22-typist**

Days Of Repair: **6**  
 Resurvey No. of Trip: **2**

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Inv (\$ \_\_\_\_\_)  
 : Misc (\$ \_\_\_\_\_)

Survey Fee:

Transportation:	_____
_____ S + RS. _____ SI	_____
Prints	_____
Others	_____
TOTAL	_____

Report Form: **TP**  
 Loss: **LS \$4300**

**SUCCESS UNITED PTE LTD**

2 Kaki Bukit Ave 2, #01-33 / #02-29  
 Kaki Bukit Autohub, Singapore 417921  
 Tel No. : 67461515 / 67471787 Fax No. : 67485015  
 Website : www.successunited.com.sg  
 Buss. Reg. No. : GST No. 200402570C

MS First Capital Insurance Limited  
 36 Robinson Road  
 #16-01 City House  
 Singapore 068877

Attention : Motor Claim Department  
 Contact : 65073848 Fax No. : 65073849

Estimate : TP22-014

Date : 29/01/2022  
 Vehicle Num. : JRD6189  
 Make/Model : Toyota Vios-2015  
 Chassis/Eng# : PN153HYF005080155/1NZZ328810  
 Accident Date : 27/01/2022  
 Claim No. :  
 Reference :  
 Policy No. : (22/11/2022)

S/N	Quantity	Particular	Unit Price	Amount S\$
		LIST ITEMS :		
1.	1 pc	Rear Boot Lid		890 987.10 / DT
2.	1 pc	Rear Boot Lid Toyota Logo		58.90 / nee
3.	1 pc	Rear Boot Lid 'Vios' Emblem		64.20 / nee
4.	1 pc	Rear Boot Lid 'G' Emblem		49.60 / nee
5.	1 pc	Rear Boot Lid Chrome Trim Moulding		213 436.70 / DT
6.	1 pc	Rear No. Plate Lamp		83.60 / rra
7.	1 pc	Rear Boot Lid Mechanism Lock	97.10	220 438.80 / jam
8.	2 pcs	Rear Boot Hinge L/R	423.10	194.20 / rsv
9.	2 pcs	Rear Lamp Assy L/R		846.20 / rsv
10.	1 pc	Rear Boot Lid Weatherstrip		190 258.40 / cut
11.	1 pc	Rear Bumper Assy	5.79	638 731.50 / DT
12.	10 pcs	Rear Bumper Clips	254.90	30 57.90 / nee
13.	2 pcs	Rear Bumper Side Holder L/R	97.60	509.80 / rsv
14.	2 pcs	Rear Bumper Bracket L/R		195.20 / nee
15.	1 pc	Rear End Panel		219 915.60 / DT
16.	1 pc	Rear End Panel Inner Top Garnish		180.70 / DT
17.	1 pc	Rear Floor Spare Tyre Panel		698.70 / r
18.	1 set	Reverse Sensor		380.70 / rsv
		List Total S\$ :		7,087.80
		25.00% Discount S\$ :		1,771.95
				5,315.85
				3601.5
1.	1 pc	SPECIAL NETT ITEMS :		50.00 40
		Rear No. Plate		50.00
		Special Nett Total S\$ :		120.00 40
		LABOUR :		
		To remove, rearrange electrical wirings, check lighting		

CONTINUE / ...

# SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29  
Kaki Bukit Autohub, Singapore 417921  
Tel No. : 67461515 / 67471787 Fax No. : 67485015  
Website : www.successunited.com.sg  
Buss. Reg. No. : GST No. 200402570G

MS First Capital Insurance Limited  
36 Robinson Road  
#16-01 City House  
Singapore 068877

Attention : Motor Claim Department  
Contact : 65073848 Fax No. : 65073849

## Supplementary Estimate : TP22014S

Date : 10/02/2022  
Vehicle Num. : JRD6189  
Make/Model : Toyota Vios-2015  
Chassis/Eng# : PN153HYF005080155/1NZZ328810  
Accident Date : 24/01/2022  
Claim No. :  
Reference :  
Policy No. : (22/11/2022)

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	2 pcs	LIST ITEMS : Rear Bumper Reflector L/R	116.80	233.60 ✓ Cra
		List Total S\$ :		233.60
		25.00% Discount S\$ :		58.40
				175.20

Total S\$ : 175.20  
=====



SUCCESS UNITED PTE LTD

# SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29  
 Kaki Bukit Autohub. Singapore 417921  
 Tel No. : 67461515 / 67471787 Fax No. : 67485015  
 Website : www.successunited.com.sg  
 Buss. Reg. No. : GST No. 200402570G

MS First Capital Insurance Limited  
 36 Robinson Road  
 #16-01 City House  
 Singapore 068877  
 Attention : Motor Claim Department  
 Contact : 65073848 Fax No. : 65073849

Estimate : TP22-014

Date : 29/01/2022  
 Vehicle Num. : JRD6189  
 Make/Model : Toyota Vios-2015  
 Chassis/Eng# : PN153HYF005080155/1NZZ328810  
 Accident Date : 27/01/2022  
 Claim No. :  
 Reference :  
 Policy No. : (22/11/2022)

S/N	Quantity	Particular	Unit Price	Amount S\$
		To remove, reinstal upholstery, Inner trim garnishes.		250.00 50
		To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident		1,600.00 400x800
		To putty and respray painting on affected area.		1,200.00 400x800
		Labour Total S\$ :		3,170.00

5331.5  
 - 200%  
 = 4265.2  
 = 4250

Therian @ LK Auto. loan  
 82235769  
 8/2/22 1200  
 LFS 7 days wp  
 6

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Total S\$ : 8,535.85  
 =====

SUCCESS UNITED PTE LTD



Police Station Of Origin:  
Kampong Ubi NPP  
9 Eunos Crescent #01-2687 SINGAPORE  
400009  
Tel No: 1800-7479999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 27/01/2022 17:05		Vide Report No.:		Station Diary No.: 10	
<b>Informant's Particulars</b>					
Name of Informant ANG CHIN THON			Address:		
ID Type / ID No.: FIN NO / G7449354N			Contact No.: Home/Office:		Mobile: 97791926
Nationality MALAYSIAN			Email:		
Sex: Male	Age: 42	Date of Birth: 09/05/1979	Type of Informant: Driver		
Race: Chinese		Language: Malay		Institution / School Name:	
Occupation: CONSTRUCTION WORKER		Driving Licence Information: Class:		Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 27/01/2022 13:45	Type of Location: Y-Junction
Location:  JURONG WEST CENTRAL 3				
Weather: Sunny		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Pedestrian Crossing		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JRD6189	Car	TOYOTA	VIOS	Silver	Slightly Damaged	0
SMB324B	Bus/Coach/Minibus					0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20220127/2076

2 of 3

Report No. T/20220127/2076

Police Station Of Origin:  
Kampong Ubi NPP  
9 Eunos Crescent #01-2687 SINGAPORE  
400009  
Tel No: 1800-7479999

**CONTINUATION OF REPORT**

<b>Driver Name</b>	ANG CHIN THON		<b>ID No.</b>	G7449354N
<b>Related Vehicle</b>	JRD6189 (Car)		<b>Contact No.</b>	97791926
<b>Hospital/Clinic</b>	NIL		<b>Class of Driving Licence &amp; Expiry Date</b>	Class: NIL Date of Expiry: NIL
<b>Date Treatment</b>	NIL	<b>Date Discharge</b>	NIL	
<b>No. of Days granted Medical Leave</b>	NIL	<b>Degree of Injury</b>	NIL	
<b>Driver Name</b>	LOH ENG CHOONG MICHAEL		<b>ID No.</b>	S1573444B
<b>Related Vehicle</b>	SMB324B (Bus/Coach/Minibus)		<b>Contact No.</b>	97952944
<b>Hospital/Clinic</b>	NIL		<b>Class of Driving Licence &amp; Expiry Date</b>	Class: NIL Date of Expiry: NIL
<b>Date Treatment</b>	NIL	<b>Date Discharge</b>	NIL	
<b>No. of Days granted Medical Leave</b>	NIL	<b>Degree of Injury</b>	NIL	

**Brief Details.**

On 27/01/2022 at about 1.45 pm, I was driving along Jurong West Central 3. I was about to make a left turn at the zebra crossing. As there was oncoming traffic, I stop and waited for traffic to clear. Suddenly, I felt a huge impact from the rear. I looked at my rear view mirror and noticed that an 'SMRT' bus had collided onto the rear of my vehicle. I step out of my vehicle to make a check. Both the bus driver and myself was not injured. We exchange particulars and took photo of the damages to each vehicle. I was advised to lodge a police report. The damage to my vehicle are dents on the rear portion.



**SINGAPORE  
POLICE FORCE**



T/20220127/2076

3 of 3

Report No T/20220127/2076

Police Station Of Origin:  
Kampong Ubi NPP  
9 Eunos Crescent #01-2687 SINGAPORE  
400009  
Tel No: 1800-7479999

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report

G /  
SGT 3 MUHAMMAD SAYYIDI  
BIN TAUHID

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
27/01/2022 17:05

Officer In Charge Of Case:  
TP / AEIT /  
SI TAN JEOK LENG  
Contact No.: 65476151

Classification Of Case:

Authentication Stamp  
NP168



SINGAPORE  
POLICE FORCE

SIGNATURE

Please call KAA Toll Free 1 800 88 3833 for breakdown or accident assistance"

**PRIVATE CAR SCHEDULE / JADUAL KERETA PERSENDIRIAN  
auto365 Comprehensive Premier**

The Insured / Pemegang Polisi <b>SIAU SWEE LAN</b>		Policy No. / No. Polisi <b>JVE1639791</b>	
NO. 51, JALAN KEMBIA 11, TAMAN PUTRI WANGSA, 81800 ULU TIRAM		Account No. / No. Akaun <b>790800-00</b>	
Occupation / Pekerjaan <b>MANAGER</b>		Type of Cover / Jenis Perlindungan <b>COMPREHENSIVE PREMIER</b>	
I.C. No. / No. Kad Pengenalan <b>710213015414</b>		Period of Insurance / Tempoh Insurans From / Dari <b>00:00:01 AM 23-11-2021</b> To / Hingga <b>22-11-2022</b>	
Hire Purchase Owner / Pemilik Sewa Beli -		Premium / Premium <b>RM 1,093.95</b>	
Make & Type of Body / Buatan & Jenis Badan <b>TOYOTA VIOS E / 4D SEDAN</b>		NCD / Diskaun Tanpa Tuntutan <b>55.00%</b> Wef / Berkuatkuasa dari <b>23-11-2021</b>	
Registration No. / No. Pendaftaran <b>JRD6189</b>		Optional Cover	
Excess / Lebihan <b>0.00</b>		Legal Liability Of Passengers / Liabiliti Penumpang Di Sisi Undang-Undang Kerana Perbuatan Cuaai <b>7.50</b>	
Regn. Card No. / No. Kad Pendaftaran -		Legal Liability To Passengers / Liabiliti Dari Segi Undang-Undang Kepada Penumpang <b>33.75</b>	
Carrying or Seating Capacity Incl. Driver / Muatan Tempat Duduk Termasuk Pemandu <b>5</b>		Windscreen Damage (Tempered/Laminated Glass Inclusive Labour Cost) / Kerosakan Cermin Kenderaan (Pengubahan Cermin / Cermin Berlapis Termasuk Kos Buruh) RM <b>270.00</b>	
Year of Manufacture / Tahun Diperbuat <b>2015</b>		Gross Premium / Premium Kasar <b>803.53</b>	
Engine/Motor No. / No. Enjin/Motor <b>1NZZ328810</b>		Service Tax / Cukai Perkhidmatan 6% <b>48.21</b>	
Chassis No. / No. Casis <b>PN153HYF005080155</b>		Stamp Duty / Duti Setem <b>10.00</b>	
Trailer / Treler -		Total Due / Jumlah Berbayar <b>RM 861.74</b>	
Named Driver / Pemandu Yang Dinamakan: <b>ANY AUTHORISED DRIVER</b>		Total Due (OTC) / Jumlah Berbayar Di Kaunter <b>RM 861.75</b>	
Note : Compulsory excess will be applied for named driver under 21 years old / Provisional (P) or Learner (L) driver's licence / unnamed driver. / Ekses wajib akan dikenakan untuk pemandu yang dinamakan di bawah umur 21 tahun / pemegang lesen memandu Percubaan (P) atau Pelajar (L) / Pemandu yang tidak dinamakan.			
Geographical Area : Malaysia , Republic of Singapore and Negara Brunei Darussalam. / Kawasan Geografi : Malaysia, Republik Singapura dan Negara Brunei Darussalam. Limitations as to Use : As described in the Certificate of Insurance. / Had Penggunaan / Seperti yang tercatat dalam Sijil Insurans.			
Replacing Cover Note No. / Gantian No. Nota Perlindungan Renewal of Policy No. / Pembaharuan No. Polisi <b>W0524784</b> Date of Proposal or Declaration / Tarikh Cadangan atau Pengisytiharan <b>17-11-2021</b> Date of Issue / Time / Tarikh Dikeluarkan / Waktu <b>17-11-2021 08:56:35 PM</b>		Issued By / Dikeluarkan Oleh : <b>XEN YANG AGENCY</b> <b>NO 7, JALAN HARMONIUM 31/8,</b> <b>TAMAN DESA TEBRAU,</b> <b>81100 JOHOR BAHRU</b> Tel : 0197554545 Fax :	
		For / untuk <b>AmGeneral Insurance Berhad</b>   Authorised Signature / Tandatangan Yang Diberi Kuasa	
210210171121E344			

Note: / Nota: No refund of premium for any cancellation of policy if premium is charged on minimum premium / Tiada bayaran balik premium bagi sebarang pembatalan polisi sekiranya premium yang dikenakan adalah premium minima.