



**SINGAPORE  
POLICE FORCE**



T/20220127/2076

Police Station Of Origin:  
Kampong Ubi NPP  
9 Eunos Crescent #01-2687 SINGAPORE  
400009  
Tel No: 1800-7479999

1 of 3

Report No: T/20220127/2076

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 27/01/2022 17:05		Vide Report No.:		Station Diary No.: 10	
<b>Informant's Particulars</b>					
Name of Informant ANG CHIN THON			Address:		
ID Type / ID No.: FIN NO / G7449354N			Contact No.: Home/Office:		Mobile: 97791926
Nationality MALAYSIAN			Email:		
Sex: Male	Age: 42	Date of Birth: 09/05/1979	Type of Informant: Driver		
Race: Chinese		Language: Malay		Institution / School Name:	
Occupation: CONSTRUCTION WORKER		Driving Licence Information: Class:		Date of Expiry:	

<b>General Information of the Accident</b>				
Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 27/01/2022 13:45	Type of Location: Y-Junction
Location:  JURONG WEST CENTRAL 3				
Weather: Sunny		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Pedestrian Crossing		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JRD6189	Car	TOYOTA	VIOS	Silver	Slightly Damaged	0
SMB324B	Bus/Coach/Minibus					0

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20220127/2076

2 of 3

Report No. T/20220127/2076

Police Station Of Origin:  
Kampong Ubi NPP  
9 Eunus Crescent #01-2687 SINGAPORE  
400009  
Tel No: 1800-7479999

**CONTINUATION OF REPORT**

<b>Driver Name</b>	ANG CHIN THON		<b>ID No.</b>	G7449354N
<b>Related Vehicle</b>	JRD6189 (Car)		<b>Contact No.</b>	97791926
<b>Hospital/Clinic</b>	NIL		<b>Class of Driving Licence &amp; Expiry Date</b>	Class: NIL Date of Expiry: NIL
<b>Date Treatment</b>	NIL	<b>Date Discharge</b>	NIL	
<b>No. of Days granted Medical Leave</b>	NIL	<b>Degree of Injury</b>	NIL	
<b>Driver Name</b>	LOH ENG CHOONG MICHAEL		<b>ID No.</b>	S1573444B
<b>Related Vehicle</b>	SMB324B (Bus/Coach/Minibus)		<b>Contact No.</b>	97952944
<b>Hospital/Clinic</b>	NIL		<b>Class of Driving Licence &amp; Expiry Date</b>	Class: NIL Date of Expiry: NIL
<b>Date Treatment</b>	NIL	<b>Date Discharge</b>	NIL	
<b>No. of Days granted Medical Leave</b>	NIL	<b>Degree of Injury</b>	NIL	

**Brief Details.**

On 27/01/2022 at about 1.45 pm, I was driving along Jurong West Central 3. I was about to make a left turn at the zebra crossing. As there was oncoming traffic, I stop and waited for traffic to clear. Suddenly, I felt a huge impact from the rear. I looked at my rear view mirror and noticed that an 'SMRT' bus had collided onto the rear of my vehicle. I step out of my vehicle to make a check. Both the bus driver and myself was not injured. We exchange particulars and took photo of the damages to each vehicle. I was advised to lodge a police report. The damage to my vehicle are dents on the rear portion.



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Kampong Ubi NPP  
9 Eunos Crescent #01-2687 SINGAPORE  
400009  
Tel No: 1800-7479999



T/20220127/2076

3 of 3

Report No T/20220127/2076

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report

G /  
SGT 3 MUHAMMAD SAYYIDI  
BIN TAUHID

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
27/01/2022 17:05

Officer In Charge Of Case:  
TP / AEIT /  
SI TAN JEOK LENG  
Contact No.: 65476151

Classification Of Case:

Authentication Stamp  
NP168



SINGAPORE  
POLICE FORCE

SIGNATURE