

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 19960/198R GST Reg. No. 19-960/198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	ORACLE LAW CO	RPORATION	Ref:	CS/LAW22001145/Ktf3e2	
	237 ALEXANDRA #04-11 THE ALEX SINGAPORE 1599	CIER	Date	: 25/03/2022	
			Code	e: L143	
1.	Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	FBH 6150U	Veh. Inspected	SLH 5812G	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	SB/PO/Acc/2020-9393	Excess (\$)	0.00	
	Assign From	PATRICK YEO	Assign Date	07/02/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL (A)	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	RU31218255	Colour	METALLIC PEARL WHITE	
	Odometer	116367 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
	L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
	R/H Rear Tyre	215/60 R16	DUNLOP	8 mm	
	L/H Rear Tyre	215/60 R16	DUNLOP	8 mm	
4.	Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
	REPAIR CONDITION SEE DETAILS.				
5.	5. General Information				
	Accident Date	12/08/2020	Inspection Date	10/03/2022	
	Survey held at HIAP LEK AUTOMOBILE TRADING				
	160 SIN MING DRIVE #05-17 SIN MING AUTOCITY SINGAPORE 575722				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: