

(08/11/13) wef

ASS. REC. BY: JanREF: CS/CTI 220001169/Rty3

866A

## ASSIGNMENT

From: \_\_\_\_\_

Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMN 40444at Workshop m/s NINETEENof 34, WOODWARD'S CLOSE @ MCHX #0124Insured: CTI

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 75K

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMN 40444Yr Regn: 2019 / AUG

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HYUNDAI AVANTE 1.6 GLS (A) c.c 1591Colour WHITE

A/C: Insured / Std / NI / NA

Sp. Reading 26907

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KM1H0841CML4964227Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 02/02/22D.O.I. 08/02/22

Survey held at

NINETEEN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 42K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐

: Site Insp (\$

)      S + RS      SI☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others

☐ : Weekend (\$

)

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

# NINETEEN AUTOWERKS PTE LTD

Blk 436 Tampines Street 43

#07-97 Singapore 520436

Tel: (65) 9674 1991

✉ nineteenautowerks@gmail.com

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DATE:

DOA:

VEHICLE NO:

MAKE & MODEL:



NINETEEN  
AUTOWERKS

7-Feb-22

2-Feb-22

SMN 4044 U

HYUNDAI AVANTE

## ESTIMATE

DESCRIPTION	QUANTITY	AMOUNT	TOTAL
<b>LIST ITEMS</b>			
Rear Bumper <i>di</i>	1	\$988.50	\$988.50
Rear Bumper Side Retainer <i>X</i>	2	\$105.60	\$211.20
Rear Bumper Reflector <i>?</i>	2	\$69.20	\$138.40
Rear Bumper Lower Cover <i>?</i>	1	\$319.00	\$319.00
Rear Bumper Inner Sponge <i>X</i>	1	\$162.80	\$162.80
Rear Bumper Reinforcement <i>X</i>	1	\$328.00	\$328.00
Rear Bumper Bracket <i>X</i>	2	\$156.20	\$312.40
Total			\$2,460.30
Less 20%			\$492.06
			\$1,968.24

## SPECIAL NETT ITEMS

Sundries	1	\$60.00	\$60.00 <i>X</i>
Rear Bumper Clips (set)	1	\$100.00	\$100.00 <i>30</i>
Reverse Sensor	1	\$400.00	\$400.00 <i>X</i>
			\$560.00
Parts Total			\$2,528.24

## LABOUR CHARGES

Panel Beating	\$1,000.00 <i>300</i>
Spray Painting	\$800.00 <i>200</i>
Remove & Refit Reverse Sensor	\$100.00 <i>60</i>
To apply undercoating for rust roofing	\$150.00 <i>X</i>
Check Wiring system after disconnect & connect	\$100.00 <i>30</i>
Labour Total	\$2,150.00

## Total Parts and Labour Cost of Repair

\$4,678.24

LKK Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*RASUL*  
*Hp 90010068*  
*3 days*  
*4/8*  
*08/02/22 @ 1510*  
*Resurvey after repair*



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	03/02/2022 18:10 (SGT)
Date of Accident	02/02/2022 18:46 (SGT)
Exact Location of Accident	51 Yishun Ave 11, Singapore 768867
Additional Location Information	YISHUN AVE 9
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMN4044U
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	CHIA TING FANG KIMBERLEY
NRIC No	S9247866A
Email Address	chiakimberleytf@gmail.com
Mobile Phone No	(Phone) +65-96444366
Alternative Phone No	+65-96444366

### VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Avante
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1300

### INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	VPA/2318270
Cover Note Number	-

### DRIVER

Name of Driver	CHIA TING FANG KIMBERLEY
NRIC No	S9247866A

Date Of Birth	21/12/1992
Occupation	Indoor
Date Of Driving Pass	05/12/2018
Driving experience	3 YEARS AND 2 MONTHS
Gender	Female
Mobile Number	(Phone) +65-96444366
Alt. Phone Number	-
Email Address	chiakimberleytf@gmail.com
Address	221, YISHUN STREET 21 #09-429
Address complement	-
Postcode	760221
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	OWNER
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER ATTACHED ( SKETCH PLAN )

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMT8698A
Vehicle Manufacturer	BMW
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-

Postcode ..... -  
Insurance Company Name ..... -  
Nature Of Damage ..... -  
Details of property damaged in accident ..... -  
No. Of Passenger (Including Driver) ..... 1





**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date &amp; Time



Driver's Signature (If driver is not the policyholder) / Date &amp; Time

Witnessed by Reporting Centre Personnel

**Sketch Plan**


Scanned with CamScanner

**Describe Circumstances of the Accident**

On the stated date & time, I was travelling in my vehicle (SMU4044U) along Yichun Avenue 9. As the traffic light turn red, I came to a halt. Suddenly, I felt an impact from the rear. A vehicle bearing (SMT8698A) had collided onto the rear portion of my vehicle. We then exchange particulars and I decided to proceed with insurance claims.

**Declaration**

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Scanned with CamScanner



> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	866A
Vehicle No.:	SMN4044U
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Feb 2022
Vehicle Make:	HYUNDAI
Vehicle Model:	AD AVANTE 1.6 GLS (A) S
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	G4FGKU190791
Chassis No.:	KMHD841CMLU964227
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$14,501.00
Original Registration Date:	07 Aug 2019
First Registration Date:	07 Aug 2019
Transfer Count:	0
Actual ARF Paid:	\$14,501.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Aug 2029
PARF Rebate Amount:	\$10,875.00
COE Expiry Date:	06 Aug 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$28,589.00
COE Rebate Amount:	\$21,426.00
Total Rebate Amount:	\$32,301.00

The information contained herein is correct as at 08 Feb 2022

OK



# Hyundai Avante 1.6A GLS

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

## TAY MOTOR & CREDIT PTE LTD

Our Accreditations:



<b>Price</b>	<b>\$75,800</b>		
<b>Depreciation</b> ?	\$9,240 /yr <a href="#">View models with similar depre</a>	<b>Reg Date</b>	14-Aug-2019 (7yrs 6mths 5days COE left)
<b>Mileage</b>	32,000 km (12.8k /yr)	<b>Manufactured</b> ?	2019
<b>Road Tax</b> ?	\$738 /yr	<b>Transmission</b>	Auto
<b>Dereg Value</b> ?	\$29,619 as of today (change)	<b>OMV</b> ?	\$12,771
<b>COE</b> ?	\$26,667	<b>ARF</b> ?	\$12,771
<b>Engine Cap</b>	1,591 cc	<b>Power</b>	93.8 kW (125 bhp)
<b>Curb Weight</b> ?	1,345 kg	<b>No. of Owners</b> ?	2