



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT                                                                 |                                                                                                                                                                                                                                                                                                                                             |                                                                         |                                                              |                                                                                       |
|----------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------|--------------------------------------------------------------|---------------------------------------------------------------------------------------|
| AXA INSURANCE PTE LTD<br>8 SHENTON WAY #24-01 AXA TOWER<br>SINGAPORE 068811<br>ATTN: OH VALE |                                                                                                                                                                                                                                                                                                                                             |                                                                         | Ref: CS3/ASM22001170/Gqy3e2<br>Date: 15/03/2022<br>Code: ASM |                                                                                       |
| 1. Policy Particulars :- (THIRD PARTY CLAIM)                                                 |                                                                                                                                                                                                                                                                                                                                             |                                                                         |                                                              |                                                                                       |
|                                                                                              | Insured Veh.                                                                                                                                                                                                                                                                                                                                | SH 6804R                                                                | Veh. Inspected                                               | SMM 4287R                                                                             |
|                                                                                              | Policy No.                                                                                                                                                                                                                                                                                                                                  | VFX/P2419138                                                            | Coverage (\$)                                                | 0.00                                                                                  |
|                                                                                              | Claim No.                                                                                                                                                                                                                                                                                                                                   | S2M03ST4                                                                | Excess (\$)                                                  | 0.00                                                                                  |
|                                                                                              | Assign From                                                                                                                                                                                                                                                                                                                                 | OH VALE                                                                 | Assign Date                                                  | 08/02/2022                                                                            |
| 2. Vehicle Particulars & Condition                                                           |                                                                                                                                                                                                                                                                                                                                             |                                                                         |                                                              |                                                                                       |
|                                                                                              | Make & Model                                                                                                                                                                                                                                                                                                                                | MERCEDES BENZ C180<br>AVANTGARDE                                        | c.c                                                          | 1595                                                                                  |
|                                                                                              | Engine No.                                                                                                                                                                                                                                                                                                                                  | HIDDEN                                                                  | Year of Reg.                                                 | 2017                                                                                  |
|                                                                                              | Chassis No.                                                                                                                                                                                                                                                                                                                                 | WDD2050402R262333                                                       | Colour                                                       | WHITE                                                                                 |
|                                                                                              | Odometer                                                                                                                                                                                                                                                                                                                                    | 78784 KM                                                                | Steering                                                     | IN ORDER                                                                              |
|                                                                                              | Brakes                                                                                                                                                                                                                                                                                                                                      | IN ORDER                                                                | Modification                                                 | STANDARD ALLOY RIM                                                                    |
|                                                                                              | General                                                                                                                                                                                                                                                                                                                                     | GOOD                                                                    |                                                              |                                                                                       |
| 3. Conditions of Tyres                                                                       |                                                                                                                                                                                                                                                                                                                                             |                                                                         |                                                              |                                                                                       |
|                                                                                              |                                                                                                                                                                                                                                                                                                                                             | Size                                                                    | Make                                                         | Balance                                                                               |
|                                                                                              | R/H Front Tyre                                                                                                                                                                                                                                                                                                                              | 225/50 R17                                                              | MICHELIN                                                     | 6 mm                                                                                  |
|                                                                                              | L/H Front Tyre                                                                                                                                                                                                                                                                                                                              | 225/50 R17                                                              | MICHELIN                                                     | 6 mm                                                                                  |
|                                                                                              | R/H Rear Tyre                                                                                                                                                                                                                                                                                                                               | 225/50 R17                                                              | MICHELIN                                                     | 6 mm                                                                                  |
|                                                                                              | L/H Rear Tyre                                                                                                                                                                                                                                                                                                                               | 225/50 R17                                                              | MICHELIN                                                     | 6 mm                                                                                  |
| 4. Description of Damages                                                                    |                                                                                                                                                                                                                                                                                                                                             |                                                                         |                                                              |                                                                                       |
|                                                                                              | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.                                                                                                                                                                                                                                                                                          |                                                                         |                                                              |  |
| 5. General Information                                                                       |                                                                                                                                                                                                                                                                                                                                             |                                                                         |                                                              |                                                                                       |
|                                                                                              | Accident Date                                                                                                                                                                                                                                                                                                                               | 05/02/2022                                                              | Inspect Date / Time                                          | 08/02/2022 ( 05:00 PM )                                                               |
|                                                                                              | Survey held at                                                                                                                                                                                                                                                                                                                              | GARAGE 13 PTE LTD<br>8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875 |                                                              |                                                                                       |
| 5a. Remarks                                                                                  |                                                                                                                                                                                                                                                                                                                                             |                                                                         |                                                              |                                                                                       |
|                                                                                              | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.<br>D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000 |                                                                         |                                                              |                                                                                       |
| 5b. Estimate Days of Repair                                                                  |                                                                                                                                                                                                                                                                                                                                             |                                                                         |                                                              |                                                                                       |
|                                                                                              | ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                                                                                                                                                                         |                                                                         | 4 Working Days                                               |                                                                                       |

Report Ref No. CS3/ASM22001170/Gqy3e2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or  
relying on this Report, in whole or in part, does so at his or her own risk.