

ASS. REC. BY:

REF: U021 CS/UOI22001173/Kvf3Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. M11D14562202

Sum Insured: _____

Excess: _____

500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$ 40k

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 03 days

Res.: Yes or No

Lum Sum: 1.B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

11/3/22

Kenneth informed final fig \$1529 (Red 659, 30%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2) 11/3/22-typist

Report Format: OD

Lump Sum / I.B.I: (\$ 1529)

Days Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

TOTAL

Veh No: SKQ3950 TYr Regn: 11, 14Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ToyC.C. 1590Colour: M. Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 66761

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053REH104508531Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 26/1/12D.O.I. 14/2/2022

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or BS MS

The U/C / Chassis frame / Body Structure affected due to collision.

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : DHOM110178172100
Accident Date : 26-Jan-2022

No. : 32199

Date : 07-Feb-2022

Our Ref : 021617 / MH

PAGE : 1

WONG YOKE EU (MDM)
C/O UNITED OVERSEAS INSURANCE LIMITED
3 ANSON ROAD
#28-01
SPRINGLEAF TOWER
Singapore 079909

*NOT Withheld
Lly &
Purvey After Repair
Part by Part*

ESTIMATED COST OF REPAIR FOR TOYOTA COROLLA ALTIS 1.6L (2014) SKQ3950T

1 pc front bumper	190.00	c	✓
1 pc LH front bumper side retainer	35.00	c	✓
1 pc LH front bumper foglamp	135.00	c	?
1 pc LH front bumper foglamp cover	55.00	c	x
10 pcs front bumper clips	15.00	c	✓
1 pc LH headlamp assy	650.00	c	✓
	1,080.00		
Add 10% :	108.00		
	1,188.00		

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

400.00 *250/*

To focus headlamps. To check front
wiring and lighting operation.

50.00 *20/*

To putty and respray on affected
portions.

450.00 *280/*

To conduct front wheel alignment
test.

~ 100.00 x

Total : S\$ 2,188.00

Singapore Dollars Two Thousand One Hundred and
Eighty Eight Only

Note: Amount quoted above is subject to prevailing

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis.
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 26/01/2022 20:19 (SGT)
Date of Accident 26/01/2022 15:00 (SGT)
Exact Location of Accident Singapore
Additional Location Information 202 HOUGANG STREET 21 NTUC CARPARK
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKQ3950T

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner WONG YOKE EU
NRIC No SXXXX556H
Email Address ALISONWONGYE@GMAIL.COM
Mobile Phone No (Phone) +65-94550061
Alternative Phone No +65-94550061

VEHICLE PARTICULARS

Manufacturer Toyota
Model Corolla
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 0

INSURANCE COMPANY

Name of Insurance Company United Overseas Insurance Ltd
Type of Coverage -
Fleet Policy No
Policy Number DHOM110178172100
Cover Note Number -

DRIVER

Name of Driver TAN CHEE HONG
NRIC No SXXXX014Z

✓ Describe Circumstances of the Accident

At around 3pm I was driving slowly out of the car park lot.

I did not notice any car to my left as I was turning right to exit the lot.

Suddenly I heard a small bang and notice my car and the other car has collided.

My left front bumper has collided with the other's car right front bumper.

Both cars came to a halt immediately.

I believe ~~both cars~~ I have right of way as I was already $\frac{3}{4}$ out of the car lot.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



Require PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID: Singapore NRIC

Vehicle Details

556H

Vehicle No.:

Vehicle to be Exported:

SKQ3950T

Intended Deregistration Date:

No

Vehicle Make:

07 Feb 2022

Vehicle Model:

TOYOTA

Primary Colour:

TOYOTA COROLLA ALTIS 1.6L CVT

Manufacturing Year:

Silver

Engine No.:

2014

Chassis No.:

1ZRX414456

Maximum Power Output:

MR053REH104508531

Open Market Value:

90.0 kW (120 bhp)

Original Registration Date:

\$18,759.00

First Registration Date:

26 Nov 2014

Transfer Count:

26 Nov 2014

Actual ARF Paid:

1

Intended PARF Rebate Details

\$13,759.00

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

25 Nov 2024

PARF Rebate Amount:

\$8,255.00

Intended COE Rebate Details

COE Expiry Date:

25 Nov 2024

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$65,710.00

COE Rebate Amount:

\$18,398.00

Total Rebate Amount:

\$26,653.00

The information contained herein is correct as at 07 Feb 2022

OK