

ASS. REC. BY:

REF: U021Kenneth

## ASSIGNMENT

From: \_\_\_\_\_

Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 840k

IDAC Accident Report: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 03 days

Res.: Yes or No

Lum Sum: 1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No: SKQ3950 TYr Regn: 11, 14Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Toy AltisC.C. 1590Colour M. Silver

A/C: Insured / Std / NI / NA

Sp. Reading 66761

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR053REH104508531Gen. Cond: Good / Fair / Poor / BurntSteering: Inoper / Jammed / Leaked / Burnt orBrake: Inoper / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal. 2 mmR/Bal. 2 mmL/Bal. 2 mmL/Bal. 2 mmD.O.A. 26/1/12D.O.I. 14/2/2022

Survey held at \_\_\_\_\_

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or  
BS MS

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

**金興(龔)汽車私人有限公司**

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

Your Reference : DHOM110178172100  
Accident Date : 26-Jan-2022

No. : 32199

Date : 07-Feb-2022

Our Ref : 021617 / MH

PAGE : 1

WONG YOKE EU (MDM)  
C/O UNITED OVERSEAS INSURANCE LIMITED  
3 ANSON ROAD  
#28-01  
SPRINGLEAF TOWER  
Singapore 079909

*NOT Withheld  
Lly &  
Purvey After Repair  
Part by Part*

**ESTIMATED COST OF REPAIR FOR TOYOTA COROLLA ALTIS 1.6L (2014) SKQ3950T**

1 pc front bumper	190.00	c	✓
1 pc LH front bumper side retainer	35.00	c	✓
1 pc LH front bumper foglamp	135.00	c	?
1 pc LH front bumper foglamp cover	55.00	c	x
10 pcs front bumper clips	15.00	c	✓
1 pc LH headlamp assy	650.00	c	✓
	1,080.00		
Add 10% :	108.00		
	1,188.00		

To remove, cut out damaged parts,  
panel beating, welding, align,  
refix and to renew affected parts.

400.00 *250/*

To focus headlamps. To check front  
wiring and lighting operation.

50.00 *20/*

To putty and respray on affected  
portions.

450.00 *280/*

To conduct front wheel alignment  
test.

*~ 100.00 x*

Total : S\$ 2,188.00

Singapore Dollars Two Thousand One Hundred and  
Eighty Eight Only

Note: Amount quoted above is subject to prevailing

**LKK Auto Consultants hence notify  
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis.
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 26/01/2022 20:19 (SGT)  
Date of Accident ..... 26/01/2022 15:00 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... 202 HOUGANG STREET 21 NTUC CARPARK  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SKQ3950T

### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... WONG YOKE EU  
NRIC No ..... SXXXX556H  
Email Address ..... ALISONWONGYE@GMAIL.COM  
Mobile Phone No ..... (Phone) +65-94550061  
Alternative Phone No ..... +65-94550061

### VEHICLE PARTICULARS

Manufacturer ..... Toyota  
Model ..... Corolla  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... -  
Are you claiming under your own insurance policy for repair to your vehicle? ..... Yes  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 0

### INSURANCE COMPANY

Name of Insurance Company ..... United Overseas Insurance Ltd  
Type of Coverage ..... -  
Fleet Policy ..... No  
Policy Number ..... DHOM110178172100  
Cover Note Number ..... -

### DRIVER

Name of Driver ..... TAN CHEE HONG  
NRIC No ..... SXXXX014Z

✓ Describe Circumstances of the Accident

At around 3pm I was driving slowly out of the car park lot.

I did not notice any car to my left as I was turning right to exit the lot.

Suddenly I heard a small bang and notice my car and the other car has collided.

My left front bumper has collided with the other's car right front bumper.

Both cars came to a halt immediately.

I believe ~~both cars~~ I have right of way as I was already  $\frac{3}{4}$  out of the car lot.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



## Require PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type:

Owner ID: Singapore NRIC

## Vehicle Details

556H

Vehicle No.:

Vehicle to be Exported:

SKQ3950T

Intended Deregistration Date:

No

Vehicle Make:

07 Feb 2022

Vehicle Model:

TOYOTA

Primary Colour:

TOYOTA COROLLA ALTIS 1.6L CVT

Manufacturing Year:

Silver

Engine No.:

2014

Chassis No.:

1ZRX414456

Maximum Power Output:

MR053REH104508531

Open Market Value:

90.0 kW (120 bhp)

Original Registration Date:

\$18,759.00

First Registration Date:

26 Nov 2014

Transfer Count:

26 Nov 2014

Actual ARF Paid:

1

## Intended PARF Rebate Details

\$13,759.00

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

25 Nov 2024

PARF Rebate Amount:

\$8,255.00

## Intended COE Rebate Details

COE Expiry Date:

25 Nov 2024

COE Category:

A - Car up to 1600cc &amp; 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$65,710.00

COE Rebate Amount:

\$18,398.00

Total Rebate Amount:

\$26,653.00

The information contained herein is correct as at 07 Feb 2022

OK