

ASS. REC. BY:

TCLM

REF:

CSM/MSG22001178/Btf3

Denise

## ASSIGNMENT

From:

Date: 21/2/2022

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKN 9573A

at Workshop m/s

Bifrost Auto

of 8kaki Bt Ave 4 Premier #01-49

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

52,000/-

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRSW

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKN 9573A

Yr Regn:

1/8/2014

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 1.6l

c.c 1598

Colour

Brown

AC: Insured / Std / NI / NA

Sp. Reading

109819

T/Radio: Insured / Std / NI / NA

Eng/No:

B004J723N13B16A

C/No:

WBA3A16070N37611

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Jammed / Leaked / Burnt orBrake: ☒ Jammed / Leaked / Burnt or

Modi: Nil / SRM / STD A/Rim or

Tyre Size:

F:

205/60/16

R:

205/60/16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

31/1/2022

D.O.I.

21/2/2022

Survey held at

Bifrost Auto

Des. of Damages: Frt / Rear / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range: 5,000/- - 6,000/-

Recommended CR: LS \$5350.00

finalized amount of LS \$4,050/- 6 Days of repair  
red: 8683.75;68%

MV 52,000/-

PV 31,528/-

NV 20,472/-

TCLM

10/3/2022

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

1)

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format:

Lump Sum / L.B.I. ( )

Company Reg No: 201929175W

Chassis number: WBA3A16070NS37611

2014

DDV ✓  
NECV ✓  
NDX  
BRV ✓  
DDV ✓  
BRV ✓  
NECV ✓  
} NDX  
JM  
NDX

NECV ✓  
NEC ✓  
CUTX R  
NECV ✓  
NECV ✓  
NNX  
NECV ✓

297.00

	Labour and painting		Amount
--	---------------------	--	--------



1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	800.00	\$ 1,200.00	/
2	Spray painting on affected areas and panels	800.00	\$ 1,200.00	/
3	Check wiring and lighting system		\$ 50.00	} NNX
4	Apply rust coating chemical on affected areas and panels		\$ 80.00	
5	Remove and reinstall RH rear door inner mechanism to new door	80.00	\$ 150.00	/
6	Remove and reinstall RH rear fender inner trims, boards, roof lining, carpet and garnish to assist repair	150.00	\$ 350.00	/
7	Remove and reinstall rear windscreen glass to assist repair	120.00	\$ 220.00	/
8	Remove and reinstall rear bumper reverse sensors to assist repair	60.00	\$ 70.00	/
9	Remove and replace rear undercarriage parts to assist repair		\$ 450.00	NNX
10	Test drive and adjust wheel alignment system		\$ 100.00	NNX
11	Remove and reinstall fuel tank, pipes, hoses and sensors to assist repair		\$ 180.00	NNX
			2010.00	
	Total		\$ 4,050.00	

Survey & Resurvey

21/2/2022

1520 hrs

Tim Min

Spare Parts: \$ 6,996.75  
Special Nett: \$ 1,687.00  
Labour: \$ 4,050.00

Total Amount: \$ 12,733.75

Lump sum repair  
Repair days 6

Parts 4401.26

SN 297.00

Labour 2010.00

6708.26

@ 20% 1341.65

5366.60

LS 5350/2

Tim Min  
10/3/2021

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	277U
Vehicle Details	
Vehicle No.:	SKN9573A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	09 Feb 2022
Vehicle Make:	B.M.W.
Vehicle Model:	316i 1.6 AT D/AB 4DR ABS HID
Primary Colour:	Brown
Manufacturing Year:	2014
Engine No.:	B004J723N13B16A
Chassis No.:	WBA3A1607ONS37611
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$31,234.00
Original Registration Date:	01 Aug 2014
First Registration Date:	01 Aug 2014
Transfer Count:	2
Actual ARF Paid:	\$25,728.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Jul 2024
PARF Rebate Amount:	\$15,436.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jul 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$65,002.00
COE Rebate Amount:	\$16,092.00
<b>Total Rebate Amount:</b>	<b>\$31,528.00</b>

The information contained herein is correct as at 09 Feb 2022

OK

MV 52,000/2  
PV 31,528/2  
NV 20,472/2

Tim Min  
10/3/2022



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$68 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

Maserati Levante S GranSport.



Immaculate Condition, Warranty  
And Free Servicing Still Valid!  
Direct Owner StarAd

**PRIME MOTOR & LEASING**  
(CHENG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)  
With over 200 units of vehicles  
to choose from, ranging from  
all European to Japanese Makes.

Sort by  20 results/page

12 vehicles











BMW 316i

Any Category

Advanced Search



Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	<b>BMW 316i</b>		Any	Any	<b>2014</b>	Any	Any	Any	<b>Available</b>
	<b>BMW 3 Series 316i</b>		<b>\$53,800</b>	<b>\$16,320 /yr</b>	<b>30-Sep-2014</b>	<b>1,598 cc</b>	100,063 km	Luxury	<b>Available</b>
Superb Well Maintained Condition. Single Owner. Low Usage At 14'km Clocked Annually. Smooth & Quiet Engine, Test Drive You Will Know! Clean And Neat Interior. Best Selling Executive Sedan, Good Road Handling, Excellent Ride Comfort. Call Us For An Viewing Appoi...									
Posted: 07-Mar-2022									
	<b>BMW 3 Series 316i</b>		-	N.A	<b>30-Sep-2014</b>	<b>1,598 cc</b>	77,215 km	Luxury	<b>Available</b>
No Scratches. No Dents. No Stains. No Marks. No Sticky Parts. Car Like New Car Showroom Looks! Extremely Extremely Extreme Clean. Nothing You Can Find Fault. Examine Test Try Drive Check. Expensive Tyres For Safety. No China Indonesia Korean Tyres. Servicing Done...									
DIRECT OWNER									
Posted: 06-Mar-2022									
	<b>BMW 3 Series 316i</b>		-	N.A	<b>30-Sep-2014</b>	<b>1,598 cc</b>	81,568 km	Luxury	<b>Available</b>
Genuine Mileage On 28 January 2022 : Genuine Mileage: 81568 Km At BMW. Buy Real Genuine Mileage For A Peace Of Mind. This Is Not The Fake Mileage Cars. Request Seller To Go With You To Bmw Singapore To Update The Latest Mileage In The Bmw Service Book. If Th...									
DIRECT OWNER									
Posted: 06-Mar-2022									
	<b>BMW 3 Series 316i</b>		-	N.A	<b>24-Sep-2014</b>	<b>1,598 cc</b>	72,510 km	Luxury	<b>Available</b>
One Owner Only. Real Original Mileage Dated On 22 February 2022 Of Genuine Mileage At,72518km. Real Original Genuine Mileage. Extremely Extremely New Car Looks. Mileage Recorded In BMW Service Agent Official Agent Of,72518km. No Scratches. No Dents. No M...									
DIRECT OWNER									
Posted: 07-Mar-2022									
<b>GET YOUR COE RENEWAL LOAN</b>									
Is your COE expiring? Let us help you renew it!									
Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.									
	<b>BMW 3 Series 316i</b>		-	N.A	<b>28-Aug-2014</b>	<b>1,598 cc</b>	72,528 km	Luxury	<b>Available</b>
Low Mileage Genuine Mileage Recorded 72,528km In Singapore BMW Service Book On 04 March 2022. Zero Sticky Parts. Zero Marks. Zero Sticky Interior. Zero Scratches. Zero Dents. Zero Stains. Zero Ugly Interior Exterior. Beautiful Showroom Looks. Looks Like New Showroo...									
DIRECT OWNER									
Posted: 10-Mar-2022									
	<b>BMW 3 Series 316i</b>		-	N.A	<b>26-Aug-2014</b>	<b>1,598 cc</b>	42,816 km	Luxury	<b>Available</b>
Serviced By PML From Day 1 With Receipt. All Wear And Tears Replaced With Receipts To Prove. Genuine Low Mileage, Parked Under Shelter, Under Utilized.									
DIRECT OWNER									
Posted: 10-Mar-2022									
	<b>BMW 3 Series 316i</b>		<b>\$53,800</b>	<b>\$17,990 /yr</b>	<b>12-Jun-2014</b>	<b>1,598 cc</b>	113,000 km	Luxury	<b>Available</b>
Pristine Condition, Like Brand New. PML Serviced. Parked Under Shelter. Smooth And Quiet Engine. STA Assessed. Full Loan Available. Trade-in Welcome. View To Believe. Do Not Miss This Beauty.									
Posted: 08-Mar-2022									
	<b>s 316i Sport</b>		-	N.A	<b>01-Apr-2014</b>	<b>1,598 cc</b>	-	Luxury	<b>Available</b>
Scratches. Zero Dents. Zero Marks. Zero Stains. Zero Dirt. Zero Sticky Parts. Extremely Totally Extremely Extremely									
DIRECT OWNER									

Compare

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	07/02/2022 15:04 (SGT)
Date of Accident	31/01/2022 13:30 (SGT)
Exact Location of Accident	102 Canberra St, Singapore 751102
Additional Location Information	-
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN9573A
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LIM CHAIN HOONG
Passport No/FIN	F1421277U
Email Address	ilynaynil@hotmail.com
Mobile Phone No	(Phone) +65-81399599
Alternative Phone No	+65-81399599

#### VEHICLE PARTICULARS

Manufacturer	BMW
Model	316i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1598

#### INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	511972372
Cover Note Number	-

#### DRIVER

Name of Driver	LIN YANYI
NRIC No	S8710644F



Date Of Birth	08/04/1987
Occupation	Indoor
Date Of Driving Pass	23/03/2011
Driving experience	10 YEARS AND 10 MONTHS
Gender	Female
Mobile Number	(Phone) +65-81399599
Alt. Phone Number	-
Email Address	inyaynil@hotmail.com
Address	101 JURONG EAST STREET 13 #07-168
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### PASSENGER 1

Name	LIM CHAIN HOONG
Gender	Male

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

ON THE STATED DATE AND TIME, I WAS TRAVELLING TOWARDS THE DROP OFF POINT OF 102 CANBERRA STREET. SUDDENLY, I FELT AN IMPACT AT MY RIGHT PASSENGER DOOR. I ALIGHTED AND FOUND OUT THAT (SLK854C) HAS REVERSED AND COLLIDED ONTO MY VEHICLE.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	NOT AVAILABLE. WITH TP WORKSHOP
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK854C
Vehicle Manufacturer	-
Vehicle Model	-

Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	VEHICLE B
No. Of Passenger (Including Driver)	-

#### INJURED PERSONS DETAILS

##### INJURED 1

Name of injured person	LIN YANYI
Gender	Female
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SKN9573A
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

##### INJURED 2

Name of injured person	LIM CHAIN HOONG
Gender	Male
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SKN9573A
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No



**SKETCH PLAN**

**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (if driver is not the policyholder) / Date & Time

7/2/22 11am  
Witnessed by Reporting Centre Personnel

**Sketch Plan**



### Describe Circumstances of the Accident

On the stated date and time, I (SKN 9573A) was travelling towards the drop-off point of 102 Canberra Street. Suddenly, I felt an impact at my right passenger door. I alighted and found out that (SLK 854G) had reversed and collided onto my vehicle.

### Declaration

(We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_

Driver's Signature (If different from above) \_\_\_\_\_  
& Time \_\_\_\_\_

Witnessed by Reporting Centre  
Personnel