

(08/11/13) wef

ASS. REC. BY:

REF:

CC4/LPC22001198/Rea3

196w

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBH 392C

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 15K

Veh No:

GBH 392C

Yr Regn:

2017 / DEC

Type: M/Caf / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

FIAT DOBLO CARRO MAXI 1-6 c.c 1598

Colour

WHITE

A/C:

Insured / Std / NI / NA

Sp. Reading

30695

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZFA26300006999586

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

K5/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CONTINENTAL

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

01/02/22

D.O.I.

01/02/22

Survey held at

VENDA

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



Venda Engineering & Trading Pte Ltd

GST / Company Reg No.: 200411725H

Quotation

From :
VENDA ENGINEERING & TRADING PTE LTD
 8 TUAS AVENUE 18
 SINGAPORE 638892
 Officer in Charge : HOH PEI JIN
 Tel :
 Email :

Customer :
GOLDBELL LEASING PTE LTD
 59 SENOKO ROAD
 SINGAPORE 758123
 Attn :
 Tel : 6494 2800
 Fax No. : 6861 7097

Quotation No. : CQO22-0210008	Quotation Date : 08/02/2022	Terms : 30 DAYS
Vehicle No. : GBH392C	Chassis No. : ZFA26300006G99586	Policy Number : 29146062
Model : DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE		Date of Accident : 07/02/2022
Third Party Insurer : LONPAC		TP Vehicle No. : GBG3585Z
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR WINDSCREEN, RH <i>bro</i>	1	255.3700	255.37
2	REAR WINDSCREEN, LH <i>bro</i>	2	262.4600	524.92
3	REAR TAILGATE, RH <i>lt</i>	1	986.8000	986.80
4	REAR TAILGATE, LH <i>lt</i>	1	1,025.3000	1,025.30
5	REAR BUMPER <i>de</i>	1	797.6900	797.69
6	REAR BUMPER SIDE RETAINER, RH & LH <i>re</i>	1	58.7500	58.75
7	REAR BUMPER REINFORCEMENT ?	1	441.5000	441.50
8	REAR BUMPER REFLECTOR, RH <i>ca</i>	1	65.2000	65.20
9	REAR PANEL, RH <i>lt</i>	1	2,152.1000	2,152.10
10	REAR PANEL, LH <i>X old damaged</i>	1	2,152.1000	2,152.10
11	REAR TAIL LAMP, LH <i>X old damaged</i>	1	379.5900	379.59
12	REAR DOOR WEATHERSTRIP <i>re</i>	1	410.6800	410.68
13	REAR THIRD STOP LAMP ASSY <i>ca</i>	1	87.3100	87.31
14	"DOBLO" EMBLEM <i>re</i>	1	95.2000	95.20
15	"MAXI" EMBLEM <i>re</i>	1	75.7000	75.70
16	LESS 10%	1	-950.8200	-950.82
17	REAR NUMBER PLATE WITH CASING <i>X</i>	1	50.0000	50.00
18	COMPANY LOGO STICKER <i>re</i>	1	750.0000	750.00
19	REVERSE SENSOR <i>lt</i>	1	220.0000	220.00
20	SPEED LIMIT STICKER <i>re</i>	1	20.0000	20.00

C/F 0.00

Page 1 of 3

Mailing Address
 Contact Number (HQ)

: No.1, Sunview Road, #08-15 Eco-Tech@Sunview, Singapore 627615
 : (Tel) : 6355 9014 (Purchasing Dept.) 6355 9015 (Sales Dept.)
 (Fax) : 6254 0424
 : venda_eng@singnet.com.sg

E-mail





Venda Engineering & Trading Pte Ltd

GST / Company Reg No.: 200411725H

Quotation

From :

VENDA ENGINEERING & TRADING PTE LTD
8 TUAS AVENUE 18
SINGAPORE 638892

Officer in Charge : HOH PEI JIN
Tel :
Email :

Customer :

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attn :
Tel : 6494 2800
Fax No. : 6861 7097

Quotation No. : CQ022-0210008	Quotation Date : 08/02/2022	Terms : 30 DAYS
Vehicle No. : GBH392C	Chassis No. : ZFA26300006G99586	Policy Number : 29146062
Model : DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE	Date of Accident : 07/02/2022	
Third Party Insurer : LONPAC	TP Vehicle No. : GBG3585Z	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
21	PAX STICKER <i>M</i>	1	<i>10</i> 20.0000	0.00
22	SILICONE <i>M</i>	2	<i>50</i> 50.0000	100.00
23	PRIMER <i>M</i>	2	25.0000	50.00
24	REMOVE & RENEW THE REAR RH & LH WINDSCREEN	1	<i>160</i> 250.0000	250.00
25	REMOVE & RENEW THE ABOVE MENTIONED PARTS, PANEL BEAT REAR PORTION	1	850.0000	850.00
26	CUT & WELD REAR RH & LH SIDE PANEL, RE-ALIGN REAR RH & LH PORTION	1	1,100.0000 <i>1100</i>	1,100.00
27	TRANSFER PARTS	1	120.0000 <i>60</i>	120.00
28	TO CHECK WIRING	1	120.0000 <i>40</i>	120.00
29	RE-PASTE COMPANY LOGO STICKER	1	120.0000 <i>60</i>	120.00
30	PUTTY & SPRAY PAINT REAR RH & LH TAILGATE, REAR RH & LH SIDE PANEL, REAR BUMPER REINFORCEMENT & REAR BUMPER	1	1,300.0000 <i>800</i>	1,300.00

C/F 0.00

Page 2 of 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mailing Address
Contact Number (HQ)

: No.1, Sunview Road, #08-15 Eco-Tech@Sunview, Singapore 627615
: (Tel) : 6355 9014 (Purchasing Dept.) 6355 9015 (Sales Dept.)
(Fax) : 6254 0424

E-mail

: venda_eng@singnet.com.sg





Venda Engineering & Trading Pte Ltd

GST / Company Reg No.: 200411725H

Quotation

From : VENDA ENGINEERING & TRADING PTE LTD 8 TUAS AVENUE 18 SINGAPORE 638892 Officer in Charge : HOH PEI JIN Tel : Email :	Customer : GOLDBELL LEASING PTE LTD 59 SENOKO ROAD SINGAPORE 758123 Attn : Tel : 6494 2800 Fax No. : 6861 7097
--	--

Quotation No. : CQO22-0210008	Quotation Date : 08/02/2022	Terms : 30 DAYS
Vehicle No. : GBH392C	Chassis No. : ZFA26300006G99586	Policy Number : 29146062
Model : DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE	Date of Accident : 07/02/2022	
Third Party Insurer : LONPAC	TP Vehicle No. : GBG3585Z	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Rasul
Hp 90010068
8 days
45
09/02/22 P1630
Resy after repair

Sub Total	13,627.39
Discount	(0.00)
GST(7.00%)	953.92
Total (SGD)	14,581.31

We accept the above quotation.

VENDA ENGINEERING & TRADING PTE LTD

Authorised Signature



Please conduct the survey at
 Venda Engineering @ 8 Tuas Avenue 18 Level 5 Singapore 638892

Customer's Name & Signature
 Company Stamp/Date



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	07/02/2022 16:22 (SGT)
Date of Accident	07/02/2022 07:15 (SGT)
Exact Location of Accident	BKE, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH392C
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	GOLDBELL LEASING PTE LTD
Company Reg No	1XXXXX196N
Email Address	isaacngcl@gb.com.sg
Mobile Phone No	(Phone) +65-90409759
Alternative Phone No	(Office) +65-64942897

VEHICLE PARTICULARS

Manufacturer	Fiat
Model	Doblo
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	1598

INSURANCE COMPANY

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	29146062
Cover Note Number	-

DRIVER

Name of Driver	JONATHAN BASIL FERDINAND JOHN
NRIC No	SXXXX956A

Date Of Birth 12/06/1988
 Occupation Outdoor
 Date Of Driving Pass 29/03/2011
 Driving experience 10 YEARS AND 11 MONTHS
 Gender Male
 Mobile Number (Phone) +65-90409759
 Alt. Phone Number -
 Email Address isaacngcl@gbl.com.sg
 Address 105 WOODLANDS VIEW #11-10
 Address complement -
 Postcode 737710
 Is the driver the policyholder? No
 If No, Relationship of the Driver with the Insured Hirer
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 2
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

PASSENGER 1

Name UNKNOWN
 Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

ON THE 07/02/2022 AT AROUND 0715HRS, I VEHICLE A (GBH392C) WAS TRAVELLING ALONG BKE(PIE) ALONG THE SECOND LANE AT AROUND 65KM/HR WITH A PASSENGER ON BOARD. VEHICLE AHEAD OF ME INITIATED A JAM BRAKE AND I FOLLOW SUIT. SHORTLY AFTER AROUND A FEW SECONDS, I SAW ON MY REAR MIRROR VEHICLE B(GBG3585Z) WAS TAIL FISHING AND I HELD ON MY PASSENGER BRACING FOR IMPACT. IMPACT IS HARD AND THERE IS NO INJURIES AT THE MOMENT.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBG3585Z
 Vehicle Manufacturer -
 Vehicle Model -

Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

BKE (PIE)

A - G8H392C

B - G8G3585Z



Dahnial

Describe Circumstances of the Accident

ON THE 07/02/2022 AT AROUND 0715HRS. I VEHICLE A (GBH392C) WAS TRAVELLING ALONG BKE(PIE) ALONG THE SECOND LANE AT AROUND 65KM/HR WITH A PASSENGER ON BOARD. VEHICLE AHEAD OF ME INITIATED A JAM BRAKE AND I FOLLOW SUIT. SHORTLY AFTER AROUND A FEW SECONDS. I SAW ON MY REAR MIRROR VEHICLE B(GBG3585Z) WAS TAIL FISHING AND I HELD ON MY PASSENGER BRACING FOR IMPACT. IMPACT IS HARD AND THERE IS NO INJURIES AT THE MOMENT.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time
07/02/2022 0715

Dahnial

Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	196N
Vehicle Details	
Vehicle No.:	GBH392C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	28 Feb 2022
Vehicle Make:	FIAT
Vehicle Model:	DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	263A50002183491
Chassis No.:	ZFA26300006G99586
Maximum Power Output:	-
Open Market Value:	\$20,282.00
Original Registration Date:	28 Dec 2017
First Registration Date:	28 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$1,015.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$57,701.00
COE Rebate Amount:	\$33,596.00
Total Rebate Amount:	\$33,596.00

The information contained herein is correct as at 08 Feb 2022

OK

Fiat Doblo Cargo Maxi 1.6A Multijet Glaze

Overview

Financial

Accessories

Similar

Research

Photos

Map



YOUR ONE-STOP COMMERCIAL VEHICLE
SOLUTION PROVIDER

Price	\$44,800	Lifespan ⓘ	01-Jun-2037
Depreciation ⓘ	\$8,440 /yr View models with similar depre.	Reg Date	02-Jun-2017 (5yrs 3mths 22days COE left)
Mileage	113,695 km (24.2k /yr)	Manufactured ⓘ	2016
Road Tax ⓘ	N.A.	Transmission	Auto
Dereg Value ⓘ	\$16,239 as of today (change)	Fuel Type	Diesel
COE ⓘ	\$30,600	OMV ⓘ	\$18,800
Engine Cap	1,598 cc	ARF ⓘ	\$940
Curb Weight ⓘ	1,500 kg	No. of Owners ⓘ	1