

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *FBR3069P*at Workshop m/s *AHM Performance*of *02-46 AH Hong*Insured: *SM759404*

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: *£16k*

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: *97907538*Veh No: *FBR3069P*Yr Regn: *04/104/20*

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *XMAR320*Make: *Kiaho 020300A*

c.c

*292*Colour: *Grey*

A/C:

Insured / Std / NI / NA

Sp. Reading: *27277*

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: *MH35H0841K009552*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: *120/70-15*R: *140/70-14*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *metre/r*

Front

Rear

R/Bal. *7*

mm

R/Bal. *7*

mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. *27/1/22*D.O.I. *10/2/22*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear 2 O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA to 3168 request of report

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$)☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

☐

: Weekend (\$)

) \$ + RS. \$

) Photos

) Others

Report Format : _____

Lump Sum / I.B.I: (\$) _____)

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	559G
Vehicle Details	
Vehicle No.:	FBR3069P
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Feb 2022
Vehicle Make:	YAMAHA
Vehicle Model:	CZD300A / XMAX300
Primary Colour:	Green
Manufacturing Year:	2019
Engine No.:	H336E0069455
Chassis No.:	MH35H0841LK009552
Maximum Power Output:	-
Open Market Value:	\$4,463.00
Original Registration Date:	04 Apr 2020
First Registration Date:	04 Apr 2020
Transfer Count:	3
Actual ARF Paid:	\$670.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	03 Apr 2030
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$3,889.00
COE Rebate Amount:	\$3,168.00
Total Rebate Amount:	\$3,168.00

The information contained herein is correct as at 10 Feb 2022

OK

2/10/22, 9:16 AM

Used MotorCycles/Bikes For Sale in Singapore by Owners & Dealers - SGBikemart

Vehicle Type : Scooters

Mileage

19702km

SGD \$15500

Posted on 19/12/2021

★ Paid Ad

★ Direct Seller

Details >



Yamaha Xmax 300

Reg Date : 15/05/2019

Capacity : 292cc

Vehicle Type : Scooters

Mileage : 43000km

SGD \$18000

Posted on 09/02/2022

★ Direct Seller

Details >



Yamaha Xmax 300

Reg Date : 02/11/2018

Capacity : 292cc

Vehicle Type : Scooters

Mileage : 46000km

SGD \$22000

Posted on 08/02/2022

★ Direct Seller

Details >



Yamaha Xmax 300

Reg Date : 25/03/2020

Capacity : 292cc

Vehicle Type : Scooters

Mileage : 33000km

SGD \$17000

Posted on 07/02/2022

★ Direct Seller

Details >



Yamaha Xmax 300

Reg Date :

Vehicle Type :

Posted on 05/02/2022

Manulife

From a room for two to a

★ Direct Seller

Details >

FR3069P Xmax300 9.2.22

Rear side cover "R" (F1741-00) Dark green
 Footrest board "R" black padnel (F7488-00)
 Battery cover black panel (B74-H2129-00) ty
 Front body cowling "R" (F8371-00) Dark green
 Front body under black panel "R" (F83SK-00)
 Brake lever "R"
 Mirror "R"
 Air box
 Rear numberplate
 Rear suspension
 R&G exhaust guide
 Exhaust pipe
 Handle balance
 Ton
 Labour

Cu1	£105	✓
Cu1	£90	✓
Cu1	£75	✓
Cu1	£98	✓
Cu1	£70	✓
Cu1	£24	✓
Cu1	£65	✓
Cu1	£180	✓
3cu1	£48	38
5VU	£198	X
Cu1	£120	✓
	£600	?
Cu1	£120	✓
	£60	?
	£450	28

Not Allowed

1/15

3 days.

10/7/22

Telephone After 14...

90096608

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: