
























Report No: 0781-18-TCA

26 November 2018

ACCIDENT VEHICLE SURVEY REPORT

Ng Gek Huay
Blk 236 Compassvale Drive #15-516
Singapore 540236

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SKJ6080X	<i>Odometer:</i>	123781km
<i>Make & Model:</i>	Volkswagen Scirocco 1.4L	<i>Colour:</i>	Silver
<i>Chassis number:</i>	WVWZZZ13ZCV034933	<i>Date of accident:</i>	24/05/2018
<i>Year of Regn.:</i>	08/08/2012	<i>Date inspected:</i>	28/05/2018
<i>Repairer at:</i>	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	06/06/2018

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.































