

ASS. REC. BY:

REF:

CS/GAI22001242/Aqf3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. **CLMOMVC000004122**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **4** days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **YQ5071B** Yr Regn: **2021 / Nov**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Hino XZU710R** c.c **4009**

Colour **White** A/C: Insured / Std / NI / NA

Sp. Reading **756** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **JH44CV3FXOK041419**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **195/85R16**

R: **195/85R16**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. **06** mm R/Bal. **06** mm

L/Bal. **06** mm L/Bal. **06** mm

D.O.A. _____ D.O.I. **11/02/22**

*Survey held at **Chery Motor**

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Great American
	LS \$2500, 4 days. (Red \$6159.80, 71%)
	MV :
	PV :
	Nett :
	1776

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: **4**

1) **19/04** Typist

: Final Report

Resurvey No. of Trip: **2**

Survey Fee:

Transportation:

Date/Time, File Return to?

3 + RS \$

2)

Add Fee: : Site Insp (\$)

Photos

Report Format: **TP**

: Interview (\$)

Other

LEAD SUM TOTAL \$ **2500**

: Tech. Invs (\$)

: Washhand (\$)

Date Of Birth	08/07/1986
Occupation	Outdoor
Date Of Driving Pass	06/12/2013
Driving experience	8 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-93762207
Alt. Phone Number	-
Email Address	allan8514@yahoo.com
Address	51 NORTH COAST AVE
Address complement	#03-35
Postcode	756992
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLS REFER TO THE ATTACHED STATEMENT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD5775J
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	NACHIMUTHU KUMAR
Passport No/FIN	GXXXX575R
Contact Number	(Phone) +65-96181373
Address	-

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 09/02/2022 11:22 (SGT)
Date of Accident 08/02/2022 14:13 (SGT)
Exact Location of Accident Woodlands Ave 9, Singapore
Additional Location Information SHELL PETROL KIOSK
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number YQ5071B

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner YES AIR-COND ENGRG PTE LTD
Company Reg No XXXXXXXXXC
Email Address allan8514@yahoo.com
Mobile Phone No (Phone) +65-90227811
Alternative Phone No +65-90227811

VEHICLE PARTICULARS

Manufacturer Hino
Model XZU710R 14FT WID CAB 5T MT
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Commercial vehicle
Transmission Manual
CC 4009

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number DMCVSNW00148182100
Cover Note Number -

DRIVER

Name of Driver RAMASAMY KATHIRVEL
Passport No/FIN GXXXX775U

Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



R. Kethel

8. 2. 22.

ojym 09/02/22

Sketch Plan

WOODLANDS AVE 9 SHELL PETROL KIOSK



A - YQ5071B
B - XD5775J

Describe Circumstances of the Accident

I pumped petrol at woodland Ave 9 shell petrol kiosk pump no 1. After pumped petrol, I make payment at the counter. When I came back I saw damages on my front veh. I went back to the counter and ask them to look at CCFV. ^{Shell} After the manager looked at the CCFV, the manager give me the TP veh no and their office contact no.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

R. Thiriel 8.2.22
 Driver's Signature (if driver is not the policyholder) / Date & Time

Shym 09/02/22
 Witnessed by Reporting Centre Personnel