

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 19960/198R GST Reg. No. 19-960/198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	ALLIED WORLD A	SSURANCE COMPANY LTD	Re	ef: CS/AWA22001260/Vqf3e2	
	(SINGAPORE BRA 60 ANSON ROAD MAPLETREE ANS SINGAPORE 0799	#08-01 (8th FLOOR) ON	Da	ate: 18/05/2022	
			Co	ode: AWA	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	GBF 351G	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C070835/001-001	Excess (\$)	0.00	
	Assign From	SHIRLEY TAN	Assign Date	10/02/2022	
2. Vehicle Particulars & Condition					
	Make & Model	PEUGEOT PARTNER	c.c	1560	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	VF37F9HF8FJ884521	Colour	WHITE	
	Odometer	235741 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.					
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	BRIDGESTONE	5 mm	
	L/H Front Tyre	195/65 R15	BRIDGESTONE	5 mm	
	R/H Rear Tyre	195/65 R15	BRIDGESTONE	5 mm	
	L/H Rear Tyre	195/65 R15	BRIDGESTONE	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5. General Information					
	Accident Date	07/02/2022	Inspection Date	10/02/2022	
	Survey held at AUTO BOLT BODY & PAINT PTE LTD				
	8 KAKI BUKIT AVENUE 4 #03-01 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: