

NGS MOTORSPORT PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK AutoPoint Singapore 568047
Tel : 9695 5547 Fax: 6481 5727 e-mail : evelynnstrading@gmail.com
Reg No: 201812604N

10/2/2022

Ergo Insurance Pte Ltd
5 Temasek Boulevard
Singapore 038985
Attn: Motor Claims Dept

*Not Authorised
61 Rm @ 155dp
Merry After Pain
4 days*

RE: Accident On 21/01/2022 @14:30Hrs
Along Moonbeam Walk, Involving SJT3199S & YN2641S
Claims Against YN2641s
Your Claim Ref: CDMCG22000154

We submit herewith our direct claim estimate quotation as follow:-
Replacement parts - Toyota Vios

1	Frt Bumper		CM	\$	447.90	✓
1	Frt Bumper Retainer LH			\$	56.50	✓
1	Cover, Frt Bumper Fog Lamp LH			\$	80.81	X
1	Bonnet		R	\$	465.17	✓
2	Frt bumper side retainer RH/LH	Repair	\$	48.16	\$	96.32 X
20	Clips, Fender liner		\$	3.50	\$	70.00 X
1	Frt logo "Badge"	S.nett			\$	45.30 ✓
1	Support panel				\$	256.70 X
1	Brace panel				\$	43.00 X
1	Frt Bumper Grille Lower	251			\$	56.00 X
1	Radiator Grill				\$	138.90 ✓
1	No plat	\$40 S.nett	Not ✓			

To remove frt damaged part with all necessary component/attachn.
Straighten chassis member, repair/reshape dented body panel..
Replace damaged part. Refit into position.

\$ 600.00 500

To spray painting -

\$ 600.00 550

Check wiring & light function

\$ 50.00 20

\$ 3,006.60

Any other parts which necessitate repair or renewal will incur additional charged.
Please contact our Ms Evelyn @HP96955547 to arrange for survey. Thank you

Yours faithfully.

NGS MOTORSPORT PTE LTD
EVELYN NG

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 24/01/2022 14:04 (SGT)
Date of Accident 21/01/2022 14:30 (SGT)
Exact Location of Accident Singapore
Additional Location Information MOONBEAM WALK
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJT3199S
INSURED/POLICYHOLDER
Is company? Yes
Name Of Registered Owner ABOI CAR RENTAL
Company Reg No 53378618E
Email Address ABOICARACCIDENT@GMAIL.COM
Mobile Phone No (Phone) +65-98800332
Alternative Phone No +65-98800332

VEHICLE PARTICULARS

Manufacturer Toyota
Model Corolla
Variant Altis
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private hire
Transmission Auto
CC 1600


INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type of Coverage ThirdPartyFireTheft
Fleet Policy No
Policy Number 5113388789-02
Cover Note Number 20/08/2021 - 19/08/2022

DRIVER

Name of Driver TAN KIAN HO
NRIC No S7316078B

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle was stationary parked at along the Moonbeaam walk behind of vehicle B. Awhile later vehicle B driver came to my client house and informed me that his vehicle rolled back into my vehicle front as the road was sloped. After which I assess the damage, took some photos and exchange particulars. The whole conversation between driver B and me was recorded in my phone. No one was injured in this accident.

Declaration

I/We declare the foregoing particulars are true in every respect

ABOI CAR RENTAL

Reg No 53378618E
81 TAGORE LANE
#04-19 TAG A
SINGAPORE 787502
24/01/22 13:53

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Ganesh (S993561)
Customer Care Executive
Motor Service Centre

Witnessed by Reporting Centre Personnel