

Figure 1. Sketch Diagram of Forklift Incident at Block 22 (6R2) of PLAD




Figure 2. Placement Position of Pallet #3 (P3) on PTC Lorry




Figure 1: Schematic Diagram



Figure 2A: Front of MID 51257



Figure 2B: Back of MID 51257



Figure 2C: Side of MID 51257



Figure 2D: Opposite side of MID 51257



Figure 3A: Back of GBJ 8874R



Figure 3B: Left and Right side of GBJ 8874R



Figure 3C: Front of GBJ8874R



Figure 3D: Close up of damage

Statement of ME1 Koh Wen Hao Jason

On 06 0930H Jan 22, I (ME1 Koh Wen Hao Jason SXXXX608I) was tasked to load RAI boxes to PTC (Peck Tiong Chun) vehicle for PYAD (Paya Lebar Ammunition Depot). Upon drawing the forklift, I did my BOC and went to 6R2 to park my forklift while waiting for the arrival of PYAD PTC vehicle.

At 06 1220H Jan 22, PYAD PTC vehicle arrival, I pause my work for 6R2 and go to load the RAI Boxes. I proceed to collect the RAI boxes of M2A1 on the extreme left side on block 22.

At 06 1240H Jan 22, on my third pallet I went to the container which was at extreme right side of block 22 to take the RAI boxes of M2 boxes. Upon going into the issue bay I accidentally knock onto the MMRC vehicle as I misjudge the turning radius and hit the passenger side of the vehicle. Where it was dented at the bottom left passenger door of the vehicle.

At 06 1242H Jan 22, I have reported it to my superior on the incident.

Jason
Koh

Digitally signed
by Jason Koh
Date:
2022.01.06
15:19:05 +08'00'

Figure 4: Driver's statement



**SINGAPORE
POLICE FORCE**



G/20220126/2102

1 of 2

POLICE REPORT (NP299)

Report No. G/20220126/2102

Police Station Of Origin
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

Date/Time Report Made 26/01/2022 18:17	Vide Report No.	Station Diary No. 36
Name Of Informant KOH WEN HAO, JASON	Address [REDACTED]	
ID Type / ID No. NRIC NO / [REDACTED] 6081	Contact No. Home/Office	Mobile [REDACTED]
Nationality SINGAPORE CITIZEN	Email Address jasonkohjkw@ gmail .com	
Occupation Army Personnel	Sex Male	Age 26
Institution/School Name	Date of Birth 26/05/1995	Race Chinese
Date/Time Of Incident 26/01/2022 12:20	Location Of Incident 110 PASIR LABA ROAD PASIR LABA CAMP SINGAPORE 637899 Ammunition Depot	

Brief details.

On the 06/01/2022 at or about 0930hrs., I was deployed to load Recoverable Ammunition Items (RAI) boxes onto a Peck Tiong Chun vehicle.

At or about 1220hrs, I proceeded to collect the RAI boxes to be loaded to the vehicle, I was driving a forklift(MID51257), while loading the pallet, I accidentally knock into a MMRC vehicle, GBJ8874R, as I

Signature Of Officer Recording The Report: G / Sgt 2 BENNY TAN KENG HONG 	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 26/01/2022 18:17
Officer In-Charge Of Case: G / Bedok Police Divisional Investigation Branch / Other TAN YU KAI, JUSTIN Contact No.:	Classification Of Case:
Authentication Stamp 	

Figure 5A: Police Report Part 1



**SINGAPORE
POLICE FORCE**



G/20220126/2102

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20220126/2102

misjudged the turning radius, and hit the left passenger door of the vehicle. The passenger door sustained a dent.

No government properties was damaged in the incident, no one was injured.

I am lodging this report for record purpose.

Signature Of Officer Recording The Report:
G / Sgt 2 BENNY TAN KENG HONG

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
26/01/2022 18:17

Officer In-Charge Of Case:
G / Bedok Police Divisional
Investigation Branch /
Other TAN YU KAI, JUSTIN
Contact No.:



Classification Of Case:

Authentication Stamp

SIGNATURE

Figure 5B: Police Report Part 2