



Schematic of Incident Choa Chu Kang Ave 3



Schematic of Incident Choa Chu Kang Ave 3



Photographs of the Accident Vehicle

Front View of MID 21976



Rear View of MID 21976



Left Side View of MID 21976



Right Side View of MID 21976




Photographs of the Accident Vehicle

Zoomed In View of MID 21976




- Damage Assessment:
 - Right blindspot mirror shattered.


SINGAPORE ARMED FORCES
STATEMENT OF DRIVER/WITNESS

STATEMENT OF	CPL MOHAMAD RIDUAN BIN ROSLAN				ALIASES				
NRIC NO	5172	AGE	21		MALE/FEMALE	MALE			
EMPLOYMENT	NSF	DRIVING LICENCE NO	SAF/TPT/00263/21		NATIONALITY	Singaporean			
DIALECT	-	LANGUAGE SPOKEN	English		TEL NO				
ADDRESS									
INTERPRETED BY	N.A.	RANK	N.A.	TIME	N.A.	DATE	N.A.	SIGN	N.A.
RECORDED BY		RANK		TIME		DATE		SIGN	
<p>I, 5172, CPL MOHAMAD RIDUAN BIN ROSLAN, drew my vehicle, MID 21976, Hiera cp for Cyrus Battery Rot 1 FTR 1. BOS was done at 0620 hrs and was standing by to move off ^{to T63} while waiting for the guns to hook up. Approximately 0715 hrs, we moved off being the vehicle behind DET 6 and ration tonner, MID 20443, behind my vehicle. After exiting the camp, I turned right towards Choa Chu Kang way and proceeded to turn right onto Choa Chu Kang Ave 3. As I approached the first traffic light, it turned red and I stopped. While ^{stationary} waiting, I was checking my left and right mirror as there was construction going on, I had to keep center or slightly right of my lane, but did not want into the right lane. I ^{was} checking my right mirror when I saw a civilian private bus driving quite fast on the right lane, when the bus got closer he did not slowdown and ended up hitting my right blindspot mirror. ^{at around 0745 hrs} The bus driver, PC 8679 J, came down and exchange contacts number and after that I called my commander 3SG1 Adli to inform him of the incident while my vehicle commander inform his side. I placed the break down sign while waiting for further instructions.</p>									
DATE	180122		SIGNATURE OF DRIVER/ WITNESS						

SINGAPORE ARMED FORCES
STATEMENT OF DRIVER/WITNESS

STATEMENT OF	3 SG LAU XIANG YU				ALIASES	N/A	
NRIC NO	██████ ISIC	AGE	19		MALE/FEMALE	MALE	
EMPLOYMENT	NSF	DRIVING LICENCE NO	N/A		NATIONALITY	SINGAPOREAN	
DIALECT	N/A	LANGUAGE SPOKEN	ENGLISH		TEL NO	██████████	
ADDRESS	██						
INTERPRETED BY	N/A	RANK	N/A	TIME	N/A	DATE	N/A
RECORDED BY		RANK		TIME		DATE	
<p>I, ██████ ISIC, 3 SG LAU XIANG YU was the front passenger for MID21976 when it was moving from 215A garage to TP3. At around 0745, the vehicle stopped for a red light at Choa Chu Kang Ave 3. The vehicle was at a complete stop when a dark red bus went past, and I heard cracking sound from the right. We looked over to the right and realise that the bottom right rear-view mirror was broken. The accident happened on a 2-lane road, with the hira CP on the left, and the bus on the right. There was construction work on the left, which resulted in a narrower lane than usual.</p>							
DATE	180122		SIGNATURE OF DRIVER/ WITNESS				

SINGAPORE ARMED FORCES
STATEMENT OF DRIVER/WITNESS

STATEMENT OF	2LT XU KAI				ALIASES	N/A			
NRIC NO	██████ 5416	AGE	20		MALE/FEMALE	MALE			
EMPLOYMENT	NSF	DRIVING LICENCE NO	N/A		NATIONALITY	SINGAPOREAN			
DIALECT	N/A	LANGUAGE SPOKEN	ENGLISH		TEL NO	██████████			
ADDRESS	██								
INTERPRETED BY	N/A	RANK	N/A	TIME	N/A	DATE	N/A	SIGN	N/A
RECORDED BY		RANK		TIME		DATE		SIGN	
<p>I, ^(CHIEF) ████████ 5416, 2LT XU KAI, was the Vehicle Commander for vehicle MID 21976 6-ton CP vehicle. We were driving from Kranji Camp III to TP3 along Sengkang Avenue 3, and we stopped at the traffic light before bus stop 44511 (before block 249) at 0745hrs. We were on the left lane, and there were barriers set up on our left for construction, while the light was red, a maroon colored civilian ^{private} bus drove up to the traffic light on the right lane. As it slowed to stop at the traffic light, the left rearview mirror of the bus hit the right rearview mirror of our vehicle. After the collision, we noticed that the bottom (blindspot) mirror was missing, and the frame of the mirror was broken on the right side. The bus then moved and stopped at the bus stop temporarily so we could talk up with our TO. We got the contact & the license plate from the bus driver. The mirror was picked up by another vehicle in the convoy.</p> <p>The vehicle was completely stationary prior to the incident, and the vehicle was positioned clearly in the left lane to the best of the TO's ability given the construction barriers. MT-RAC was carried out prior to us moving off at 0755hrs.</p>									
DATE	18/01/2022		SIGNATURE OF DRIVER/ WITNESS						



**SINGAPORE
POLICE FORCE**



T/20220118/2105

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

1 of 3

Report No. T/20220118/2105

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/01/2022 22:14	Vide Report No.:	Station Diary No.: 76
--	------------------	--------------------------

Informant's Particulars

Name of Informant: MOHAMAD RIDUAN BIN ROSLAN			Address: [REDACTED]	
ID Type / ID No.: NRIC NO / [REDACTED] 517Z			Contact No.: Home/Office: [REDACTED] Mobile: [REDACTED]	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 21	Date of Birth: 25/10/2000	Type of Informant: Driver	
Race: Malay			Language:	Institution / School Name:
Occupation: National Service Full Time			Driving Licence Information: Class: [REDACTED] Date of Expiry: [REDACTED]	

General Information of the Accident

Type of Accident: Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 18/01/2022 07:45	Type of Location: Straight Road
Location: CHOA CHU KANG AVENUE 3			
Weather: Clear	Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way	Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Moving vehicle against stationary vehicle			Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
21976MID	6 Ton Command Post Tonne				Slightly Damaged	7
PC8679J	Bus/Coach/Mi nibus				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20220118/2105

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

2 of 3

Report No. T/20220118/2105

CONTINUATION OF REPORT

Brief Details.

I am an NSF with Singapore Armed Forces and my current vocation is as a transport operator. I have a valid Singapore Armed Forces driving permit and I am permitted to drive class 3 & 4 of Military motor vehicles.

On 18/01/2022 at about 0745 hours, I was driving the 6 Ton Command Post Tonner bearing plate number 21976MID along Choa Chu Kang Avenue 3 on the left lane of a two-lane road, heading towards Brickland Road.

I wish to state that as I entered Choa Chu Kang Avenue 3, there were barricades on the left side of the road (along the double yellow line). As such, I had to adjust the position of the vehicle to be slightly away from the allocated left lane on the road.

While driving along that road, the traffic light (Beside Block 286 Choa Chu Kang Avenue 3) along that road turned red. I then stopped the vehicle.

Thereafter, I noticed one commercial bus bearing plate number PC8679J approaching on the right lane. As it drove on the side of the vehicle I was driving, its left side mirror collided onto my right-side mirror.

Due to that, the right-side mirror of the SAF vehicle was damaged (glass fell off & cracked frame).

I then exchanged particulars with the bus driver. The particulars of the driver are as follows:

Chue Yock Chin
[REDACTED] 837F
Tong Wei Bus Services
9326 5386

I wish to state that there were no injuries to any party.



**SINGAPORE
POLICE FORCE**



T/20220118/2105

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

3 of 3



Report No. T/20220118/2105

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

<p>Signature of Officer Recording The Report</p> <p>J /</p> <p>Sgt J ABRAM KARNAIN BIN 'AZI</p>  <p>Signature Of Interpreter:</p> <p>Not applicable</p> <p>SIGNATURE</p>	<p>Signature Of Informant:</p>  <p>Date/Time:</p> <p>18/01/2022 22:14</p>
<p>Officer In Charge Of Case:</p> <p>TP / GIA /</p> <p>DSP (2) YIP YEW SENG NELSON</p> <p>Contact No.: 65476182</p> <p>Authentication Stamp</p> <p>NP168</p>	<p>Classification Of Case:</p>

