



Service Request Details

Claim

S2M03T08

Reference

CS3/ASM22001290/Eqy3 

Loss Date

5 February 2022

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

10 Feb 2022 9:38:11 AM

Request Date

10 February 2022

Due Date

17 February 2022

Services

Pre-Repair Survey

Actions

Next Step

Agree to perform service

Decline Work

Vehicle Information

Incident Vehicle Registration #
FBQ9961D

Make
TPVD -Yamaha

Model
Aerox

Service Address

, , ,

Primary Contact/Insured

YU ZHUO
BLK 365B UPP SERANGOON ROAD, #17-1066, 532365, Singapore
94896332
ZHUO0417@GMAIL.COM

Claim Handler

ONG Kian Theng Derick

derick.ongkt@axa.com.sg

Additional Instructions

- Messages1
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document SubType

▼

 Upload Documents

Already Attached

NAME	 GA545619-Policy Schedule.pdf.pdf
TYPE	Forms / Claim Documents
SUBTYPE	Policy Schedule / Covernote / Certificate of insurance
AUTHOR	PODUVAL, Akash
DATE UPLOADED	10 February 2022

NAME	 GA545619-Certificate of Insurance.pdf.pdf
TYPE	Forms / Claim Documents
SUBTYPE	Policy Schedule / Covernote / Certificate of insurance
AUTHOR	PODUVAL, Akash
DATE UPLOADED	10 February 2022

NAME	 TP PRI PDF.pdf.pdf
TYPE	Letters and Correspondence
SUBTYPE	Solicitor / Advocate
AUTHOR	PODUVAL, Akash
DATE UPLOADED	10 February 2022

NAME	 TP GIA REPORT.pdf.pdf
TYPE	Reports & Statement
SUBTYPE	GIA Report
AUTHOR	PODUVAL, Akash
DATE UPLOADED	10 February 2022
