



Service Request Details

Claim

S2M03T1H

Reference

CS3/ASM22001296/Rqy3 

Loss Date

9 February 2022

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

10 Feb 2022 2:40:01 PM

Request Date

10 February 2022

Due Date

10 February 2023

Services

Standard workshop survey

Actions

Next Step

Finish the work

Complete Work

Vehicle Information

Incident Vehicle Registration #

SMN3116C

Make

TPVDHonda

Model

FIT

Service Address

''''

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

ONG Kian Theng Derick

derick.ongkt@axa.com.sg

Additional Instructions

Messages3

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE



SENT

22/4/22 12:16 PM

BODY

Dear Sir/Madam, please be informed that the TP PRS...



TYPE



SENT

15/2/22 9:20 PM

FROM

ONG Kian Theng Derick

SUBJECT

WORKSHOP DETAIL

BODY

Hi, Please refer to linked documents for details....



TYPE



SENT

10/2/22 3:20 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

WORKSHOP DETAIL

BODY

Dear Derick, Thank you for the assignment. Please ...

