

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	SOMPO INSURAN	ICE SINGAPORE PL	Ref:	CS3/SMO21009204/Aqf3e2-1	
	50 RAFFLES PLAC SINGAPORE LAN	CE #03-03 D TOWERSINGAPORE 048623	Date:	04/04/2022	
			Code	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLM 2268X	Veh. Inspected	GBK 4061R	
	Policy No.	D21NTPV01002713	Coverage (\$)	0.00	
	Claim No.	CMTD2102627/LOR	Excess (\$)	0.00	
	Assign From	GNOH PAU LOONG	Assign Date	11/02/2022	
2. Vehicle Particulars & Condition					
	Make & Model	NISSAN NV350	c.c	2488	
	Engine No.	HIDDEN	Year of Reg.	2020	
	Chassis No.	JN1MC2E26Z0032255	Colour	WHITE	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195 R15C	MICHELIN	6 mm	
	L/H Front Tyre	195 R15C	MICHELIN	6 mm	
	R/H Rear Tyre	195 R15C	MICHELIN	6 mm	
	L/H Rear Tyre	195 R15C	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	31/08/2021	Inspection Date	02/09/2021	
	Survey held at	GARAGE 13 PTE LTD			
	8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.				
5a.	. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				