


REC BY: Thuan | TMT

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
QD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 5H410F Yr Rogn: 9/1/19
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius hybrid c.c. 1798

Colour: Yellow AC: _____ Insured / Std / NI / NA

Sp. Reading: 409694 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STDK83Fus03078187

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NII / SIRM / STD A/Rlm or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. S mm R/Bal. S mm

L/Bal. S mm L/Bal. S mm

O.O.A. 9/2/22 D.O.I. 10/2/22 1700

Survey held at CDGE

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

NO GIA provided

Deadline, File Pass to?

☐ : Prelim. Report

1)

☐ : Final Report

Deadline, File Return to?

3)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : Wash and

Survey Fee:

Transportation:

S + RS \$

Prints

Others

Request Form:

Form Sing / B.J. 12

ComfortDelGro Engineering Pte Ltd (CA REG NO: 10007800000)

591 MYANG DRIVE
SINGAPORE 410669
Tel: 6214 8300

TP INSURER:
CCPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	09/02/2022
Vehicle Reg. No.:	SHC110E	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS, 1.8 HYBRID	Vehicle Reg. Date:	09/01/2019
	CVT (A)		
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	2ZR2B88504	Chassis No:	JTDKB3FU503078187
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair	3		
(day)			
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	1,385.72
Miscellaneous Items	11.00
Labour	820.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,216.72
+ GST 7.00% (S\$)	155.17
Nett Amount (S\$)	2,371.89

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Repairer Estimates

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Feb 2022)
Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHC110E/10/02/2022 14:07
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	25.00	0.00	*458.60 FL (qt
2	1		*REAR BUMPER CENTER COVER	25.00	0.00	*552.60 FL /scr
3	1		*REAR BUMPER EXTENSION RH	25.00	0.00	*232.00 FL xr
4	1		*REAR BUMPER TOW COVER	25.00	0.00	*82.70 FL /DPS
5	10		*REAR BUMPER CLIPS	25.00	0.00	*22.00 FL /ne
6	1		*REVERSE SENSORS	0.00	0.00	*135.70 F /lat
7	1		*REAR BUMPER REINFORCEMENT	25.00	0.00	*318.80 FL 7.

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)

1,802.40

- List Item Discount on L Items (S\$)

416.68

Total Parts (S\$)

1,385.72

ComfortDelGro Engineering Pte Ltd/SHC110E/10/02/2022 14:07. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

10/02/2022

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	400.00 350
2	SPRAY PAINTING	New	300.00 250
3	R/I REVERSE SENSORS	New	120.00 30
Gross Labour Cost (\$\$)			820.00

ComfortDelGro Engineering Pte Ltd/SHC110E/10/02/2022 14:07. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thuan 82235769
10/2/22 1700
P/P b4u paint photo
2days w/p

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: