

⏪

⏩

1 of 2 ?

⏴

⏵

↺

↻

100% ▾

📄 ▾

🖨

Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|                                                                                                                                        |                                                                                            |      |                          |            |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|------|--------------------------|------------|
| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                            |      |                          |            |
| MS FIRST CAPITAL INSURANCE LTD                                                                                                         |                                                                                            |      | Ref: CS/FCI22001321/Vvf3 |            |
| 36 ROBINSON ROAD                                                                                                                       |                                                                                            |      | Date: 11/02/2022         |            |
| #16-01 CITY HOUSESINGAPORE 068877                                                                                                      |                                                                                            |      | Code: FCI2               |            |
| 1. Policy Particulars :- THIRD PARTY CLAIM                                                                                             |                                                                                            |      |                          |            |
| Insured Veh.                                                                                                                           | GBA 9523U                                                                                  |      | Veh. Inspected           | FBP 3260M  |
| Policy No.                                                                                                                             |                                                                                            |      | Coverage (\$)            | 0.00       |
| Claim No.                                                                                                                              | D22000398MFCV                                                                              |      | Excess (\$)              | 0.00       |
| Assign From                                                                                                                            | AINI BINTE                                                                                 |      | Assign Date              | 11/02/2022 |
| 2. Vehicle Particulars & Condition                                                                                                     |                                                                                            |      |                          |            |
| Make & Model                                                                                                                           |                                                                                            |      | c.c                      | 0          |
| Engine No.                                                                                                                             | HIDDEN                                                                                     |      | Year of Reg.             |            |
| Chassis No.                                                                                                                            |                                                                                            |      | Colour                   |            |
| Odometer                                                                                                                               | -                                                                                          |      | Steering                 |            |
| Brakes                                                                                                                                 |                                                                                            |      | Modification             |            |
| General                                                                                                                                |                                                                                            |      |                          |            |
| 3. Conditions of Tyres                                                                                                                 |                                                                                            |      |                          |            |
|                                                                                                                                        |                                                                                            | Size | Make                     | Balance    |
|                                                                                                                                        | R/H Front Tyre                                                                             |      |                          | mm         |
|                                                                                                                                        | L/H Front Tyre                                                                             |      |                          | mm         |
|                                                                                                                                        | R/H Rear Tyre                                                                              |      |                          | mm         |
|                                                                                                                                        | L/H Rear Tyre                                                                              |      |                          | mm         |
| 4. Description of Damages                                                                                                              |                                                                                            |      |                          |            |
|                                                                                                                                        |                                                                                            |      |                          |            |
| 5. General Information                                                                                                                 |                                                                                            |      |                          |            |
| Accident Date                                                                                                                          | 09/02/2022                                                                                 |      | Inspection Date          | 11/02/2022 |
| Survey held at                                                                                                                         | KARZ WORK SOLUTIONS<br>53 UBI AVE 1 #02-24<br>PAYA UBI INDUSTRIAL PARK<br>SINGAPORE 408934 |      |                          |            |
| 5a. Remarks                                                                                                                            |                                                                                            |      |                          |            |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                            |      |                          |            |