

ASS. REC. BY: Steve

REF:

CS/SMR22001343/EV43

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SHB 5717C

Policy No. _____

Claims No. TAX/02/22/2012

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLQ 4330P Yr Regn: 11/7/17Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1797Colour: White A/C: ☒ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 355716 T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ NAEng/No: JDDKB3AV103561868

C/No: _____

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: ☒ NII / ☐ S/Rim / ☐ STD A/Rim orTyre Size: F: 195/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 4 mmL/Bal. 4 mmD.O.A. 7/2/22Survey held at BorneoDes. of Damages: ☒ Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	MV- 67K
	PV- 32,290
	NV- 34,710
21/3/22	Steve informed repair cost \$33,000 (red 57,088.30, 63%)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 22/3/22-typistReport Format: TPLump Sum / I.B.I: (\$ 33,000)Days Of Repair: 18Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$1

Photos

Others

TOTAL



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no : 6831 1168



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM <i>liability check</i>			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd			
			Document No.		6 Battery Road			
			0		#38-04			
			Document Date		Singapore 049909			
			10/02/2022		Work: 65703925			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHXEBW Q3	11/07/2017	SLQ4330P	0	13277	SLQ4330P	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKB3FU103561868		2ZRS057391	60	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:						30.00
2	S	BP-SUBLET TO SUPPLY AND INSTALL FRONT NO.PLATE WITH CASING.						80.00
3	Z	BP-SLANT SUPPLY SEALANT (NETT)						200.00
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME						180.00
5	B	BP-MECH2 TO CONDUCT WHEEL ALIGNMENT CHECK.						180.00
6	B	BP-MECH2 R/I AIRCON CONDENSER/RADIATOR TO FACILITATE REPAIRS.						360.00
7	B	BP-MECH2 R/I FRONT UNDERCARRIAGE AND SUSPENSION TO FACILITATE REPAIRS.						1440.00
8	B	BP-MECH2 R/I ENGINE ASSY AND TRANSMISSION TO FACILITATE REPAIRS.						1710.00
9	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO FOCUS HEADLAMP.						180.00
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd								
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
							Amount Due	

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No.				
			0				
			Document Date				
			10/02/2022				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	11/07/2017	SLQ4330P	0	13277	SLQ4330P

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKB3FU103561868	2ZRS057391	60	Raymond Seah L M	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-LAB2 TO REPLACE FRONT ACCIDENT DAMAGE PARTS. <i>720 x 6</i> STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREA.				<i>4320</i> 4928.00
11	B	BP-RES2 TO SPRAY PAINT ON FRONT ACCIDENT AFFECTED AREAS. <i>590 x 5</i>				<i>2950</i> 4720.00
12	Z	BP-SLANT SUPPLY SEALANT (NETT)				200.00
13	B	BP-LAB2 R/I REAR REVERSE SENSOR TO FACILIATE REPAIRS AND TEST FUNCTION.				180.00
14	B	BP-WS R/I REAR WINDSCREEN TO FACILIATE REPAIRS.				X 462.00
15	B	BP-LAB2 R/I REAR CARPET, TRIMMING AND OTHER ATTACHMENT TO FACILIATE REPAIRS.				? 360.00
16	B	BP-LAB2 TO REPLACE REAR ACCIDENT DAMAGE PARTS. <i>590 x 3</i> STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.				<i>1180</i> 5040.00
17	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.				<i>1770</i> 3540.00
18	1	U81145-47691 UNIT, HEADLAMP <i>- BR</i>	1.00	2794.80		2794.80
19	2	U81185-47691 UNIT, HEADLAMP <i>- BR</i>	1.00	2794.80		2794.80
20	3	U81016-47690 COMPUTER SUB-ASSY, <i>- ?</i>	1.00	1015.70		1015.70
21	4	U81056-47690 COMPUTER SUB-ASSY, <i>- ?</i>	1.00	1015.70		1015.70
22	5	U81193-47120 RETAINER, HEADLAMP <i>- BR</i>	1.00	25.50		25.50

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	Less Amount Due
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128452, Tel no.: 6631 1189

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925			
			Document No. 0					
			Document Date 10/02/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHXEBW Q3	11/07/2017	SLQ4330P	0	13277	SLQ4330P	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKB3FU103561868		2ZRS057391	60	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
23	6	U81193-47140	RETAINER, HEADLAMP	1.00	14.10		14.10	
24	7	U81194-47120	RETAINER, HEADLAMP	1.00	25.50		25.50	
25	8	U81194-47130	RETAINER, HEADLAMP	1.00	14.10		14.10	
26	9	U81210-47020	LAMP ASSY, FOG, RH	1.00	1009.10		1009.10	
27	0	U81220-47020	LAMP ASSY, FOG, LH	1.00	1009.10		1009.10	
28	1	U82124-02120	WIRE, ENGINE, NO.4	1.00	65.00		65.00	
29	2	U28800-37130	BATTERY	1.00	1584.90		1584.90	
30	3	U82671-47040	BLOCK, JUNCTION	1.00	20.00		20.00	
31	4	U82621-47020	COVER, FUSIBLE LINK	1.00	35.90		35.90	
32	5	UG9214-47070	BRACKET, INVERTER,	1.00	261.20		261.20	
33	6	UG9215-47050	BRACKET, INVERTER,	1.00	221.40		221.40	
34	7	UG921E-47010	PROTECTOR, INVERTER	1.00	33.40		33.40	
35	8	UG9200-49116	INVERTER ASSY,	1.00	5116.40		5116.40	
36	9	U85315-47160	JAR, WASHER, A	1.00	232.20		232.20	
37	0	U85319-47170	PIPE, WASHER, A	1.00	71.10		71.10	
38	1	U86510-47060	HORN ASSY, HIGH	1.00	143.00		143.00	
39	2	U86520-47040	HORN ASSY, LOW	1.00	143.00		143.00	
40	3	U88460-10320	CONDENSER ASSY	1.00	1891.80		1891.80	
41	4	U19000-37B00	ENGINE ASSY, PARTIAL	1.00	0.00			
42	5	U30900-47090	TRANSAXLE ASSY,	1.00	12528.50		12528.50	
For & on behalf of			Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd			Please acknowledge receipt of vehicle	Parts		Less		
				Labour				
				Sublet				
				Lubrication/Fluid				
				Others		Amount Due		

Customer Copy

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925			
			Document No.					
			0					
			Document Date					
			10/02/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHXEBW Q3	11/07/2017	SLQ4330P	0	13277	SLQ4330P	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKB3FU103561868		2ZRS057391	60	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
43	6	U16562-37010	SEAL, RADIATOR TO	1.00	31.50		31.50	
44	7	U16593-37040	GUIDE, RADIATOR AIR,	1.00	69.30		69.30	
45	8	U16595-37050	GUIDE, RADIATOR AIR,	1.00	74.00		74.00	
46	9	U16563-37010	SEAL, RADIATOR TO	1.00	31.50		31.50	
47	0	U16400-37311	RADIATOR ASSY	1.00	2350.70		2350.70	
48	1	U16361-37070	FAN	1.00	298.20		298.20	
49	2	U16361-37060	FAN	1.00	232.20		232.20	
50	3	U16711-37160	SHROUD, FAN	1.00	280.90		280.90	
51	4	U16363-36160	MOTOR, COOLING FAN	1.00	568.10		568.10	
52	5	U16363-37060	MOTOR, COOLING FAN	1.00	694.40		694.40	
53	6	U164A2-37012	TANK, RESERVE SEALED	1.00	160.50		160.50	
54	7	U17120-37110	MANIFOLD ASSY,	1.00	1088.30		1088.30	
55	8	U17753-37010	INLET, AIR CLEANER,	1.00	44.60		44.60	
56	9	U17752-37121	INLET, AIR CLEANER,	1.00	119.80		119.80	
57	0	U17751-37110	INLET, AIR CLEANER,	1.00	164.80		164.80	
58	1	U17771-37020	BRACKET, AIR CLEANER	1.00	34.10		34.10	
59	2	U17700-37330	CLEANER ASSY, AIR	1.00	1218.90		1218.90	
60	3	U53112-47240	GRILLE, RADIATOR,	1.00	180.30		180.30	
61	4	U52114-47190	BRACKET, FR BUMPER	1.00	109.80		109.80	
62	5	U52119-47962	COVER, FR BUMPER	1.00	547.10		547.10	

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	
		Lubrication/Fluid	Amount Due
		Others	

Customer Copy

Inchcape
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd			
			Document No. 0		6 Battery Road #38-04 Singapore 049909			
			Document Date 10/02/2022		Work: 65703925			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHXEBW Q3	11/07/2017	SLQ4330P	0	13277	SLQ4330P	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKB3FU103561868		2ZRS057391	60	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
63	6	U52127-47907	COVER, FR BUMPER	CR4	1.00	31.10		31.10
64	7	U52128-47906	COVER, FR BUMPER	CR4	1.00	31.10		31.10
65	8	U53395-47040	SEAL, HOOD TO FR END	CR4	1.00	54.70		54.70
66	9	U52161-16010	PIECE, RR BUMPER	MC	10.00	4.80		48.00
67	0	U52115-47050	SUPPORT, FR BUMPER	BR	1.00	84.70		84.70
68	1	U52116-47050	SUPPORT, FR BUMPER	BR	1.00	84.70		84.70
69	2	U53101-47081	GRILLE SUB-ASSY,	BR	1.00	367.20		367.20
70	3	U75310-47060	EMBLEM ASSY,	CR4	1.00	96.60		96.60
71	4	U53301-47110	HOOD SUB-ASSY	CR4	1.00	1043.40		1043.40
72	5	U53341-47041	INSULATOR, HOOD	CR4	1.00	435.80		435.80
73	6	T90467-09050	CLIP	MC	10.00	3.00		30.00
74	7	U53801-47080	FENDER SUB-ASSY, FR	CR4 (RH)	1.00	1037.80		1037.80
75	8	U53802-47100	FENDER SUB-ASSY, FR	CR4 (LH)	1.00	1037.80		1037.80
76	9	U53875-47070	LINER, FR FENDER, RH	?	1.00	218.90		218.90
77	0	U53876-47110	LINER, FR FENDER, LH	?	1.00	214.50		214.50
78	1	U75374-47140	EMBLEM, SIDE PANEL	MC	1.00	58.00		58.00
79	2	U75374-47150	EMBLEM, SIDE PANEL	MC	1.00	58.00		58.00
80	3	U53510-47140	LOCK ASSY, HOOD	BT	1.00	143.00		143.00
81	4	U53410-47130	HINGE ASSY, HOOD, RH	BT	1.00	62.40		62.40
82	5	U53420-47130	HINGE ASSY, HOOD, LH	BT	1.00	62.40		62.40
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd								
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
							Amount Due	

Customer Copy

Inchcape
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd			
			Document No. 0		6 Battery Road #38-04 Singapore 049909			
			Document Date 10/02/2022		Work: 65703925			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHXEBW Q3	11/07/2017	SLQ4330P	0	13277	SLQ4330P	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKB3FU103561868		2ZRS057391	60	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
83	6	U53289-47072 COVER, RADIATOR			1.00	249.60		249.60
84	7	U16592-37020 GUIDE, RADIATOR AIR			1.00	119.80		119.80
85	8	U53205-47900 SUPPORT S/A,			1.00	400.10		400.10
86	9	U53213-47050 SUPPORT, RADIATOR,			1.00	83.60		83.60
87	0	U53214-47050 SUPPORT, RADIATOR,			1.00	83.60		83.60
88	1	U53028-47010 SUPPORT SUB-ASSY,			1.00	434.50		434.50
89	2	U53202-47901 SUPPORT S/A,			1.00	260.10		260.10
90	3	U53203-47901 SUPPORT S/A,			1.00	260.10		260.10
91	4	U53217-47030 BRACE, HOOD LOCK			1.00	82.80		82.80
92	5	SPC507-47001 16 BACK SENSOR WHITE PEARL SILVER			1.00	169.60		169.60
93	6	U89997-30100 ANTENNA, ELECTRICAL			1.00	76.30		76.30
94	7	U81551-47283 LENS & BODY, RR			1.00	479.30		479.30
95	8	U81561-47153 LENS & BODY, RR			1.00	469.90		469.90
96	9	U81497-47020 COVER, RR			1.00	68.50		68.50
97	0	U81498-47020 COVER, RR			1.00	68.50		68.50
98	1	U81581-47011 LENS & BODY, RR			1.00	532.00		532.00
99	2	U81591-47011 LENS & BODY, RR			1.00	532.00		532.00
100	3	U52159-47913 COVER, RR BUMPER			1.00	469.50		469.50
101	4	U52453-47010 GUARD, RR BUMPER,			1.00	611.30		611.30
102	5	U52169-47020 COVER, RR BUMPER,			1.00	16.30		16.30
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd								
		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
						Amount Due		

Customer Copy

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd		
			Document No. 0		6 Battery Road #38-04 Singapore 049909		
			Document Date 10/02/2022		Work: 65703925		
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	11/07/2017	SLQ4330P	0	13277	SLQ4330P
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU103561868		2ZRS057391	60	Raymond Seah L M	0.00		0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
103	6	U52161-16010 PIECE, RR BUMPER / <i>acc</i>	10.00	4.80		48.00	
104	7	U52565-47900 FILLER, RR BUMPER <i>- mis</i>	1.00	131.10		131.10	
105	8	U52566-47900 FILLER, RR BUMPER <i>- mis</i>	1.00	131.10		131.10	
106	9	U52575-47040 RETAINER, RR BUMPER <i>- BR</i>	1.00	124.90		124.90	
107	0	U52576-47040 RETAINER, RR BUMPER <i>- BR</i>	1.00	123.60		123.60	
108	1	U52023-47030 REINFORCEMENT <i>- ON</i>	1.00	353.10		353.10	
109	2	U58311-47130 PAN, RR FLOOR <i>x R</i>	1.00	618.90		618.90	
110	3	U58307-47090 PANEL SUB-ASSY, BODY <i>x R</i>	1.00	689.70		689.70	
111	4	U64716-47130 C0 COVER, DECK TRIM, RR <i>x</i>	1.00	134.30		134.30	
112	5	U58415-47110 C2 BOARD, RR FLOOR, <i>x</i>	1.00	550.60		550.60	
113	6	U68105-47291 GLASS SUB-ASSY, BACK <i>x</i>	1.00	1758.70		1758.70	
114	7	U56117-50140 DAM, WINDOW GLASS <i>x</i>	1.00	30.60		30.60	
115	8	T21000-20 SIKI 182010 SIKI TACK GO! (BLA <i>x</i>	2.00	108.00		216.00	
116	9	T21000-22 SIKI 207. G+P ADHESIVE PRIMER <i>x</i>	1.00	200.00		200.00	
117	0	U67005-47460 PANEL SUB-ASSY, BACK <i>x R</i>	1.00	1177.30		1177.30	
118	1	U67881-47051 WEATHERSTRIP, BACK <i>x</i>	1.00	394.70		394.70	
119	2	U69350-47050 LOCK ASSY, BACK DOOR <i>x</i>	1.00	495.40		495.40	
120	3	U69321-47010 COVER, BACK DOOR <i>x</i>	1.00	32.10		32.10	
121	4	U69430-52050 STRIKER ASSY, BACK <i>x</i>	1.00	27.40		27.40	
122	5	U76801-47110 A1 GARNISH SUB-ASSY, <i>x</i>	1.00	984.40		984.40	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy

Inchcape
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no : 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details				
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd				
			Document No. 0		6 Battery Road #38-04 Singapore 049909				
			Document Date 10/02/2022		Work: 65703925				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2017	ZVW50R	AHXEBW Q3	11/07/2017	SLQ4330P	0	13277	SLQ4330P		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTDKB3FU103561868		2ZRS057391	60	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00		
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
123	6	U75403-48010	EMBLEM SUB-ASSY, X / NK			1.00	76.00		76.00
124	7	U75441-47130	PLATE, LUGGAGE COMPT / NK			1.00	58.00		58.00
125	8	U75442-47130	PLATE, LUGGAGE COMPT / NK			1.00	58.00		58.00
126	9	U64801-47031	GLASS SUB-ASSY, BACK X			1.00	805.80		805.80
<p>Stew (LKK) 14/2/22, 10.00am</p> <p>ML PL PIP LJ PL LJ 14 JJS</p>									
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 									
For & on behalf of			Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd			Signature:		Parts 60,252.40		84,030.40		
Date:			Please acknowledge receipt of vehicle		Labour 23,710.00		GST 7.00% 5,882.13		
					Sublet 68.00		Less 0.00		
					Lubrication/Fluid 0.00				
					Others 0.00		Amount Due 89,912.53		

Customer Copy

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	08/02/2022 19:17 (SGT)
Date of Accident	07/02/2022 07:10 (SGT)
Exact Location of Accident	KPE, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ4330P
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	GRAB RENTALS PTE LTD
Company Reg No	2XXXXX200G
Email Address	gr.sg.accident@grab.com
Mobile Phone No	(Phone) +65-98388203
Alternative Phone No	(Office) +65-66550005

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1798

INSURANCE COMPANY

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	G 400001194 MCX
Cover Note Number	-

DRIVER

Name of Driver	LIM WAI CHOENG
NRIC No	SXXXX387H

Date Of Birth
Occupation
Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address

Address complement
Postcode

Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

13/04/1970
Outdoor
03/08/1990
31 YEARS AND 6 MONTHS
Male
(Phone) +65-98388203
-
gr.sg.accident@grab.com
27 PASIR RIS GROVE #15-50
-

518073
No
Hirer
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Chain Collision
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other vehicle or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No
5
Yes
No
Yes
2
No

PASSENGER 1

Name
Gender

UNKNOWNM
Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Police Station Name
Police Station Phone No
Alt. Police Station Phone No
Police Station Address
Was notice of intended Prosecution given?
If yes, against whom?

Yes
Traffic Police
(Phone) +65-65470000
(Fax) +65-65474900
10 Ubi Avenue 3 Singapore 408865
No
-

CIRCUMSTANCES OF ACCIDENT

ON 07/02/2022 AT AROUND 7AM, I WAS DRIVING MY CAR (SLQ4330P), TRAVELLING ALONG SENGKANG TOWARDS KPE HEADING TOWARDS CLEMENTI CAMP. I WAS TRAVELLING ON THE EXTREME RIGHT LANE AND I NOTICED THAT A CAR (SKG8868T) IN FRONT OF MY CAR HAD CAME TO A STOP, HENCE I ALSO TRIED TO STOP MY CAR. HOWEVER, THE CAR IN FRONT HAD STOPPED ABRUPTLY HENCE I COULD NOT STOP IN TIME AND HAD HIT INTO IT. AT THE VERY SAME TIME, I EXPERIENCED A VERY STRONG IMPACT COMING FROM BEHIND AND REALISED THAT A TAXI (SHB5717C) HAD COLLIDED INTO THE BACK OF MY CAR, THUS PUSHING MY CAR TO SURGE FORWARD AND HIT INTO THE CAR IN FRONT OF MINE. AFTER THE ACCIDENT, I HAD PAIN AND DISCOMFORT IN MY BACK, NECK AND SHOULDERS AND ALSO EXPERIENCED NUMBNESS IN MY HANDS SO I WENT TO SEE A DOCTOR AT CARE MEDICAL CLINIC ON THE SAME DAY AND WAS GIVEN 5 DAYS OF MC.

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?

Yes
No

Was there any audio recorded?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB5717G
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	3

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKG8868T
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SGX2118Y
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	SND7634M
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

2

INJURED PERSONS DETAILS

INJURED 1

Name of injured person

Gender

Phone No

Address

Address Complement

Post Code

Approximate Age Years Old

Injuries Sustained

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

LIM WAI CHOENG

Male

(Phone) +65-98388203

PAIN ON BACK, NECK, SHOULDERS, NUMBNESS IN HANDS
AND 5 DAYS MC.

SLQ4330P

Yes

No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

- ☒ A SLQ4330P (4)
- ☒ B SHB5717C (5)
- ☒ C SKG8868T (3)
- ☒ D SGX2118Y(1)
- ☒ E SND7634M (2)

SENGKANG EXIT
TO KPE



Describe Circumstances of the Accident

REFER TO POLICE REPORT.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel



**SINGAPORE
POLICE FORCE**



T/20220207/7041

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20220207/7041

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/02/2022 16:52		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: LIM WAI CHOENG			Address: 27 PASIR RIS GROVE #15-50 SINGAPORE 518073		
ID Type / ID No.: NRIC NO / S7012387H			Contact No.: Home/Office:		Mobile: 98388203
Nationality: SINGAPORE CITIZEN			Email: WAICHOENG@FONTCRAFT.COM.SG		
Sex: Male	Age: 51	Date of Birth: 13/04/1970	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Private Hirer			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 07/02/2022 07:00	Type of Location: Straight Road
Location: KALLANG PAYA LEBAR EXPRESSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Chain Collision			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of
SHB5717C	Car				Seriously Damaged	0
SKG8868T	Car					0
SLQ4330P	Car				Seriously Damaged	1



**SINGAPORE
POLICE FORCE**



T/20220207/7041

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20220207/7041

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LIM WAI CHOENG	ID No.	S7012387H
Related Vehicle	SLQ4330P (Car)	Contact No.	98388203
Hospital/Clinic	CARE MEDICAL CLINIC	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	07/02/2022	Date	NIL
No. of Days granted Medical Leave	05	Degree of	Serious
Passenger			
Name	PATRICK	ID No.	NIL
Related Vehicle	NIL	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL

Brief Details.

On 07/02/2022 at around 7am, I was driving my car (SLQ4330P), travelling along Sengkang towards KPE heading towards Clementi Camp. I was travelling on the extreme right lane and I noticed that a car (SKG8868T) in front of my car had came to a stop, hence I also tried to stop my car. However, the car in front had stopped abruptly hence I could not stop in time and had hit into it. At the very same time, I experienced a very strong impact coming from behind and realised that a taxi (SHB5717C) had collided into the back of my car, thus pushing my car to surge forward and hit into the car in front of mine.

After the accident, I had pain and discomfort in my back, neck and shoulders and also experienced numbness in my hands so I went to see a doctor at Care Medical Clinic on the same day and was given 5 days of MC.





**SINGAPORE
POLICE FORCE**



T/20220207/7041

3 of 3

Report No. T/20220207/7041

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
SYED MUHAMMAD ISA BIN OMAR
ALHABSHEE
Contact No.: 65476214

NP 128

Signature Of Informant:
The identity of the person making this report has
been authenticated by Singpass. No signature is
required.

Date/Time:
07/02/2022 16:52

Classification Of Case:





