	e Services Test Jacobs	
Date In: 11/02/2002 14:52	Job description Date & Tune Completed Done	by
Ref No NA/LDC 22001349/m4	SAS e-filing	
Ref No NA/LPC 22001349/m4 Veh No GBG 1031T	Fmail (within 8hrs: AIC 2hrs)	
DOA 10/02/2002 10:30	i-Motor Claim Form	
	i-Motor W/O (Within: OD 2hrs, TP 4hrs)	n 18 () .
OD (TP) Reporting Only	i-Photo Uploaded	1.00
TP Insurer:	Assessment/Survey Report	
	Ass't Report by Fax / Hand to Owner/Wksp	DE 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Preferred Wksp / INC Assign Wksp / QW: (Tel: Fax:	
TP Particulars: Veh No: GE	3K 2633D INC()/Non-INC()	
Owner / Driver: (Tel:	
Policy No: () Per	riod: () Cover Type: ()	och telvalobilos
Confirmed by : (Date: Time:)	35 20 3 2 1 7 1
Insured/Driver Liability: (%) [Note-Est. Status (WO): N: 0-20%; P: 21-79%. F: \$0-100%]	
Year of Registration: () V	Warranty: YES () / NO ()	
Excess: (\$) Loading: \$1,00	00 () / \$2,000 ()	
General Remarks:-		
() Walk-In Customer: Customer's infor	rmation strictly Confidential & Strictly NO rafer of repairer.	
() Total Loss Case : to e-mail Insure		P. LOVA LINES
According to the second		
Drive-In ()/ Towed-In (); Invoice	E: YES () / NO (); Towing Co. (
Remarks:- (INC horline: 6788 6616)	Date&Time Completed Done	by
1) Apply for Transport Allowance ()/C		
1) Apply for Hansport Allowance ()/ C	Courtesy Car ()	
	Courtesy Car ()	
2) QC Check / Post Repair Inspection	()	
QC Check / Post Repair Inspection Upload Resurvey Photo [Repair Cost > \$3	()	
2) QC Check / Post Repair Inspection	()	
QC Check / Post Repair Inspection Upload Resurvey Photo [Repair Cost > \$3	()	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury:	()	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury:	()	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury:	()	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury:	()	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury:	()	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury:	() 3000] ()	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions	Invoice Preparation Checklist Antt (3) 1st Bill	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions	Invoice Preparation Checklist Invoice Preparation Checklist Ist Bill 1) AR: Accident Reporting (\$30);	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions Claimant's Particulars:-	Invoice Preparation Checklist Invoice Preparation Checklist I) AR: Accident Reporting (\$30); I) DA: Damage Assessment (\$100); INC (\$80) 3) TF: Towing Fee \$40/\$45	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions Claimant's Particulars:-	Invoice Preparation Checklist Invoice Preparation Checklist I) AR: Accident Reporting (\$30); I) DA: Damage Assessment (\$100); INC (\$80) 3) TF: Towing Fee \$40/\$45 4) FT: Follow-Through Survey \$120	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions Claimant's Particulars:- Driver/Owner:	Invoice Preparation Checklist Invoice Preparation Checklist 1) AR: Accident Reporting (\$30); 2) DA: Darnage Assessment (\$100); INC (\$80) 3) TF: Towing Fee \$40/\$45 4) FT: Follow-Through Survey \$120 5) FT: Follow-Through Survey (Resurvey) \$30 For claiming against INC Only (wef 10 Jan 2005)	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions Claimant's Particulars:- Contact No:	Invoice Preparation Checklist Invoice Preparation Checklist Ist Bill 1) AR: Accident Reporting (\$30); 2) DA: Damage Assessment (\$100); INC (\$80) 3) TF: Towing Fee \$40/\$45 4) FT: Follow-Through Survey \$120 5) irT: Follow-Through Survey (Resurvey) \$30	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions Claimant's Particulars:- Contact No:	Invoice Preparation Checklist Invoice Preparation Checklist 1) AR: Accident Reporting (\$30); 2) DA: Damage Assessment (\$100); INC (\$80) 3) TF: Towing Fee \$40/\$45 4) FT: Follow-Through Survey \$120 5) IT: Follow-Through Survey (Resurvey) \$30 For claiming against INC Only (wef 10 Jan 2005) 6) TR: Re-inspection \$75 7) N1: Idne DA + SMRT Survey \$160 8) NTUC Additional Services	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions Claimant's Particulars:- Oriver/Owner: Contact No: Damaged Portion:	Invoice Preparation Checklist Invoice Preparation Checklist I) AR: Accident Reporting (\$30); Ist Bill I) AR: Accident Reporting (\$30); I) DA: Damage Assessment (\$100); INC (\$80) 3) TF: Towing Fee \$40/\$45 4) FT: Follow-Through Survey (\$120 5) FT: Follow-Through Survey (Resurvey) \$30 For claiming against INC Only (wef 10 Jan 2005) 6) TR: Re-inspection \$75 7) NI: Idae DA + SMRT Survey \$160 8) NTUC Additional Services:- OD*	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions Claimant's Particulars:- Oriver/Owner: Contact No: Damaged Portion:	Invoice Preparation Checklist Invoice Preparation Checklist 1) AR: Accident Reporting (\$30): 2) DA: Damage Assessment (\$100); INC (\$80) 3) TF: Towing Fee \$40/\$45 4) FT: Follow-Through Survey \$120 5) FT: Follow-Through Survey (Resurvey) \$30 For claiming against INC Only (wef 10 Jan 2005) 6) TR: Re-inspection \$77 7) N1: idae DA + SMRT Survey \$160 8) NTUC Additional Services: OD!* *N5: Courtesy Car / Tpt Allowance \$5 *N6: Repair Co-ordination \$10	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions Claimant's Particulars:- Driver/Owner: Contact No: Damaged Portion: QC Checked by (Engr-In-Charge):	Invoice Preparation Checklist	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions Claimant's Particulars:- Oriver/Owner: Contact No: Damaged Portion: QC Checked by (Engr-In-Charge): Auditors' Comments:-	Invoice Preparation Checklist	Anst (3 Add B
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions	Invoice Preparation Checklist	



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process:
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving
- and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission

Date of Accident

Exact Location of Accident

Additional Location Information

Country/State of Loss

11/02/2022 14:52 (SGT) 10/02/2022 10:30 (SGT)

Singapore

BLK 212 / 211 HOUGANG ST 21 CARPARK COMPOUND

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

GBG1031T

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No

Email Address

Mobile Phone No

Alternative Phone No

HI-TEC IMAGE CONCEPT SERVICES

5XXXXX314J

abc8627e@gmail.com

(Phone) +65-90290166

+65-90290166

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle?

Vehicle Category

Transmission

CC

Private use

Nissan

Nv350

No - Claiming third party

Commercial vehicle

Manual

2488

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage

Fleet Policy

Policy Number

Cover Note Number

Lonpac Insurance Bhd

Comprehensive

No

Z21VC05007362

DRIVER

Name of Driver

NRIC No

CHUA HUA HONG SXXXX991J

Page 1 of 16

Date Of Birth 24/12/1957 Occupation Outdoor Date Of Driving Pass 28/11/1983 Driving experience 38 YEARS AND 3 MONTHS Gender Male Mobile Number (Phone) +65-90290166 Alt. Phone Number Email Address abc8627e@gmail.com Address BLK 709 PASIR RIS DRIVE 10 Address complement #07-173 Postcode 510709 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured OWNER Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Hit and run / Vandalism / Damaged whilst parked Weather Conditions Road Surface Wet OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 0 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT PLS REFER TO THE ATTACHED STATEMENT ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No Was there any audio recorded? No **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number GBK2633D Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Commercial vehicle Name of Driver Contact Number Address Address complement

Page 2 of 16

Accident report SN09222B0007

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

CONCEAT

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Vehicle A'. GBG 1031

John B. GBK 2633 D

Sketch Plan

auparli

Describe Circumstances of the Accident		
		(a)
	1	3.0
	1	
	+	,
	+	
	1	
\ /	1/ \	
h//	7	
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	1	
M		
	-	
+		
	-	
	-	
A ~		
A 4		
	+	
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
7		
	+	
		
	-	
	1	
Destaudion		
Declaration		
I/We declare the foregoing particulars are true in avery respect		
I/We declare the foregoing particulars are true in every respect.		
CONCEPT		
	4	11/02/22
	Pa	11/02/22

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

ON THE STATED DATE AND TIME. I, VEHICLE A (GBG1031T) WAS STATIONARY ON BLOCK 212/211 HOUGANG STREET 21 CARPARK. SUDDENLY I SAW VEHICLE B (GBK2633D) REVERSE AND COLLIDED ONTO MY STATIONARY VEHICLE REAR LEFT PORTION.

I WISH TO STATE THAT THE VEHICLE B (GBK2633D) DRIVER CLAIM THAT BECAUSE HIS MIRROR IS BLUR SO HE DIDN'T NOTICE MY VEHICLE.

VEHICLE A: GBG1031T

VEHICLE B: GBK2633D



SINGAPORE ACCIDENT STATEMENT

Accident Date: 10 1 2012 Time: 10:30 (hh:	mm) 24 hr format
Location BK 212 (21) Hougary & 21 Carparle compound	
The standing of the part compound	
Vehicle Number GBG10317 (M) (2488cc)	
Insured Name Hi - Tec Image Concept Services	
NRIC/FIN 5297 5314J Contact Number —	
Make Hissan Model NV350	
Are you claiming under your own insurance policy for repair to your vehicle	?
() Yes If No,Pls select: () Third Party () Reporting	
Insurance Company Longac	
Type of Policy () Comphensive () Third Party Fire & Theft	() TP Only
Policy Number Zlavco5007362	
Name of Driver Chua Hoa Hong ()Same as Insured
	John Cas Insufed
NIBIC (FIN 0.2) = =00 =	- 11
NRIC/FIN \$1300991J Contact Number 90)	0166
Date of Birth 24/12/1957	
Driving Pass Date 28 HOV 1983	
Occupation () Indoor () Outdoor	
Gender () Male () Female	
Email Address abc8627e@gnail.com ()NO EMAIL
Address of Driver BIK 709 Pasir Ris Dake 10 707-173	(5)+85+ 51070
Was driver an employee of the Insured's Company? () Yes (/) No	
If No, Relationship of the Driver with the Insured	
(Nowner () Spouse () Friend () Relative () Children	() Sibling
Does the Driver Own Any Other Vehicle? () Yes () No	
If Yes , Vehicle Registration Number of Driver's Own Vehicle	
Insurance Company of Driver's Own Vehicle	
Weather Conditions () Clear (/) Raining () Others	
Road Surface () Dry (\sqrt) Wet () Others	
Was any foreign vehicle involved in this accident? () Yes () N	lo
Was anybody injured in the accident? () Yes ()?	lo
If yes, injured detail	
Was there any video captured by Car Camera? () Yes () No	
	es attach police report
DETAILS OF 3 rd party Name Nric	Conner
Veh B GBK 1633D	
Veh C	
Veh D	
Veh E	
Veh F	
V CH 1	



LONPAC INSURANCE BHD (S98FC5635C)

(Incorporated in Malaysia)

Singapore Office: 300, Beach Road #17-04/07, The Concourse, Singapore 199555. Tet: (65) 6250 7368 Fax: (65) 6296 3767 Website; www.lonpac.com.sg GST Reg No.: F9-0005635-C

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP 189) REPUBLIC OF SINGAPORE.
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1960 (REPUBLIC OF SINGAPORE).
ROAD TRANSPORT ACT 1987 (MALAYSIA).
ROAD TRANSPORT (AMENDMENT) ACT 2019 (MALAYSIA).
THE MOTOR VEHICLES (THIRD PARTY RISKS) RULES 1959 (MALAYSIA).

Certificate No.: Z21VC05007362

Type of Cover : COMPREHENSIVE

1. Index Mark and Vehicle Registration Number

NISSAN NV350 - GBG1031T

2. Name of Policy Holder

HI-TEC IMAGE CONCEPT SERVICES

 Effective Date of the Commencement of Insurance for the purpose of the Act

31/05/2021

4. Date of Expiry of the Insurance

30/05/2022

5. Person To Drive

(A) THE POLICYHOLDER.

(B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS/THEIR PERMISSION.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use

USE IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS.

USE FOR THE CARRIAGE OF PASSENGERS (OTHER THAN FOR HIRE OR REWARD) IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS.

USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES.

THE POLICY DOES NOT COVER:-

USE FOR HIRE OR REWARD OR FOR RACING, PACEMAKING, RELIABILITY TRIALOR SPEED TESTING.

USE WHILST DRAWING A TRAILER EXCEPT THE TOWING OF ANY ONE DISABLED MECHANICALLY PROPELLED VEHICLE.

Excess

: S\$ 600.00 (SECTION 1)

S\$ 2,500,00 (SECTION 1) ADDITIONAL EXCESS FOR YOUNG AND/OR INEXPERIENCED DRIVERS \$\$ 100.00 WINDSCREEN EXCESS (EXCESS WILL BE DOUBLED ON SUBSEQUENT CLAIMS)

Condition

: ACCIDENT REPAIRS AT LONPAC'S AUTHORISED WORKSHOPS

* Limitations rendered inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore are not included under heading.

I/WE hereby certify that this covering Note is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia) and Motor Vehicles (Third-Party Risks and Compensation) Act (Cap 189) Republic of Singapore.

H.P. Owner: TAN CHONG CREDIT PTE LTD

CHIEF EXECUTIVE (Singapore Branch)

nele.

User ID: XLCHEN Date Issued: 19/04/2021