ASS. REC. BY: Steve | DEPT: CSS/ASM2:1007051/EAC

ASSIGNMENT

From: PRS | Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FX 361K

at Workshop m/s: PRIMERO RACING

at

Insured: SH 6608R

Policy No.

Claims No.: S1M03CI0

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S | O/S

Bal. or Market Value:

IDAC Accident Rport: | Consistent? : Yes or No

SIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: 3 days | Res.: Yes or No

Sum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: FX 361K | Yr Regn: 11/5/06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Texi / Prime Mover / Truck / Trailer or

Make: Honda CB400 | c.c 399

Colour: Yellow | A/C: Insured / Std / Nil / N

Sp.Reading: N/A | T/Radio: Insured / Std / Nil / N

Eng/No:

C/No: JH2NC39935M100379

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/60ZR17

R: 160/60ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Pirelli

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	mm	L/Bal.	mm
D.O.A.	24/6/21	D.O.I.	28/6/21

Survey held at: Primero Racing @10.30am

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collisio

Date / Time	Action / Instruction
	MV-SK $1500 - $2000 repair targe
	3 repair days
29/6/2021	Submit PRS.
15/02/22	Submit LS $3050, 3 days (Red $600, 16%)

Date/Time, File,Pass to? | ☐ : Prell. Report

15/02 TYPIST | ☐ : Final Report

Date/Time, File Return to?

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech. Inve (%) ☐ : Weekend (%)

Survey Fee:

Transportation: $ + RS $

Photos

Others

TOTAL

Prepared by: TP

Insp Sum Hdlr: 3050