



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:JANICE

Ref: CC4/ASM22001380/Rpa3q2
Date: 18/05/2022
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 7027L	Veh. Inspected	SNA 9755A
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	S2M03T5Q	Excess (\$)	0.00
Assign From		Assign Date	14/02/2022

2. Vehicle Particulars & Condition

Make & Model	KIA CERATO 1.6 A EX	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	KNAF3416MM5107138	Colour	BLACK
Odometer	19442 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	NEXEN	6 mm
L/H Front Tyre	205/55 R16	NEXEN	6 mm
R/H Rear Tyre	205/55 R16	NEXEN	6 mm
L/H Rear Tyre	205/55 R16	NEXEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/02/2022	Inspection Date	14/02/2022
Survey held at	39 WOODLANDS CLOSE MEGA #01-24		
Repairer	NINETEEN AUTOWERKS PTE. LTD.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**