

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

EQ Insurance Company Ltd (HQ)

Singapore

MVA: YY

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	13/02/2022
Vehicle Reg. No.:	SHC8780T	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS, 1.5 (A)	Vehicle Reg. Date:	30/05/2017
Vehicle Colour:	BLUE	Chassis No:	JTDKB3FU503557533
Engine No:	2ZRS044836		
Odometer:	622444 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	4,953.49
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	4,953.49
+ GST 7.00% (\$\$)	346.74
Nett Amount (\$\$)	5,300.23

This claim is handled by: LOKE YY 62148355

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 14 Feb 2022)**Parts:** 144 TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC8780T/14/02/2022 13:43**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER COVER	25.00	0.00	de *499.90 FL
2	1		*FRONT BUMPER CLIPS	25.00	0.00	we *22.00 FL
3	1		*FRONT BUMPER FOG LAMP	25.00	0.00	X *920.00 FL
4	1		*FRONT BUMPER SIDE BRACKET LH	25.00	0.00	X *82.30 FL
5	1		*FRT BUMPER SUPPORT LH	25.00	0.00	X *81.70 FL
6	1		*HEAD LAMP PANEL LH	25.00	0.00	X *240.10 FL
7	1		*HEADLAMP LH	25.00	0.00	X *2,735.28 FL
8	1		*FRT BUMPER REINFORCEMENT ABSORBER LH	25.00	0.00	X *115.70 FL
9	1		*FRT BUMPER REINFORCEMENT	25.00	0.00	X *696.40 FL
10	1		*FRT BUMPER LOWER REINFORCEMENT	25.00	0.00	X *364.20 FL
11	1		*FRT BUMPER SPONGE	25.00	0.00	X *78.80 FL
12	1		*RADIATOR GRILLE	25.00	0.00	X *438.00 FL
13	1		*FRT BUMPER CENTRE GRILLE	25.00	0.00	X *301.90 FL
14	1		*FRT BUMPER TOWING COVER LH	25.00	0.00	ent *28.38 FL
15	1		*RADIATOR SUPPORT LH	25.00	0.00	X *234.70 FL
16	1		*RADIATOR ASSY	25.00	0.00	X *1,841.80 FL
17	1		*CONDENSER ASSY	25.00	0.00	X *1,336.60 FL
18	1		*COOLANT	25.00	0.00	X *90.00 FL
19	1		*FRT NUMBER PLATE EXTENSION	0.00	0.00	de *99.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) 6,604.66

- List Item Discount on L Items (S\$) 1,651.17

Total Parts (S\$) 4,953.49

ComfortDelGro Engineering Pte Ltd/SHC8780T/14/02/2022 13:43. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

ComfortDelGro Engineering Pte Ltd/SHC8780T/14/02/2022 13:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

(SUPPLEMENTARY)

TP INSURER:
 CTPL

EQ Insurance Company Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	13/02/2022
Vehicle Reg. No.:	SHC8780T	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS, 1.5 (A)	Vehicle Reg. Date:	30/05/2017
Vehicle Colour:	BLUE	Chassis No:	JTDKB3FU503557533
Engine No:	2ZRS044836		
Odometer:	622444 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	0.00
Miscellaneous Items	0.00
Labour	1,990.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,990.00
+ GST 7.00% (S\$)	139.30
Nett Amount (S\$)	2,129.30
+ Previous Estimates (S\$)	9,998.96
Claim Total (S\$)	12,128.26

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 14 Feb 2022)**Parts:** 144 TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** **ComfortDelGro Engineering Pte Ltd/SHC8780T/14/02/2022 13:45****Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

There are no new parts selected.

ComfortDelGro Engineering Pte Ltd/SHC8780T/14/02/2022 13:45. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	350 1,050.00
2	SPRAY PAINTING CHARGE	New	250 800.00
3	CHECK ALL LIGHTING	New	X 80.00
4	TUFF KOTE	New	X 60.00
Gross Labour Cost (S\$)			1,990.00

ComfortDelGro Engineering Pte Ltd/SHC8780T/14/02/2022 13:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanphn 97495749
WP' 2/5 Resurvey after repair
- 2 days
15/2/22 @ 3:25 pm
Tanphn 2/14/2022

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Date:

Date/Time: 14.02.2022 11:20

Page : 1

Job: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4173511

JC NO.305504818

Customer

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)


Job Card No.

REGN NO: SHC8780T	MILEAGE
MAKE: TOYOTA	FUEL E.....1/2.....F
MODEL PRIUS HYBRID(G4)14	DATE/TIME IN 02.2022 08:45
YR OF MANU. 30.05.2017	TARGET DATE
CHASSIS CODE JTDKB3FU503557533	COMPLETION DATE/TIME

Accident Date: 13.02.2022
Accident Time: 3P 13.02.2022

JOB DESCRIPTION

NO LABOR CODE DESCRIPTION



Job Card & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Damage Slip

Exit Pass

Vehicle No.: **SHC8780T** YY

Vehicle No.: **SHC8780T**

Service Advisor

Signature/Date

Name of Service Advisor

Date

Job Card to be kept by Security Guard

To be kept by Security Guard