

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	NTUC INCOME IN	SURANCE CO-OPERATIVE LTD		Ref:	CS/INC22001427/Eqf3n2	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE		Date:	16/03/2022	
	ATTN: QUEK SWE	E KENG		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	YP 7769P	Veh. Inspected	l	SHA 9457G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1161695-001	Excess (\$)		0.00	
	Assign From	ANNIE KOH	Assign Date		15/02/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	KMHC851CVJU103631	Colour		YELLOW	
	Odometer	331570 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/55 R15	SAILUN		4 mm	
	L/H Front Tyre	195/55 R15	SAILUN		4 mm	
	R/H Rear Tyre	195/55 R15	SAILUN		4 mm	
	L/H Rear Tyre	195/55 R15	SAILUN		4 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.					
	DAMAGES SEE DETAILS.					
					1.0	
5.	General Information					
	Accident Date	12/02/2022	Inspect Date /	Time	15/02/2022 ( 01:00 PM )	
	Survey held at	31 CORPORATION ROAD				
	Repairer	DING AUTOMOTIVE PTE LTD				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	STIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				