

|   |   |          |   |   |   |   |        |   |   |             |
|---|---|----------|---|---|---|---|--------|---|---|-------------|
| ⏪ | < | 1 of 2 ? | > | ⏩ | ↺ | ↻ | 100% ▼ | 📄 | 🖨 | Find   Next |
|---|---|----------|---|---|---|---|--------|---|---|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                    |                          |            |  |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|--------------------------|------------|--|
| NTUC INCOME INSURANCE CO-OPERATIVE LTD                                                                                                 |                                                                    | Ref: CS/INC22001428/Evf3 |            |  |
| 73 BRAS BASAH ROAD                                                                                                                     |                                                                    | Date: 15/02/2022         |            |  |
| #05-01 NTUC TRADE UNION HOUSESINGAPORE                                                                                                 |                                                                    |                          |            |  |
| 189556                                                                                                                                 |                                                                    | Code: INC                |            |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM                                                                                             |                                                                    |                          |            |  |
| Insured Veh.                                                                                                                           | SMA 3003M                                                          | Veh. Inspected           | YQ 3529L   |  |
| Policy No.                                                                                                                             |                                                                    | Coverage (\$)            | 0.00       |  |
| Claim No.                                                                                                                              | MT/1161458-001                                                     | Excess (\$)              | 0.00       |  |
| Assign From                                                                                                                            | ANNIE KOH                                                          | Assign Date              | 15/02/2022 |  |
| 2. Vehicle Particulars & Condition                                                                                                     |                                                                    |                          |            |  |
| Make & Model                                                                                                                           | c.c                                                                |                          | 0          |  |
| Engine No.                                                                                                                             | HIDDEN                                                             | Year of Reg.             |            |  |
| Chassis No.                                                                                                                            | Colour                                                             |                          |            |  |
| Odometer                                                                                                                               | -                                                                  | Steering                 |            |  |
| Brakes                                                                                                                                 | Modification                                                       |                          |            |  |
| General                                                                                                                                |                                                                    |                          |            |  |
| 3. Conditions of Tyres                                                                                                                 |                                                                    |                          |            |  |
|                                                                                                                                        | Size                                                               | Make                     | Balance    |  |
| R/H Front Tyre                                                                                                                         |                                                                    |                          | mm         |  |
| L/H Front Tyre                                                                                                                         |                                                                    |                          | mm         |  |
| R/H Rear Tyre                                                                                                                          |                                                                    |                          | mm         |  |
| L/H Rear Tyre                                                                                                                          |                                                                    |                          | mm         |  |
| 4. Description of Damages                                                                                                              |                                                                    |                          |            |  |
|                                                                                                                                        |                                                                    |                          |            |  |
| 5. General Information                                                                                                                 |                                                                    |                          |            |  |
| Accident Date                                                                                                                          | 05/02/2022                                                         | Inspection Date          | 15/02/2022 |  |
| Survey held at                                                                                                                         | GOLDBELL ENGINEERING PTE LTD<br>10 TUAS AVE 18<br>SINGAPORE 638894 |                          |            |  |
| 5a. Remarks                                                                                                                            |                                                                    |                          |            |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                    |                          |            |  |