Dale.	Person Contacted:	Vehicle: IN/OUT		ody Structure affected due to collision.
Date / Time	Action / Instruction			
	\$137 9.99; 1 days .	,		
	red: 463.96;25%			
		-··		
aidTime, Fle Pass	From Report	· , , D	Pays Of Repair: 1	, .
) Dale/Time_File Return	: Final Report	R	esurvey No. of Trip:	Survey Fee:
		Add Fee:	: Site Insp (\$	Transportation:

event Formus :

Interview 1\$

Tech, Inve 13

WARIGING 12

Flinkis

Cillians

709 41.



ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Mainline + 65 6383 6280 Facsimile + 65 6280 9

Workshops
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717

Date/Time: 14.02.2022 14:41

Page : 1

am:	ARC Repair TP(CLSO)1	JOB CARD	Sales Order:	4173576	JC NO.305504859
OMER			REGN NO.: SHC24	41L	FUEL
3	COMFORT TRANSPORTATION PTE	LTD	MAKE: TOYOT		EF
)MER	202 CIN MIN(+ I)KIVE		MODEL	HYBRID(G4)14.	02.2022 10:40
	Singapore SINGAPORE 575717 65508755 (0)		YR OF MANU		TARGET DATE
(R) (P)				3FU603079753	COMPLETION DATE/TIME:

UNT CARD NO.


JOB DESCRIPTION

cident Date: 13.02.2022 TURE: 3P 13.02.2022

NO.

LABOR CODE

DESCRIPTION



(ED & PASSED OUT BY: SERVICE ADVISOR CUSTOMER'S SIGNATURE Indigement Slip Exit Pass	
SERVICE ADVISOR CUSTOMER'S SIGNATURE	
SERVICE ADVISOR CUSTOMER'S SIGNATURE	OUT DV
SERVICE ADVISOR	
odgement Slip Exit Pass	ERVICE ADVISOR CUSTOMER'S SIGNATURE
agement Stip	Fuit Pass
\mathbf{i}	
SHC2441I. LIMTS SHC2441L	Vétilicle:No.2
o.: SHC2441L LIMTS SHC2441L	441L LIMIS SHOZZZIL
Service Advisor Signature/Date Name of Service Advisor Date	Signature/Date: Name of Service Advisor: Date
urned to Service Reception upon collection To be kept by Security Guard	organism and the second

Page p of P

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive Singapore 508969 Tel: 6214 8300

LKK-Thoran

TP INSURER:

CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

CPP)

Singapore

PARTICULARS OF CLAIM

Claim Type:

THIRD PARTY

Ref. No:

2/02/2020

Policy No: Vehicle Reg. No.:

SHC2441L

Date of Loss:

13/02/2022

Party At Fault:

UNKNOWN

Driveable?

NO

Make/Model:

TOYOTA PRIUS, 1.8 HYBRID

Vehicle Reg. Date: 01/04/2019

Vehicle Colour:

CVT (A) BLUE

Gen Condition:

GOOD

Engine No:

2ZR2C05253

Chassis No:

JTDKB3FU603079753

Odometer:

0 KM

Paint Type:

List Item Discount:

25.00 %

Total Loss?

NO

Est. Duration of Repair 2

(day)

Present Location:

COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS		Amount
Parts		1,402.95
Miscellaneous Items		11.00
Labour		430.00
Paintwork Labour		0.00
Towing	The the first distance was an expense of the second	0.00
	Gross Total (S\$)	1,843.95
	+ GST 7.00% (S\$)	129.08
	Nett Amount (S\$)	1,973.03

This claim is handled by: LIM TIEN SIONG

Generaled using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 14 Feb 2022)

Parts:

144

TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merlmen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC2441L/14/02/2022 15:06

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*WING MIRROR RH	25.00	0.00	*1,728.70 FL
2	1		*WING MIRROR OUTER COVER RH	25.00	0.00	*141.90 FL / M/
F=Fr	anchise	part. L=ListIter	mDisc.			
			Sub Total (S\$)			1,870.60
			- List Item Discount on L Items (S\$)			467.65
			Total Parts (S\$)			1,402.95

ComfortDelGro Engineering Pte Ltd/SHC2441L/14/02/2022 15:06. Not valid without Reference section. Generated using Merimen e-Claims IEAS



Es	stim	ates on Miscellaneous Items		Amount
No	Qty	Particulars		
Mis	cella	neous Items		11.00
1	1	OD/TP Case (Insurer)		
			Sub Total (S\$)	11.00

Estimates on Labour	Lab.Type	Amount
Labour Items 1 PANEL BEATING 2 SPRAY PAINTING 3 CHECK WIRING	New New	200.00 100 200.00 100 30.00 70
	Gross Labour Cost (S\$)	430.00

ComfortDelGro Engineering Pte Ltd/SHC2441L/14/02/2022 15:06. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thuran
82235769
14/12/22 1730
10/ay wp
1/1/2 bfr paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: