

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/FC/22001454/UVF3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLH 29384

at Workshop m/s

KF N-51

of

Insured:

XD 87204

Policy No.

Claims No.

000000434MFRS

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

854k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

9 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

B 868L

Vehicle: IN / OUT

Date:

Person Contacted:

L 746 35962

Veh No:

SLH 29384

Yr Regn:

28/10/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

GA/

Make:

Toyota Corolla Altis c.c 1598

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

201962

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MRO53REH104559087

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

14/2/22

D.O.I.

15/2/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear. 2

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Rep 106.

17/2/22

vehicle tow out already submit

Range 8-8k.

by 8:58:50, tender 12/8-20, axle beam 3616.70

7/3/22

4/5 @ 9000 insured At Yong (red 7234.33, 44%)

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2) 18/2 7/3/22-typist

Days Of Repair:

9

Resurvey No. of Trip:

3

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format: TP

Lump Sum / T.B. (\$ 9000

Survey Fee:

6x15=90

90+170

Transportation:

50

S + RS SI

50+50+50

Photos

89

Others

TOTAL

549