



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22001484/Utf3n2	
			Date: 10/03/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YN 5289G	Veh. Inspected	GBH 2054R
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2200549/SYH	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	16/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	KIA K2500 (M)	c.c	2497
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	KNCSJX76LH7185684	Colour	BLUE
	Odometer	7182 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	KUMHO	6 mm
	L/H Front Tyre	195 R15	KUMHO	6 mm
	R/H Rear Tyre	5.00 R12	KUMHO	6 mm
	L/H Rear Tyre	5.00 R12	KUMHO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/02/2022	Inspection Date	16/02/2022
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	