

ASS. REC. BY:

Tajm

REF:

INC

ASSIGNMENT

Front

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Lm TS

Veh No:

SHC12915

Yr Regn:

2020, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Lania

C.C

1580

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

192715

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMHC851CVL4187414

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

2 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Wor forker

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

15/2/22

Survey held at

Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / L.B.I. (\$

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE: **15-Feb-22**

MODEL: **Hyundai Ioniq**

VEHICLE NO.: **SHC1291J**

INSURANCE: **NTUC CP/PJ**

MVA: **LIM T S**

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$430.90 <i>Rp</i>
	Front Bumper Clips	10	\$2.20	\$22.00 <i>rec</i>
	Front Fender RH	1		\$588.80 <i>bt</i>
	Front Fender Shield RH	1		\$164.70 <i>pr</i>
	Front Fender Blue-Drive RH	1		\$26.60 <i>ur</i>
	Front Wheel Cap RH	1		\$346.40 <i>unt</i>
	DayLight RH	1		\$642.50 <i>X</i>
	DayLight Grille RH	1		\$93.45 <i>X</i>
	SUB TOTAL			\$2,315.35
	LESS 20%			\$463.07
	TOTAL SPARE PARTS			\$1,852.28
	Labour Charge			
	Panel Beating			\$800.00 <i>525</i>
	Spray Painting			\$600.00 <i>500</i>
	Check Wirings			\$40.00 <i>X</i>
	Tuff Kote			\$40.00 <i>30</i>
	TOTAL LABOUR			\$1,480.00
	ESTIMATE TOTAL			\$3,332.28

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taylor 97495749
WP 15/2/22 03pm
P/P Resey before paint
Taylor @ Hyundai
2-3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Date/Time: 15.02.2022 13:35

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 4174595

JC NO 305504931

DMER

REGN NO.:

SHC1291J

MILEAGE

MAKE:

HYUNDAI

FUEL

Engine 1/2 F

MODEL

IONIQ(G3)

DATE/TIME IN 15.02.2022 11:10

YR OF MANU.

18.03.2020

TARGET DATE

CHASSIS CODE

KMHC851CVLU187414

COMPLETION DATE/TIME

S COMFORT TRANSPORTATION PTE LTD

DMER NO. 7010045

ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

UNT CARD NO.

JOB DESCRIPTION

icident Date: 15.02.2022

ATURE: 3P 15.02.2022

NO


00010

LABOR CODE

PB

DESCRIPTION

PANEL BEATING-SHC1291J



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

o.: SHC1291J

LIMITS

Vehicle No.:

SHC1291J

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard