ASS. REC. BY: STEVE REF: CS/FC/120	01492/Erf3						
ASSIGNMENT							
From: Date:	Veh No: SKE 4200 G Yr Regn: 31/8/17						
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /						
OD (TP) WS / TP RES / OD RES / EVA / INV / MY	Truck / Trailer or						
To Inspect Vehicle No:	Make: Mini One c.c. 198						
at Workshop m/s	Colour BIVE A/C: Insured / Std / NI / NA						
of	Sp.Reading 3400 T/Radio: Insured / Std / NI / NA						
Insured:	Eng/No:						
Policy No.	CINO: WMWX519080AE 80264						
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt						
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or						
(Client's Record)	Brake: Ingrider / Jammed / Leaked / Burnt or						
Make of Veh:	Modi: Nii / S(Rim / STD A/Rim or						
	Tyre Size: F: 195/55R15						
(Policy Condition)	R:						
Remark: The veh had commenced its N/S O/S	BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM!						
repair at the time of inspection.	TOYO / YOKO or						
Bal. or Market Value:	Front Rear						
IDAC Accident Rport Consistent? : Yes or No	R/Bal. R/Bal. Mm						
GIA / PR Seen:Consistent? : Yes or No	L/Bal. 4 mm L/Bal. 17/0/09						
Est Repairs: days Res.: Yes or No	D.O.A. SIMPLY TOUCHUS ROSE						
Lum Sum: % 3 Val.: Yes or No	Survey held at Transe vio Kass						
CA / REV / REP. / 24 HRS	Des. of Damages : Frt I Rear I OIS I NIS I UIC I Rooftop or						
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.						
Date / Time Action / Instruction	The old / change hamb / Body change and the change						
MV-7 % K .							
· ·							
Date/Time, File Pass to? : Prell. Report	Days Of Repair:						
1) : Final Report	Resurvey No. of Trip: Survey Fee:						
Date/Time, File Return to?	Transportation:						
2) Add F							
	: Interview (\$) Photos						
Repide Formsk : Lump Sun / LE.L: (1)	: Tech, Invs (\$) Others						
morrolo master i tronta i in	TOTAL						
	; IVIAL						



EUROKARS HABITAT PTE LTD

27A TANJONG PENJURU, SINGAPORE 609042



ESTIMATE COST OF REPAIRS

MS First Capital Insurance Ltd			NAME:				WIP:	52481	
	obinson Roa	ADDRESS:					EXCESS:		
#16-0	01 City Hous	se						DATE:	15-Feb-22
Singa	apore 06887	77							
ATTN	N. :	MOTOR CLAIMS	TEL:						
FAX	:								
VEH	NO:	SKE4200G	DATE IN:				CONTACT PERSON:	JESS	63310685
CHAS	SSIS NO:	WMWXS120802E80269	MILEAGE:				TYPE OF CLAIM:	THIRD F	PARTY
MOD	EL:	MINI One 5 Door RHD	DATE REG.		31-Aug-17		POLICY NO. :		
				NAT	URE OF WOR	RKS			
			2	YTC.	UNIT PRICE	1ST SUF	PP	REVISED	PRICES
1	REAR BU	MPER / DD		1	984.50		M51.12.7.380.024		984.50
2	TOWING	COVER LH X		1	49.98		M51.31.7.380.025		49.98
3	TOWING	COVER RH X		1	49.98		M51.31.7.380.026		49.98
4	REAR BU	MPER LOWER SPOILER (BL	ACK)/(W	1	290.29		M51.12.7.380.030		290.29
5		OCKET (NEC) / NO		1	17.61		M51.12.7.382.306		17.61
6	PDC HOLI	DER LH (NEC) n	(1	36.27		M51.12.7.403.267		36.27
7	PDC HOLI	DER RH (NEC) N	0 0	1	36.27		M51.12.7.403.266		36.27
8		GLAMP CHROME GARNISH	- 1	1	117.58		M51.12.7.365.737		117.58
9		R BUMPER LH		1	188.56		M51.12.7.318.755		188.56
_	7 7 7 7 7 7	R BUMPER RH		1	188.56		M51.12.7.318.756		188.56
		MPER REINFORCEMENT	1	1	600.21		M51.12.7.300.788		600.21
	WASHER-			2	14.56		B51.12.7.300.789		29.12
		NIC SENSOR INNER		2	498.10		M66.20.9.302.473		996.20
		NIC SENSOR OUTER	7	2	326.56		B66.20.9.274.428		653.12
_		NIC SENSON OUTER		4	6.70		B66.20.9.283.203		26.80
-	SENSOR (1 1		1	174.20	-	M63.24.6.946.904		174.20
_	REAR FOO			1	143.97		M18.30.8.606.004		143.97
17	TAILPIPE 1	TIP X			143.97		W10.30.0.000.004		1 10.0
			· 7 % 5 1 1 1 1 2 1 3 1	(1) 800 £	SUPPLEMENT	TABY			
						45.00	on.	REVISED	PRICES
				AIK.	UNIT PRICE	151 501	<u> </u>	KEVISED	TRIOLO
1				-					
2				-				-	
3									
									4,583.22
	TOTAL PARTS				-	4,303.22			
									4 502 22
							TOTAL PARTS COST		4,583.22
	<u>Labour Description</u>						DE 40E	DDICE	
					REVISE	PRICE			
1	TO REPLACE REAR BUMPER, LOWER SPOILER, REINFORCEMENT & ALL ACCIDENT DAMAGE ARES. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.					840	1,680.00		
2	TO RESP	RAY REAR BUMPER. So.	0					800	1,000.00
3	TO TRAN	ISFER THE REVERSE SENS	SORS.						300.00

		/					
,	4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NETT	150	250.00		
5		TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT	10.	350.00		
	6	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.			200.00		
	7	SUNDRIES.	NETT	2	Ø 50.00		
			TOTAL LABOUR		Í	3,830.00	
		ARKS:	TOTAL PARTS			4,583.22	
	1HIS MORI	IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE E DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE	TOTAL	•		8,413.22	
	NFO	RMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT	LESS EXCESS			•	
SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES. TOTAL AFTER EXCESS GST 7%				•			
						•	
١			GRAND TOTAL	Sales in the second			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u>
 is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Steve CLKK) MMM 17/2/22, 10.90~ PJP JJP

SEOQ22280001 / Eurokars Habitat Pte Ltd [609042]
ENTRY DATE & TIME: 08/02/2022 18:59 (SGT)
SUBMITED BY: EUROKARS HABITAT PTE LTD - TANJONG PENJURU VERSION: 1 (08/02/2022 18:59 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Drivet

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy hability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

The issue and acceptance of this Form by insurance companies is not an authission of poincy hability on the part of the insurance companies.
 Any false reporting may be referred to the Police for investigation.
 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
 This report will be copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

08/02/2022 18:59 (SGT) Date of Submission 08/02/2022 07:50 (SGT) Date of Accident Exact Location of Accident Singapore BALESTIER ROAD Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

1400

SKE4200G Vehicle Registration Number

INSURED/POLICYHOLDER

Is company? Mr Tan Chin Hwee (Chen Jinghui) Name Of Registered Owner SXXXX623F NRIC No chinhweetan@icloud.com Email Address (Phone) +65-81881892 Mobile Phone No (Home) +65-81881892 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer One Exact purpose for which vehicle was being used at time of Private use ATTENDED TO THE TOTAL PROPERTY OF THE PARTY Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Private car Auto Transmission

INSURANCE COMPANY

AIG Asia Pacific Insurance Pte. Ltd. Name of Insurance Company Comprehensive Type of Coverage No Fleet Policy **Policy Number** Cover Note Number

DRIVER

CC

Mr Tan Chin Hwee (Chen Jinghui) Name of Driver SXXXX623F

Accident report SE0Q22280001

Page 1 of 21

te Of Birth 05/08/1971 Indoor ccupation **Date Of Driving Pass** 07/12/1994 27 YEARS AND 2 MONTHS **Driving experience** Male Gender (Phone) +65-81881892 Mobile Number (Home) +65-81881892 Alt, Phone Number chinhweetan@icloud.com **Email Address** 28 Grove Crescent Address Address complement 279161 Postcode Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Collision - Head to Rear Type of Accident DRIZZLE Weather Conditions Road Surface DAMP OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No Was there any audio recorded? Yes **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number PA8708U Vehicle Manufacturer Toyota Vehicle Model

Vehicle Woder Vehicle Variant Vehicle Colour Vehicle Category Commercial vehicle Name of Driver SANTANA SOH CHENG HAI NRIC No SXXXX537D

Contact Number Address



Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report governly the details of the accident to speed up the classic process.
- 2. This communist he completed by the Policyhelder and/or the Authorised Briver
- 3. Information provided must be as freibful and accurate as possible. Any will discrepresentation or with siding of material facts may allow insurance companies to repudiate policy liability.
- 4. The come and acceptance of this form by insurance companies is not an admission of policy i ability on the part of the insurance
- 5 Any false reporting may be referred to the Police for Investigation
- 8. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7. By the ladgment of this report to the incurers, you hereby consent to the archiving of this report at the centre and so capies of the report being made available aforesaid
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicles) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' Langers haw firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - [ii] processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims fincluding the mailing of correspondence, statements, invoices, reports or notices to me. which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, declose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Perposes.
- [d] my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection. investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:

(i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders

ver is not the policyholder)

Date & Time:

Accident report SE0Q22280001

Page 4 of 21

SKETCH PLAN	Balestier Road tourns CTE	
	Balestier Road tounds CTE bysstep	
	van - Mini	
DESCRIBE CIRCUMSTAN	ES OF THE ACCIDENT	
This morning, light to come from	trials success - I like the second	
lt was di bit dam the bass	Leting and banged into my car. 2-this lightly and the read was a p. There were at least 10 witness at too.	
	8/2/20	2
DECLARATION 1/We declare the foregoing par	itografs are true in every respect	
MHM	Driver's Signature Reports Standard Arsonner Solution	
0750	Driver's Signature (If draver is not the policyholder) Date & Time: Reporture Create Associated Solution Reporture Create Associated Solution	