

|   |        |      |             |
|---|--------|------|-------------|
| 1 | of 2 ? | 100% | Find   Next |
|---|--------|------|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|                                                                                                                                        |                                                                               |                        |                                                           |  |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------|------------------------|-----------------------------------------------------------|--|
| <b>Affiliated to Federation Internationale Des Experts En Automobile</b>                                                               |                                                                               |                        |                                                           |  |
| ERGO INSURANCE PTE LTD<br>8 TEMASEK BOULEVARD, #04-01 SUNTEC<br>TOWER THREE SINGAPORE 038988                                           |                                                                               |                        | Ref: CS/EGI22001506/Eqf3<br>Date: 16/02/2022<br>Code: EGI |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                               |                        |                                                           |  |
| <b>Insured Veh.</b>                                                                                                                    | PC 9731J                                                                      | <b>Veh. Inspected</b>  | FX 9025Y                                                  |  |
| <b>Policy No.</b>                                                                                                                      |                                                                               | <b>Coverage (\$)</b>   | 0.00                                                      |  |
| <b>Claim No.</b>                                                                                                                       | CDMFG22000289                                                                 | <b>Excess (\$)</b>     | 0.00                                                      |  |
| <b>Assign From</b>                                                                                                                     | PAULINE SOH                                                                   | <b>Assign Date</b>     | 16/02/2022                                                |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                               |                        |                                                           |  |
| <b>Make &amp; Model</b>                                                                                                                |                                                                               | <b>c.c</b>             | 0                                                         |  |
| <b>Engine No.</b>                                                                                                                      | HIDDEN                                                                        | <b>Year of Reg.</b>    |                                                           |  |
| <b>Chassis No.</b>                                                                                                                     |                                                                               | <b>Colour</b>          |                                                           |  |
| <b>Odometer</b>                                                                                                                        | -                                                                             | <b>Steering</b>        |                                                           |  |
| <b>Brakes</b>                                                                                                                          |                                                                               | <b>Modification</b>    |                                                           |  |
| <b>General</b>                                                                                                                         |                                                                               |                        |                                                           |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                               |                        |                                                           |  |
|                                                                                                                                        | <b>Size</b>                                                                   | <b>Make</b>            | <b>Balance</b>                                            |  |
| <b>R/H Front Tyre</b>                                                                                                                  |                                                                               |                        | mm                                                        |  |
| <b>L/H Front Tyre</b>                                                                                                                  |                                                                               |                        | mm                                                        |  |
| <b>R/H Rear Tyre</b>                                                                                                                   |                                                                               |                        | mm                                                        |  |
| <b>L/H Rear Tyre</b>                                                                                                                   |                                                                               |                        | mm                                                        |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                               |                        |                                                           |  |
|                                                                                                                                        |                                                                               |                        |                                                           |  |
| <b>5. General Information</b>                                                                                                          |                                                                               |                        |                                                           |  |
| <b>Accident Date</b>                                                                                                                   | 11/02/2022                                                                    | <b>Inspection Date</b> | 16/02/2022                                                |  |
| <b>Survey held at</b>                                                                                                                  | KIM KOCK MOTOR PTE LTD<br>BLK 27A JURONG PORT ROAD #01-19<br>SINGAPORE 619101 |                        |                                                           |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                               |                        |                                                           |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                               |                        |                                                           |  |