

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22001513/Rvy3e2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11		Date:	23/02/2022	
	ATTN: OH VALE			Code:	ASM	
1.		Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SJD 36H	Veh. Inspected	t	SLZ 6940T	
	Policy No.	GA556840	Coverage (\$)		0.00	
	Claim No.	S2M03TDW	Excess (\$)		0.00	
	Assign From	OH VALE	Assign Date		16/02/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	AUDI A4 SEDAN 2.0 TFSI	c.c		1984	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	WAUZZZF46JA149761	Colour		BLUE	
	Odometer	46448 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	245/40Z R18	MICHELIN		6 mm	
	L/H Front Tyre	245/40Z R18	MICHELIN		6 mm	
	R/H Rear Tyre	245/40Z R18	MICHELIN		6 mm	
	L/H Rear Tyre	245/40Z R18	MICHELIN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.	General Information					
	Accident Date	14/02/2022	Inspect Date /	Time	16/02/2022 (03:48 PM)	
	Survey held at	Survey held at HARMONY MOTOR (AMK) PTE LTD				
	BLK 10 ANG MO KIO IND. PARK 2A #02-12 AMK AUTOPOINT SINGAPORE 568047					
5a.	. Remarks					
	B) THE REPAIR ES THE REPAIRER W C) ENCLOSED PL	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
5b.	b. Estimate Days of Repair					
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM22001513/Rvy3e2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser