

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No. 19900/190R GS1 Reg. No. 19-900/196-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL		Ref:	CS/AGI22001565/Kqf3n2
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHC 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE		Date:	14/03/2022
				Code:	AGI
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJH 3074G	Veh. Inspected		SLT 3195D
	Policy No.		Coverage (\$)		0.00
	Claim No.	C10013892/CD	Excess (\$)		0.00
	Assign From	SHAFWATI MD RABU	Assign Date		17/02/2022
2.	. Vehicle Particulars & Condition				
	Make & Model	MAZDA CX-5 (A)	c.c		2488
	Engine No.	HIDDEN	Year of Reg.		2017
	Chassis No.	JM6KF2WLAJ0129454	Colour		METALLIC GREY
	Odometer	91271 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	GOOD			
3.	·				
		Size	Make		Balance
	R/H Front Tyre	245/50 R19	PIRELLI		9 mm
	L/H Front Tyre	245/50 R19	PIRELLI		9 mm
	R/H Rear Tyre	245/50 R19	PIRELLI		9 mm
	L/H Rear Tyre	245/50 R19	PIRELLI		9 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	14/02/2022	Inspection Date	9	16/02/2022
	Survey held at	THIAM HENG HUAT PTE LTD			
		176 SIN MING DRIVE #05-14 SINGAPORE 575721			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: