

ASS. REC. BY: John

REF:

CS/U0122001579/R1/f3

180H

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBL 3732Pat Workshop m/s CYSof 38, WINDLANDS RD PK 61 #07-17Insured: UOI

Policy No. \_\_\_\_\_

Claims No. M12D17762202Sum Insured: \_\_\_\_\_ Excess: 500

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 55K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: GBL 3732PYr Regn: 2021 / JunType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: NISSAN NV 200 1.6 (A) PetrolColour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 12175

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 3N14AAM 2020002040Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_Tyre Size: F: 165/80R14

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

YOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 15/02/22D.O.I. 22/02/22Survey held at CYSDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	REPAIR LIMIT - 25K
	Confirm final figure is \$1,933.20, 4 Days
	red: 2910;60%

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. SI

Photos

Others

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / I.B.B. (\$) \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)



ROC Reg. No :A05041/2001E

GST Reg. NO.: 20-0105041-E

38 Woodlands industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700

Tel: 6219 2098 (3 Lines) Fax: 6219 2096 E-mail: [cysauto@singnet.com.sg](mailto:cysauto@singnet.com.sg)

MR UNITED OVERSEAS INSURANCE LTD	POLICY NO	: DHOM120060922100
146 ROBINSON ROAD	OUR REF	: OD 3525
#02-01 UOI BUILDING	VECHICLE NO	: GBL 3732 P
SINGAPORE 068909	MAKE/MODEL	: NISSAN NV200
ATTN: MOTOR CLAIMS DEPT	CHASSIS	: JN1YAAM20Z0002040
	DATE OF ACCIDENT	: 15.02.22

SURVEY BY

DATE : 18.02.22

1	PC	TAILGATE repair ✓		S\$	950.00
1	PC	TAILGATE MIRROR BRACKET ✓			170.00
1	PC	TAILGATE GLASS ✓			600.00
1	PC	TAILGATE "NV200" EMBLEM ✓			42.00
1	PC	REAR FENDER RH repair			1,350.00
				S\$	3,112.00
		COST PLUS	10%		311.20
				S\$	3,423.20

1 SET	TAILGATE GLASS INNER SEAL	RE ✓	S\$	20.00	S/NETT
1 PC	TAILGATE GLASS SEALANT	RE ✓		40.00	"
1 PC	TAILGATE "70KM/H" STICKER	RE ✓		20.00	"
1 PC	TAILGATE "6PAX" STICKER	RE ✓		20.00	"
			S\$	100.00	

TO TRANSFER TAILGATE FITTING

## TO REMOVE AND REFIX TAILGATE GLASS

TO CLEAN AND VACUUM

## TO CHECK WIRING FUNCTION

LABOUR CHARGES

TO PUTTY AND SPRAY PAINTING CHARGES

S\$ 4,843.20

SIN DOLLARS: FOUR THOUSAND EIGHT HUNDRED FORTY-THREE AND CENTS TWENTY ONLY

YOUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

**Signature:**

Date:

Casual  
 HP 90010068  
 4 days  
 P/P  
 22/02/22 @ 1410  
 EXCESS: 500  
 REVERT  
 Resum after repair



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 16/02/2022 15:47 (SGT)  
Date of Accident ..... 15/02/2022 15:30 (SGT)  
Exact Location of Accident ..... 725 Pasir Ris Street 72, Singapore  
Additional Location Information ..... MULTI-STOREY CAR PARK  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... GBL3732P

### INSURED/POLICYHOLDER

Is company? ..... Yes  
Name Of Registered Owner ..... TOPS & HUI BUILDERS PTE LTD  
Company Reg No ..... 2XXXXX180H  
Email Address ..... homeshape@gmail.com  
Mobile Phone No ..... (Phone) +65-82885709  
Alternative Phone No ..... (Office) +65-63686915

### VEHICLE PARTICULARS

Manufacturer ..... Nissan  
Model ..... Nv200  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Employment  
Are you claiming under your own insurance policy for repair to your vehicle? ..... Yes  
Vehicle Category ..... Goods vehicle  
Transmission ..... Auto  
CC ..... 1597

### INSURANCE COMPANY

Name of Insurance Company ..... United Overseas Insurance Ltd  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... DHOM120060922100  
Cover Note Number ..... -

### DRIVER

Name of Driver ..... SU WENJIE  
Passport No/FIN ..... GXXXX736T

Date Of Birth ..... 10/01/1988  
 Occupation ..... Outdoor  
 Date Of Driving Pass ..... 13/05/2016  
 Driving experience ..... 5 YEARS AND 9 MONTHS  
 Gender ..... Male  
 Mobile Number ..... (Phone) +65-97632295  
 Alt. Phone Number ..... -  
 Email Address ..... anjay0110@gmail.com  
 Address ..... BLK. 303A PUNGGOL CENTRAL  
 Address complement ..... #14-780  
 Postcode ..... 821303  
 Is the driver the policyholder? ..... No  
 If No, Relationship of the Driver with the Insured ..... Employee  
 Does Driver Own Other Vehicles? ..... No  
 Vehicle Registration Number of Other Vehicle Owned by Driver ..... -  
 Insurance Company of Other Vehicle Owned by Driver ..... -

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident ..... Collided into Property  
 Weather Conditions ..... Clear  
 Road Surface ..... Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? ..... No  
 Number of vehicles involved in the accident ..... 1  
 Was anybody injured in the Accident? ..... No  
 Was any injured conveyed to hospital by ambulance? ..... -  
 Was any other vehicle or property damaged? ..... No  
 Number of Passengers (Including Driver) ..... 1  
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? ..... No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? ..... No  
 Was notice of intended Prosecution given? ..... No  
 If yes, against whom? ..... -

#### CIRCUMSTANCES OF ACCIDENT

ON THE ABOVE MENTION DATE & TIME, I WAS REVERSING MY VAN INTO THE CAR PARK SLOT AT BLK. 725 PASIR RIS ST. 72. I DID NOT NOTICE THE PILLAR BEHIND OF ME AND I HIT ONTO IT. IT CAUSES MY WINDSCREEN TO SHATTERED TOO.

#### ATTACHMENT(S)

Are accident photos available for attachment? ..... Yes  
 Was there any video captured by Car Camera? ..... No  
 Was there any audio recorded? ..... No



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



*[Handwritten signature]*



進友威汽車服務私人有限公司  
CYS Automobile Services Pte Ltd  
33 Woodlands Industrial Park East 1  
#07-17 Admiralty Industrial Park  
Singapore 757700  
Tel: 6219 2098 (3lines) Fax: 6219 2096

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

#### Sketch Plan

Blk 725 Partir R3 St. 72

A - GBL37321



Describe Circumstances of the Accident

ON THE ABOVE MENTION DATE & TIME. I WAS  
 REVERSING my van into THE CAR-park slot  
 AT BIK 725 PAIR RIS ST 72. I DID <sup>not</sup> notice  
 THE pillar BEHIND OF ME AND I hit  
 INTO IT. IT CAUSES my MINDSCREEN to  
 SHAKEEN too

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage claim under your own comprehensive policy. please check with your policy for more information.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

*[Signature]*

Driver's Signature (if driver is not the policyholder) / Date & Time



進友成汽車服務私人有限公司  
 CYS Automotive Services Pte Ltd  
 33 Woodlands Industrial Park East 1  
 #02-17 Admiralty Industrial Park  
 Singapore 751700  
 Tel: 6219 2098 (Lines) Fax: 6219 2096

Witnessed by Reporting Centre Personnel



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	180H
Vehicle No.:	GBL3732P
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Feb 2022
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.6 (A) PETROL
Primary Colour:	Silver
Manufacturing Year:	2021
Engine No.:	HR16186888D
Chassis No.:	JN1YAAM20Z0002040
Maximum Power Output:	-
Open Market Value:	\$18,396.00
Original Registration Date:	22 Jun 2021
First Registration Date:	22 Jun 2021
Transfer Count:	0
Actual ARF Paid:	\$920.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	21 Jun 2031
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$31,554.00
COE Rebate Amount:	\$29,439.00
Total Rebate Amount:	\$29,439.00

The information contained herein is correct as at 23 Feb 2022

OK



# Nissan NV200 1.6A

Overview

Financial


Accessories

Similar

Research

Photos

Map



## Lek Auto Pte. Ltd.

Price	\$56,800	Lifespan	19-Sep-2041
Depreciation	\$5,930 /yr <a href="#">View models with similar depre</a>	Reg Date	20-Sep-2021 (9yrs 6mths 27days COE left)
Mileage	N.A.	Manufactured	2021
Road Tax	N.A.	Transmission	Auto
Dereg Value	\$20,380 as of today (change)	Fuel Type	Petrol
COE	\$21,284	OMV	\$18,396
Engine Cap	1,598 cc	ARF	\$920
Curb Weight	1,160 kg	No. of Owners	1