

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|---|----------------|-------|-----------------------|--|
| | UNITED OVERSEA | AS INSURANCE LTD | | Ref: | CS/UOI22001579/Rtf3e2 | |
| | 146 ROBINSON RO | | | Date: | 28/03/2022 | |
| | #02-01 UOI BUILD | INGSINGAPORE 068909 | | Code: | IIOI2 | |
| 1. | | Policy Particula | re :- OWN DAM | | 0012 | |
| •• | Insured Veh. | 1 oney 1 articula | Veh. Inspected | | GBL 3732P | |
| | Policy No. | DHOM120060922100 | Coverage (\$) | • | 0.00 | |
| | Claim No. | M12D17762202 | Excess (\$) | | 500.00 | |
| | Assign From | JOSEPHINE | Assign Date | | 18/02/2022 | |
| 2. | Vehicle Particulars & Condition | | | | | |
| | Make & Model | NISSAN NV200 1.6 (A) PETROL | c.c | | 1598 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2021 | |
| | Chassis No. | JN1YAAM20Z0002040 | Colour | | GREY | |
| | Odometer | 12175 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | NIL | |
| | General | FAIR | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 165/80 R14 | TOYO | | 6 mm | |
| | L/H Front Tyre | 165/80 R14 | TOYO | | 6 mm | |
| | R/H Rear Tyre | 165/80 R14 | TOYO | | 6 mm | |
| | L/H Rear Tyre | 165/80 R14 | TOYO | | 6 mm | |
| 4. Description of Damages | | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. General Information | | | | | | |
| | Accident Date | 15/02/2022 | Inspection Dat | e | 22/02/2022 | |
| | Survey held at | CYS AUTOMOBILE SERVICES | PTE LTD | | | |
| | | 38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 | | | | |
| | | ADMIRALTY INDUSTRIAL PARK SINGAPORE 757700 | | | | |
| 5a. | | Remarks | | | | |
| | A)THE MARKET VALUE IS S\$55,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days | | | | | |
| | | | | | | |