

ASS. REC. BY:

REF:

102/ 22 0015881K

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

8150k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

I.B.I

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMU 20437

Yr Regn:

11, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 218i

c.c

1499

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

32196

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBA 2M120XC7D62831

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

235/35 ZR19

R:

235/40 ZR19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

7

mm

L/Bal.

8

mm

L/Bal.

7

mm

D.O.A.

17/12/12

D.O.I.

24/2/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 EST not ready

17/04/2023 Finalise P/P \$4,482.90 @ 3 days (Red \$1,220.95/21%)

Date/Time, File Pass to?

17/04/2023

1) Typist

Date/Time, File Return to?

2)

☐

: Prell. Report

☒

: Final Report

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format : TP

Lump Sum / I.B.I: (\$ P/P \$4,482.90