

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190R GS1 Reg. No. 19-900/190-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef:	CS/AGI22001592/Utf3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate:	28/02/2022	
			Co	ode:	AGI	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SLM 3840L	Veh. Inspected		SMD 2682T	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10013925/CD	Excess (\$)		0.00	
	Assign From	SHAFWATI MD RABU	Assign Date		18/02/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI ELANTRA GLS (A)	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	KMHD841CMJU727876	Colour		RED	
	Odometer	75909 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/45 R17	GOODYEAR		6 mm	
	L/H Front Tyre	215/45 R17	GOODYEAR		6 mm	
	R/H Rear Tyre	215/45 R17	GOODYEAR		6 mm	
	L/H Rear Tyre	215/45 R17	GOODYEAR		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	17/02/2022	Inspection Date		18/02/2022	
	Survey held at EURO SUCCESS SERVICES PTE LTD					
		1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY @ KAKI BUKIT SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: