

ASS. REC. BY: Taufik

REF:

NS/ W C 22001604/Tvy3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: SJJ 1363A
Policy No. _____
Claims No. MT/1161636-003
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: away
Vehicle: IN / OUT

Veh No: SHA90084 Yr Regn: 2021, May
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Hyundai c.c. 1580
Colour: Yellow A/C: Insured / Std / NI / NA
Sp. Reading: 116149 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: KMHC851CVL4184935
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or _____
Brake: Inorder / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 195/65R15
R: 2 -
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Washin
Front _____ Rear _____
R/Bal. 6 mm L/Bal. 6 mm
D.O.A. 12/2/2022 D.O.I. 15/2/22
Survey held at CompuTiger
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
9/3/22	Taufikh informed \$3599.92 (red 1528.36,29%)

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report
1) _____
Date/Time, File Return to?

Days Of Repair: 3
Resurvey No. of Trip: 1

2) 15/3/22-typist

Report Format: TP
Lump Sum / L.B.R. (\$) \$3599.92

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:	
Transportation:	
\$ + RS. \$	
Photos	
Others	
TOTAL	

REPAIR ESTIMATE*

VEHICLE NO SHA9008U

MAKE/REG 27.05.2021

MODEL : HYUNDAI IONIQ G3

DATE

12/02/22

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Amount
1	FRONT FENDER EMBLEM		nee ✓ \$26.60
1	FRONT FENDER RH		bt ✓ \$588.50
1	FRONT PILLAR GRANISH RH		wis ✓ \$75.00
1	RH SIDE ROCKER GARNISH		de ✓ \$290.00
1	FRONT DOOR RH		bt ✓ \$1,797.20
1	FRONT DOOR WING MIRROR RH		nn X \$1,391.70
	SUB TOTAL		\$4,169.00
	LESS 20%		\$833.80
	DISCOUNTED TOTAL		\$3,335.20
1	FRONT DOOR COMFORT STICKER		nee ✓ \$75.00
			-\$67.50
	Labour Charge		
	Panel Beating		525 \$700.00
	Spray Painting Charge		600 \$750.00
	Remove/refix door parts		60 \$120.00
	Check Wiring		30 \$60.00
	TOTAL LABOUR		\$1,630.00
	ESTIMATE TOTAL		\$5,032.70
			5128.28

Tapmi 92495744
 up' 15/2/21 330p
 P/P Rising by the point
 03 days
 Tapmi @Kuantan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 14.02.2022 15:28 Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 4173587

JC NO.305504861


STOMER
 /MS CITYCAB PTE LTD
 STOMER NO. 7010070
 DRESS 383 SIN MING DRIVE
 Singapore SINGAPORE 575717
 65551188
 (R) (O)
 (P)
 COUNT CARD NO.

REGN NO.: SHA9008U	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G3)	DATE/TIME IN 14.02.2022 11:40
YR OF MANU. 27.05.2021	TARGET DATE
CHASSIS CODE KMHC851CVLU184935	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 12.02.2022
 NATURE: 3P 12.02.200

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------



HECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wedgement Slip

Exit Pass

No.: **SHA9008U** **CHIANG**

Vehicle No.: **SHA9008U**

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard