

REPAIR ESTIMATE*

VEHICLE NO : SHA9008U

MAKE/REG : 27.05.2021

MODEL : HYUNDAI IONIQ G3

DATE

12/02/22

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Amount
1	FRONT FENDER EMBLEM		net ✓ \$26.60
1	FRONT FENDER RH		bt ✓ \$588.50
1	FRONT PILLAR GRANISH RH		wt ✓ \$75.00
1	RH SIDE ROCKER GARNISH		de ✓ \$290.00
1	FRONT DOOR RH		bt ✓ \$1,797.20
1	FRONT DOOR WING MIRROR RH		X \$1,391.70
	SUB TOTAL		\$4,169.00
	LESS 20%		\$833.80
	DISCOUNTED TOTAL		\$3,335.20
1	FRONT DOOR COMFORT STICKER		net ✓ \$75.00
			\$67.50
	Labour Charge		
	Panel Beating		525 \$700.00
	Spray Painting Charge		600 \$750.00
	Remove/refix door parts		60 \$120.00
	Check Wiring		30 \$60.00
	TOTAL LABOUR		\$1,630.00
	ESTIMATE TOTAL		\$5,032.70

Tapmi 92495744
 up' 12/2/22 330p
 P/P Rising by the point
 03 days
 Tapmi @Kuantan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 14.02.2022 15:28

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 4173587

JC NO.305504861


STOMER
/MS CITYCAB PTE LTD
STOMER NO. 7010070
DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65551188
(R) (O)
(P)
COUNT CARD NO.

REGN NO.: SHA9008U	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G3)	DATE/TIME IN 14.02.2022 11:40
YR OF MANU. 27.05.2021	TARGET DATE
CHASSIS CODE KMHC851CVLU184935	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 12.02.2022
NATURE: 3P 12.02.200

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wedgement Slip

Exit Pass

No.: **SHA9008U** **CHIANG**

Vehicle No.: **SHA9008U**

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard