

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



**AUTOMOBILE INSPECTION REPORT** 



NITLIC	NICOME INICIDE	ANICE CO ODERATIVE LTD			/av2n2	
NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC22001607/Vqy3n2						
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	08-03-2022		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SKK 2450H	Veh. Ir	nspected	SHC 3707P	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1163443-001	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	07/02/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2019	
	Chassis No.	KMHC851CVLU186886	Colou	r	BLUE	
	Odometer	163788	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST	LAKE	5 mm	
	L/H Front Tyre	195/65 R15	WEST	LAKE	5 mm	
	R/H Rear Tyre	195/65 R15	WEST		5 mm	
	L/H Rear Tyre	195/65 R15	WEST		5 mm	
4.	<del>_</del>					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	05/02/2022	Inspec	tion Date	07/02/2022	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					