

Our Job Ref No : 305504005  
Date : 11/02/22

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive, Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHD4248K


Date of Accident : 28.01.22


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC FBT1185P
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \$411.76
  - (b) Labour Charges (include advertisement stickers etc,if any) \$630.00
  - Total for Part-By-Part Repair Cost \$1,041.76
  - (c) Lumpsum Repair (if applicable)
  - Total for Lumpsum repair cost after Less: 20%
  - Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : LIM T S  
Tel : 62148398  
Fax : 65468156

Signature :   
Name : THEVAN  
Date :

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees		--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Effective Date: 1 Nov 2020

LKK -

INSURANCE: NTUC - CHS

MVA: LIM T S

DATE: 7-Feb-22

MODEL: Hyundai Ioniq

VEHICLE NO: SHD4248K

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
		1		\$459.40 Xr
		1		\$451.25 / Scv
		10	\$2.20	\$22.00 / Nic
		1		\$41.45 / Scv
				\$974.10
				\$194.82
				\$779.28
	SUB TOTAL			
	LESS 20%			
	SPARE PARTS TOTAL			
	Labour Charge			\$400.00 350
	Panel Beating			\$300.00 250
	Spray Painting Charge			\$120.00 30
	Remove/Refix Reverse Sensor			
				630
	TOTAL LABOUR			\$820.00
	ESTIMATE TOTAL			\$1,599.28

411.76

630

1041.76

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Therun 82235769

7/2/22 1630

LIS after repair photo

2days wp

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: