

ASS. REC. BY: Taufik

REF:

NS/INC22001677/Tqy3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. MT/1165780-001

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNC8946HYr Regn: 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HyundaiC.C. 1685Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 55894

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: UMHLS41444444087820

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wentake

Front

Rear

R/Bal. 0 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 21/2/22Survey held at Confia Agency

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufikh finalised LS \$3400, 2 days. (Red \$2720.92, 44%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 22/03 Typist
☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 2Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Rep. Format: TPLump Sum / L.P. / 3400Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC8946H

Make : HYUNDAI

Model : I-40

Date: 21.02.2022

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$1,052.20
10	FRONT BUMPER CLIPS		\$2.20	\$22.00
1	FRT BUMPER BRACKET TOP RH			\$44.80
1	RADIATOR GRILLE			\$1,480.00
1	HEADLAMP RH			\$1,388.00
1	HEADLAMP SUPPORT PANEL			\$907.40
1	FRT FENDER RH			\$663.00
	SUB TOTAL			\$5,557.40
	LESS 20%			\$1,111.48
	DISCOUNTED TOTAL			\$4,445.92
	FRT NUMBER PLATE WITH TRIM COVER		-10%	\$55.00
				\$55.00
	Labour Charge			
	PANEL BEATING			\$900.00
	SPRAY PAINTING CHARGE			\$600.00
	TUFF KOTE			\$60.00
	CHK ALL LIGHTING			\$60.00
	TOTAL LABOUR			\$1,620.00
	ESTIMATE TOTAL			\$6,120.92

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495745
 up 21/2/22 0445
 L/S Resurvey after repair
 Tanpin 01/02/2022
 2-3 days

Date/Time: 21.02.2022 14:25

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4176331

JC NO305506045

CUSTOMER

IR/MS COMFORT TRANSPORTATION PTE LTD

CUSTOMER NO. 7010045

ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

TEL. (R) 65508755

(P)

(O)

DISCOUNT CARD NO.

REGN NO.:
SHC8946H

MILEAGE

MAKE :
HYUNDAI

FUEL

E.....1/2.....F

MODEL
I-40

DATE/TIME IN
21.02.2022 12:10

YR OF MANU.
21.04.2016

TARGET DATE

CHASSIS CODE
KMHLB41UMGU087820

COMPLETION DATE/TIME:

Accident Date: 20.02.2022


NATURE: 3P 20.02.2022

JOB DESCRIPTION

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Delivery Slip

Exit Pass

No.: SHC8946H

YY

Vehicle No.:

SHC8946H

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard