ASS REC. BY: TOLIM REF: CS/CTIDD (01704/Bty3 Denise
ASSI	D1704/B1 45 1 2000SC
From	
Estimated Cost:	Veh No: SLN 8154X Yr Regn: 18/5/2017. Type: M.Car, I M.Cycle Bus Van Lorry Taxi Prime Mover
OD IN WS I TP RES I OD RES I EVA I INV I MV	Truck / Trailer or
To Inspect Vehicle No: SLN 8154X	Make: Handa Shuttle c.c 1496
at Workshop m/s MS Casb	Colour Grew NC: Insured / Std / NI / NA
of 8 Kaki Bt Ave 4 Premier # 01-07	Sp.Reading 144272 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No: L15 B 3 5 3 6 9 1 6
Policy No.	C/No: GK 8 1005 892
Claims No.	Gen. Cond: Good / Fair / For / Burnt
Sum Insured: Excess:	Steering: knorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: dnorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: NII / SARTIM / STD A/Rim or
	Tyre Size: F: 205/50/16
(Policy Condition)	R: 205/50/16
Remark: The veh had commenced Its N/S O/S repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
	TOYO/YOKO or Falken
Bal. or Market Value: 52,000/Y IDAC Accident Rport: Consistent? ; Yes or No	Fron Rear R/Bal. 6 mm
IDAC Accident Rport: Consistent? ; Yes or No GIA / PR Seen: Consistent? ; Yes or No	1/201
Est. Repairs:	DOA 19/21222
Luin Sum: % 3 Val.: Yos or No	10/2/2023
	Des. of Damages: Frt 1 Rear 1 O/S 1 N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS₩₽ Vehicle: IN/OUT	
Dale: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
Range: 6,000/2 - 7,00)8/7
Recommended car: LS\$	6600.00 Talin 13/3/2002
	ost of repair of LS \$6,600/- with 8 days of repair
RED: 8571.26;56%	
MV 52,0006	

8 Date/Time, File Pass to? : Prell. Report Days Of Repair: Resurvey No. of Trip: : Final Report Survey Fee: Date/Time, Filo Return to? Transportation: Add Fee: : Site Insp (\$ _S + RS.__SI 2) Interview (\$ Photos Tech. Invs (\$ Repertornat: Offices Lump Short I.E. I: 17 \/\eel:enc¦ **(\$** TOTAL

MS CAR AUTO PTE LTD 8 Kaki Bukit Ave 4 #01-07 Premier @ Kaki Bukit Singapore 415875

Tel: 6385-1838 / 9725-4442 Fax: 6386-1838 Email mscarautopl@gmail.com

101.1005 1050 / 5725 4	TEX. CODE 1000 Email motor of the Co	01-11
Market The Bearing In the said	The season of th	Vehicle Nos: 51-N 454X
SJE :		Vehicle Nos: St-N \$154X Model: Horda Shuttle
Date of Survey:		Model: Movera Zilkille
Date of Survey .		Year:
Contacts:		

20M

MAKE	& MODEL: HONDA CIVIC Shuttle	2	-017
SHEDD WILLS			
ITEM	DESCRIPTION 817.00	1	\$989.30 DD
1	Rear boot	1	\$164.20 JM
2	Rear boot lock	2	\$182.40 ND
3	Rear boot hinge L+R	1	\$137.50 TN
4	Rear boot w/strip	1	\$84.60 NEC
5	Rear boot logo	2	\$968.60 BR v
, 6	Rear boot lamp L+R	1	\$167.50 NN
7	Rear boot insulator		\$50.00 NN)
	Rear boot insulator clip	1	\$79.30 N C
9	Rear boot emble em SHUTTLE 48.60	+	\$ 674.2 0/1/
10	Rear boot spoiler	1	\$458.60 BR
11	Rear boot inner trim 243,80		\$83.70 NS
12	Rear boot inner trim handle	1	
13	Rear boot garnish 383.10	1	\$485.30 BR \$176.40 BR
14	Rear boot chrome	1	
15	Rear boot w/s glass	1	\$885.60 BR
16	Raer boot w/s glass mmoulding / 38 · 90	1	\$164.70 NJ
17	Rear boot number plate lamp L+R		\$86.40 ND
18	Rear boot number plate lamp garnish	1	\$143.20 ND
19	Rear pumper retainer RL 44.40	2	\$238.00 NG
20	Rear pumber brumply	1	\$883.50 BR √
21	Rear pumper bearn	2	\$148.00 NS
22	Rear bumper bracket L+R	2	\$96.00 NSX
23	Rear bumper clip 30100	10	\$50.00 NEU
24	Rear bumper mudflap RH	2	\$185.70] N
25	Rear bumper under cover	1	\$ 152.7 0, >
26	Tail lamp L+R 332: 40 LH	2	\$ 664.80 BB
27	Tail lamp panel L+R	2	\$328.40 NDX
28	Tail lamp clip L+R 5.00 LH (.2	\$10.00 NES
29	Rear end panel 450 · 00	1	\$623.70 D∫
30	Rear end panel top garnish	1	\$128.80 BE
31	Spare wheel panel 632.00	1	\$987.30 D
32	Spare wheel panel top board	1	\$ 377.2 0 NDX
33	Spare wheel panel side panel L+R	2	\$484.60 NDX
	Parts Sub Total		77.20 7.20 7.20 7.20 7.20 7.20 7.20 7.20

Rear w/s glass sealant 300.00 1 \$100.00		Discount 20%
Rear w/s glass sealant 30 00 1 350000 1 350000 1 350200 2 356000 1 350200 3 3 3 3 3 3 3 3 3		Parts Total \$9,056
Rear w/s glass sealant 30 00 1 350000 1 350000 1 350200 2 356000 1 350200 3 3 3 3 3 3 3 3 3	Specie	Nett
Reverse camera	A STATE OF THE STA	4 4400 00
Reverse sensor 30.00 2 \$560-00 4 Rear end panel sealant 30.00 1 \$80-00 1 \$		ユラ0~00 1 \$532.8 0
4 Rear end panel sealant 30.00 1 \$80.00 1 \$462.30 5 800 wistrip motor 390.00 1 \$462.30 5 800 wistrip motor 390.00 1 \$462.30 5 800 wistrip motor 30.00 1 \$80.00 7 7 \$pare wheel panel insulator 30.00 1 \$50.00 6 8 Rear number plate 30.00 1 \$50.00 6 7 \$50.00 6 7 \$8 Rear number plate \$9.00 8		200.00 2 \$560.00
5 Boot wistrip motor 390 ⋅ e0 1 \$462-30 ⋅ 6 5 spare wheel panel sealant 30 ⋅ n) 1 \$86-00 n 7 Spare wheel panel insulator 1 \$150-00 n 8 Rear number plate 2 50 ⋅ e0 1 \$50-00 n 1 To R & R accident damage parts, to cut/weld, knock and realign accident affected area 1 \$1,800.00 2 To putty and respray accident affected area 1 \$420-00 n 2 To rust proof accident affected area 1 \$420-00 n 5 To R & R rear boot mechanism 1 \$800.00 6 To R & R rear luggage compartment 1 \$800.00 7 To R & R reverse sensor and check function 1 \$600.00 9 To check wheel alignment 1 \$600.00 9 To check wheel alignment 1 \$400.00 10 To R & R rear w/s glass 1 \$2 ⋅ n 11 Labour Total 5 \$100.00 12 Special Nett Total: 200.00 13 Special Nett Total: 200.00 14 Special Net Total 5 \$100.00 15 Special Net Total 5 \$100.00 15 Special Nett Total: 200.00 15 Special Nett Total 5 \$100.00 15 Special Nett Total 5		
Spare wheel panel sealant 30.00 1 380.00 N 1 350.00 N 1 350.00 N N N N N N N N N	•	. 4.50.00
7 Spare wheel panel insulator 8 Rear number plate 7 € 0 € 0 € 0 € 0 € 0 € 0 € 0 € 0 € 0 €		4
Rear number plate		1 \$150.00°
1 To R & R rear luggage compartment 1 \$460.00		30.00 1 \$50.00 C
Tabour Labour To R & R accident damage parts, to cut/weld, knock and realign accident affected area 1 \$1,800.00 1 \$1,600.00 2 To putty and respray accident affected area. 1 \$4,600.00 2 To rust proof accident affected area. 1 \$420.00 k To rust proof accident affected area. 1 \$420.00 k To R & R rear boot mechanism 1 \$80.00 \(\sqrt{2} \) To R & R rear luggage compartment 1 \$60.00 \(\sqrt{2} \) To R & R reverse sensor and attachment parts 1 \$450.00 k To R & R reverse sensor and check function 1 \$60.00 \(\sqrt{2} \) To Check wheel alignment 1 \$400.00 k Defail of the company of the	o Real Humber plate	
Second S		960.42 Special Nett Total: \$2,005.4
1 To R & R accident damage parts, to cut/weld, knock and realign accident affected area 1 \$1,800.00 2 To putty and respray accident affected area. 1 \$41,600.00 2 To rust proof accident affected area. 1 \$420.00 M 5 To R & R rear boot mechanism 1 \$80.00 M 6 To R & R rear luggage compartment 1 \$80.00 M 7 To R & R uphostery, garnish and attachment parts 1 \$150.00 M 8 To R & R reverse sensor and check function 1 \$60.00 M 1 To R & R rear w/s glass 1 \$140.00 M 1 Sample of the series of the se	Labou	
2 To putty and respray accident affected area. 1 \$4,600.00 2 CO 0 4 To rust proof accident affected area. 1 \$420.00 f 5 To R & R rear boot mechanism 1 \$80.00 f 6 To R & R rear luggage compartment 1 \$60.00 f 7 To R & R uphostery, garnish and attachment parts 1 \$450.00 f 8 To R & R reverse sensor and check function 1 \$60.00 f 9 To check wheel alignment 1 \$60.00 f 1 To R & R rear w/s glass 1 \$140.00 f Labour Total 9 Parts Total Special Nett Total: Labour Total Grand Total Resurvey Lump Sumvepun Parts 522 3	的时间,我们就是我们的一个人的时候,我们就是一个人的人的人,不是一个人的人的人,不是一个人的人的人,不是一个人的人的人,不是一个人的人的人,不是一个人的人的人	
1 Section	To the the doctors durings parts, to the state of the	1000.0
4 To rust proof accident affected area. 1 \$420.00 / 5 To R & R rear boot mechanism 1 \$80.00 / 6 To R & R rear luggage compartment 1 \$80.00 / 7 To R & R uphostery, garnish and attachment parts 1 \$150.00 / 8 To R & R reverse sensor and check function 1 \$60.00 / 9 To check wheel alignment 1 \$80.00 / 11 To R & R rear w/s glass 1 \$140.00 / Labour Total 9 Parts Total Special Nett Total: 2 \$905.00 Labour Total 4 \$10.00 Grand Total 6 \$15,1712	2 To putty and respray accident affected area.	1 \$1,60 0.0
1 S rust proof accident anected area. 1 \$80.00 \(\square \)	2 To party and respirely assessment	8,001
5 To R & R rear boot mechanism	4 To rust proof accident affected area.	1 \$ 120.0 0
1 \$80.00 N 7 To R & R rear luggage compartment 1 \$450.00 N 8 To R & R reverse sensor and check function 1 \$60.00 N 9 To check wheel alignment 1 \$80.00 N 1 To R & R rear w/s glass 1 \$140.00 N 1 To R & R rear w/s glass 1 \$140.00 N 1 \$140.00 N 1 \$80.00 N 1 \$140.00 N	4 To fast proof accident amount a	
6 To R & R rear luggage compartment 1 \$90.00 N 7 To R & R uphostery, garnish and attachment parts 1 \$150.00 N 8 To R & R reverse sensor and check function 1 \$60.00 N 9 To check wheel alignment 1 \$90.00 N 11 To R & R rear w/s glass 1 20.00 1 12 \$140.00 13 \$140.00 14 \$10.00 15 Parts Total Special Nett Total: Special Nett Total: Labour Total Grand Total Grand Total Falls 5 22 3	5 To R & R rear boot mechanism	1 \$80.00
7 To R & R uphostery, garnish and attachment parts 8 To R & R reverse sensor and check function 9 To check wheel alignment 1 \$80.00 / 11 To R & R rear w/s glass 120 N Labour Total Parts Total Special Nett Total: Labour Total Grand Total Resurvey Lump Sumvepun Parts 5223		
7 To R & R uphostery, garnish and attachment parts 8 To R & R reverse sensor and check function 9 To check wheel alignment 1 \$60.00 / \$	6 To R & R rear luggage compartment	1 \$ 80.00 1
8 To R & R reverse sensor and check function 9 To check wheel alignment 1 \$80.00 / 11 To R & R rear w/s glass 120.00 / Labour Total Parts Total Special Nett Total: Labour Total Grand Total Grand Total Resurvey Lump Sumvepun Parts 5223		
8 To R & R reverse sensor and check function 9 To check wheel alignment 1 \$80.00 / \$80.00 / \$10 check wheel alignment 1 To R & R rear w/s glass 1 2 0 0 1 \$140.00 / \$140.00	7 To R & R uphostery, garnish and attachment pa	arts 1 \$ 150.0 0
9 To check wheel alignment 1 \$80.00 \(\) 11 To R & R rear w/s glass 120.00 1 \$140.00 Labour Total Parts Total Special Nett Total: Labour Total Grand Total Grand Total Resurvey Lump Sum repuir Parts 5223		
11 To R & R rear w/s glass 120.00 1 \$140.00 2060.0) Labour Total Parts Total Special Nett Total: Labour Total Labour Total Grand Total Resurvey Lump Sum vepun Parts 5223	8 To R & R reverse sensor and check function	1 \$60.00 /
11 To R & R rear w/s glass 120.00 Labour Total Parts Total Special Nett Total: Labour Total Labour Total Grand Total Resurvey Lump Sum vepun Parts 5223		
Labour Total Parts Total Special Nett Total: Labour Total Special Nett Total: Labour Total Grand Total Resurvey Lump Sum vepun Pants 5223	9 To check wheel alignment	1 \$80.0 0
Labour Total Parts Total Special Nett Total: Labour Total Special Nett Total: Labour Total Grand Total Resurvey Lump Sum vepun Pants 5223		
Parts Total Parts Total Special Nett Total: Labour Total Labour Total Grand Total Resurvey Lump Sum vepun Parts 5223	11 To R & R rear w/s glass	120·N 1 \$140.00
Parts Total Special Nett Total: Special Nett Total: Labour Total Grand Total Resurvey Lump Sum vepur Parts 5223		
Special Nett Total: \$2,005.10 Labour Total \$4,410.00 Grand Total \$15,772 WIVE I Resurvey Lump Sum repair Pans 5223		Labour Total \$4,110.0
Special Nett Total: \$2,005.10 Labour Total \$4,410.00 Grand Total \$15,772 WIVE I Resurvey Lump Sum repair Pans 5223		
Labour Total Grand Total Grand Total Resurvey Lump Sum vepun Pans 5223		Parts Total \$9,056.1
Grand Total WYVEY Resurvey Lump sum repair Parts 5223		Special Nett Total: \$2,005.1
urver Resurvey Lump sum repair Parts 5223		Labour Total \$4,110.0
12/2012 Resurvey Lump sum repair Parts 5223 12/2012 23/2/2027 Repair days 8 SN 960.		Grand Total \$15.771.
12/2072 23/2/2027 Repair days 8 SN 960.	us very Resurvery Lum	p Sum repair Posts 522:
- Uni lin Tain h	12/2022 23/2/2022 Rep	air days 8 SKI 960
I SUMMERIAN SEWILL	this has the	

LS 6600/2

@20% <u>1648.70</u> 6594.88

Talin Vm 13/3/2022

> Back to OneMotoring

Enquire PA	ARF/COF	Rehate for	Registered	l Vehicle

Vehicle Owner Particulars	The contract of the contract o	and the state of t
Owner ID Type:	Singapore NRIC	Confidence to the season of th
Owner ID:	301F	
Vehicle Details	A STATE OF THE STA	والمراو والمسينة المراد أوالموافرة والمراوز والمساولة والمراوز والموادرة والمساوية والمدار
Vehicle No.:	SLN8154X	and the second s
Vehicle to be Exported:	No	n a - James no a ser de Lucipe d'aire prince d'Albert Relationage est des les
Intended Deregistration Date:	11 Mar 2022	the Sandyan inc. and U.S. Prophysical State of Laboratory of the Association State of Conference of the Conference of th
Vehicle Make:	HONDA	والمعارض والموار فالوارة والمراود والمارة والمراود والمرا
Vehicle Model:	SHUTTLE 1.5G A	يستعم والمساومة والمراجع والمراجع والمعارض والمراجع والمعارض والمراجع والمعارض والمراجع والمعارض والمراجع والم
Primary Colour:	Grey	and in which the second section of the second section of the section is the
Manufacturing Year:	2016	
Engine No.:	L15B3536916	and the second s
Chassis No.:	GK81005892	and the state of t
Maximum Power Output:	97.0 kW (130 bhp)	1964 for all Manufally in James and advantage on parts, it would can
Open Market Value:	\$18,379.00	وراد و المراد و المراد الماسية الماس
Original Registration Date:	18 May 2017	and the same against the same description of the same the same and the
First Registration Date:	18 May 2017	والمعاولات والمعاولة والمعارفة والمعارفة والمعارفة والمعارفة والمعارفة والمعارفة والمعارفة والمعارفة والمعارفة
Transfer Count:	0	and the same of th
Actual ARF Paid:	\$8,379.00	
Intended PARF Rebate Details		
PARF Eligibility:	Yes	- Branch and the second of the second
PARF Eligibility Expiry Date:	17 May 2027	na o jumpo son majambanaj jenjo in folkrijskim filip diskriptim filip i se in jenjo in jenjo in je
PARF Rebate Amount:	\$6,284.00	
Intended COE Rebate Details	the second of the second secon	and the fact of the state of th
COE Expiry Date:	17 May 2027	ay chael as Apallomas Burnes a Salam comunes in concentral ASP a mission actions of
COE Category:	A - Car up to 1600cc & 97kW (130bhp)	والمراجع والمتعارض والمراجع والمراجع والمتعارض
COE Period(Years):	10	and the second s
QP Paid:	\$51,106.00	
COE Rebate Amount:	\$26,487.00	ggings savering of the continues of the contribution of the contri
Total Rebate Amount:	\$32,771.00	والمراجع والمراجع والمنطق منافرة ويتراجع والمراجع والمحافظة والمراجع والمراجع والمراجع والمراجع والمراجع

The information contained herein is correct as at 11 Mar 2022

ОК

MV 52, 000/ γ PV 32,771/ γ NV 19,229/ γ

TOUM 9hor



Honda Shuttle 1.5A G \$53,888 \$9,530 /yr 25-May-2017 1,496 cc - Stationwagon Available

1 Owner! Nice Bidded 3 Digits Number! Elegance Silver With Black Interior! Superbly Well Maintained With 16" Sports Rims With Almost Brand New Tires! Guaranteed Non PHV Usage! Original Paintwork, Ideal Car For With Very Spacious Boot N Legroom Space! Very Fuel Ef...

Posted: 06-Jan-2022



Honda Shuttle Hybrid 1.5A X \$65,800 \$11,770 /yr 26-May-2017 1,496 cc 51,000 km Stationwagon Available Honda Sensing

Fuel Type: Petrol-Electric

Excellent Well Maintained By 1 Officer From Point To Point Owner, Pristine Interior And Exterior, Currently Welcoming 100% Loan With Low Interest To Fit Your Monthly Budget! Not To Mention, We Also Welcome Bank Loan And Cash Deal! Warranty Provided To Ensure Your Ca...

PREMIUM AD

EDM Cars Pte Ltd

Posted: 08-Mar-2022

Posted: 10-Mar-2022



Honda Shuttle 1.5A G LED \$62,800 \$11,240 /yr 07-Jun-2017 1,496 cc 69,000 km Stationwagon Available

1 Owner Unit, Low Mileage, Original Mileage Non PHV, Low Maintenance Cost, Accident Free, Contact Our Salesman Now To Book Appointment To View And Test Drive!

CONSIGNMENT



Stand out with a bidded car plate number!

Bring luck and prosperity with an auspicious car licence plate number starting from only $2,3\times$ Single digit and lucky numbers available right here!

Find out more!



Honda Shuttle 1.5A G LED \$64,800 \$11,380 /yr 30-Jun-2017 1,496 cc 48 km Stationwagon Available

Previous Owner A Housewife Ferry Her Children From Point To Point To School, Very Well Clean In Interior, Pristine Interior And Exterior, Currently Welcoming 100% Loan With Low Interest To Fit Your Monthly Budget! Not To Mention, We Also Welcome Bank Loan And Cash...

PREMIUM AD

EDM Cars Pte Ltd

Posted: 09-Mar-2022



Honda Shuttle 1.5A G LED \$72,800 \$12,580 /yr 15-Aug-2017 1,496 cc 53,649 km Stationwagon Available

Auto Tallgate Boot With Super Good Fuel Efficiency Wagon Carvery! Very Well Maintained By 1 Teacher Owner! Non PHV Unit. Previous Owner Drive To Work & Home! Flexible Loan With Attractive Interest Rate As Low As 1.88%. Welcome Full Loan Tool Genuine Mileage H...

PREMIUM AD

EDM Cars Pte Ltd

Posted: 25-Feb-2022



Honda Shuttle 1.5A G \$71,800 \$11,780 /yr 24-Nov-2017 1,496 cc 58,000 km Stationwagon Available

1 Owner! Very Low Mileage, NON PHV Guaranteed, Absolutely No Repairs Needed, Good As New, Good Legroom For Front And Back, Rear Seats Are Able To Be Kept, Large Boot Space, 100% Accident-Free, 100% In House Loan Available, Don't Miss The Opportunity And Call...

Posted: 06-Mar-2022



Honda Shuttle 1.5A G \$70,800 \$11,600 /yr 26-Dec-2017 1,496 cc 36,000 km Stationwagon Available

Giving 1x Complimentary Servicing At KAH Motor For All Honda Models! Drive Off With Instant Approval Within The Day! 1 Owner Shuttle With Immaculate Condition, One Of The Largest Boot Space Japanese Car With Rear Knock Down To Even Enhance More Space For All...

PREMIUM AD

Posted: 04-Mar-2022



Honda Shuttle 1.5A G \$68,800 \$11,140 /yr 27-Dec-2017 1,496 cc 66,200 km Stationwagon Available

Good Condition. Well Maintained. High/Full Bank/In House Loan Available. Trade In Welcome. View By Appointment.

Posted: 25-Feb-2022

Save this search criteria, to get email alerts whenever a match is found.

Make Model : Price : Depreciation : Reg Date : Eng Cap : Mileage : Veh Type : Status

For old advertisements, view Expired ads

20 results/page

Buy / Rent Cars	Sell Your Car	Aftermarket	Articles	General
New Cars For Sale	Post an Ad	Workshop Directory	Car Reviews	About Us
Used Cars For Sale	Sell by Bidding	Aftermarket Products	Car Advice	Contact Us
Cars	Consignment		Car News	Careers

D

Email: sm@idac.com.sg Tel no: 6555 6888

*If no proper documents are produced, IDAC shall not file the report. Information will be discarded after one week.

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 1 / 102 /2022 (dd/mm/yy) Time of Accident: 1 : 1 (24-HR-FORMAT)
Vehicle No. : SLN F154 X Vehicle Make & Model:
Exact location of Accident: Bedok Reservior
Policyholder's Name: Kwan Wie Sorg I/C/UEN: 52184301F Driver's Name / IC No.: (As Above)
Driver's Name / IC No.:
Driver's Contact No.: 96905893 Company Contact No (Company Veh Only):
Driver's Address:
Email address: fullsty 4230 gmail com Insurance Company: Etiga
Number / Spouse / Children / Friend / Parents / Sibling / Relative / Employee / Hirer or Others specify:
What do you wish to claim? (Please TICK one only)
Own Insurance / Other Vehicle (The one you want to claim against) / Reporting (For Record Purpose)
Exact purpose for which the vehicle Was being used at time of accident? Occupation (nature of job) Outdoor
Private use / Work purpose *No. of Passengers (Including Driver): 0
*Passanger Name: Gender: Male / Female *Passanger
Name: Gender: Male / Female
Name: Gender: Male / Female Weather condition & Road conditions? (On the day of accident)
Weather condition & Road conditions? (On the day of accident)
Name.
Weather condition & Road conditions? (On the day of accident) Clear & Dry / Raining & Wet / After-Rain & Wet / Drizzling & Wet / Others:
Weather condition & Road conditions? (On the day of accident) Clear & Dry / Raining & Wet / After-Rain & Wet / Drizzling & Wet / Others: Was there any video captured by your Car Camera? Yes / No
Weather condition & Road conditions? (On the day of accident) Clear & Dry / Raining & Wet / After-Rain & Wet / Drizzling & Wet / Others: Was there any video captured by your Car Camera? Yes / No Any Injuries: Yes / No (If YES) Injured Person' Name:
Weather condition & Road conditions? (On the day of accident) Clear & Dry / Raining & Wet / After-Rain & Wet / Drizzling & Wet / Others: Was there any video captured by your Car Camera? Yes / No Any Injuries: Yes / No (If YES) Injured Person' Name: Injuries Sustain: Injured Person in Which Vehicle: Police Report filed: Yes / No (If YES) Which Police Station: The Other Party(s) Details:
Weather condition & Road conditions? (On the day of accident) Clear & Dry / Raining & Wet / After-Rain & Wet / Drizzling & Wet / Others: Was there any video captured by your Car Camera? Yes / No Any Injuries: Yes / No (If YES) Injured Person' Name: Injuries Sustain: Injured Person in Which Vehicle: Police Report filed: Yes / No (If YES) Which Police Station:
Weather condition & Road conditions? (On the day of accident) Clear & Dry / Raining & Wet / After-Rain & Wet / Drizzling & Wet / Others: Was there any video captured by your Car Camera? Yes / No Any Injuries: Yes / No (If YES) Injured Person' Name: Injuries Sustain: Injured Person in Which Vehicle: Police Report filed: Yes / No (If YES) Which Police Station: The Other Party(s) Details: 1. Driver's Name / IC No: Yehicle No: GBC 2242 R
Weather condition & Road conditions? (On the day of accident) Clear & Dry / Raining & Wet / After-Rain & Wet / Drizzling & Wet / Others: Was there any video captured by your Car Camera? Any Injuries: Yes / No (If YES) Injured Person' Name: Injuries Sustain: Police Report filed: Yes / No (If YES) Which Police Station: The Other Party(s) Details: 1. Driver's Name / IC No: Insurance Company: Insurance Company:
Weather condition & Road conditions? (On the day of accident) Clear & Dry Raining & Wet After-Rain & Wet Drizzling & Wet Others:

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature Date

Driver's Signature


(If driver is not the policyholder) Date

& Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



DESCRIBE CIRCUMSTA	NCES OF THE ACCIDENT				
At	mentioed	Date	and	Time,	/ was
	waiting 1	×	,		
1 feel	a strong	inpact	from	1 му	rear
portions.					
					J 8154X
				B: GB	C 2242 R

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: